

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-9519

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT
2. Name of Operator TEXACO PRODUCING INC	8. Form of Lease WEST DOLLARHIDE DRINKARD UNIT
3. Address of Operator P.O. BOX 728, HOBBS, NEW MEXICO 88240	9. Well No. 34
4. Location of Well UNIT LETTER M 660 FEET FROM THE SOUTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 29 TOWNSHIP 24S RANGE 38E NMPM.	10. Field and Pool, or Wildcat DOLLARHIDE TUBB DRINKARD
15. Elevation (Show whether DF, RT, GR, etc.) 3181 D.F.	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU. INSTALL BOP. GIH W/OVERSHOT, BUMPER SUB, JARS, AND DRILL COLLARS.
- 2) JAR FISH LOOSE. TOH.
- 3) TIH W/ WASHPIPE. LATCH ONTO AND TOH WITH FISH.
- 4) TIH W/ 4 3/4" BIT. CLEANOUT WELL TO PBTD 6896'. TOH.
- 5) GIH AND SET 5 1/2" CIBP @ 6390'. (TOP PERF AT 6410'). SPOT 25X(20 FT) CLASS C + 2% CaCl₂ CEMENT ON TOP. CIRC. HOLE W/ 9.5 LB PER GAL MUD. TOH.
- 6) RUN CEMENT BOND LOG (5000'-3000'). TO C AT 4315' BASED ON DRILLING REPORT TEMPERATURE SURVEY.
- 7) PERFORATE 2 SHOTS AT 4310' (ASSUMPTION: TOC AT 4315')
- 8) TIH W/ 5 1/2" CEMENT RETAINER. SET RETAINER AT 4280'. EST. INT. RATE INTO PERFS TRY TO EST CIRCULATION. PUMP 680 SKS CLASS C + 2% CaCl₂ CEMENT - CIRC TO SURFACE. PULL UP AND SPOT 25X CEMENT ON TOP OF CEMENT RETAINER.
- 9) POH AND SPOT 100' CEMENT PLUG AT 3100' - 3200' (ACROSS 9 5/8" CSG SHOE). POH AND SPOT 100' CEMENT PLUG AT 1166' - 1266' (TOP OF SALT). POH AND SPOT 100' CEMENT PLUG AT 200' - 300' (ACROSS 13 3/8" CASING SHOE) ALSO 1" CEMENT IN 13 3/8" - 9 5/8" ANNULUS. TOH AND PUMP 10' CEMENT PLUG AT SURFACE.
- 10) CUT OFF WELLHEAD AND INSTALL DRY HOLE MARKER.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED K. E. Johnson TITLE AREA SUPERINTENDENT DATE JUL 22 1988

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: