P			
NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old
SANTA FE	NEW MEXICO OIL CONS	ERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE			Ellective 1-1-65
U.S.G.S.			Sa. Indicate Type of Lease
LAND OFFICE			State Fee
OPERATOR			5. State Oil & Gas Lease No.
			B-9519
LOO NOT USE THIS FORM FOR USE "APPL	UDRY NOTICES AND REPORTS ON PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B ICATION FOR PERMIT -" (FORM C-101) FOR SUC	WELLS	
1.			7. Unit Agreement Name
OIL GAS WELL	OTHER- Water Injection	Veet Dell	
2. Name of Operator	waler injection	West DOIL	8. Farm or Lease Name
Skalls Odl Company		West Dell	mbdde Dudukend Meda
3. Address of Operator		mest Duit	9. Well No.
D 0 Per 1251 Vdd1e			35
P. O. Box 1351, Midla 4. Location of Well	Ind, Lexas /9/UL		10. Field and Pool, or Wildcat
NT NT	(()) (out)	1000	
UNIT LETTER,,	660 FEET FROM THE South	LINE AND FEET FROM	DOTTELUIGE INDD-DLIUKEIG
	CTION 29 TOWNSHIP 245	2012	
LINE, SE	TOWNSHIP	RANGE JOL NMPM.	
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
		3217' DF	Lea AllIIIII
16. Chec	ck Appropriate Box To Indicate N		
	F INTENTION TO:		REPORT OF:
		SOBSEQUEN	REFORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	لمحمد	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	FLUG AND ABANDONMENT
OTHER Resqueeze Tubb	Zone perfs.		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The Tubb perfs. 6256-6462' were squeezed in February, 1972, in an attempt to confine injection to the main Drinkard and Upper Abo Zones. Injection profile recently run indicated water still entering these perfs.; therefore, we propose resqueezing as follows:

- 1) Rig up pulling unit. Pull tubing and packer.
- 2) Plug back from 6807' to 6550' with approximately 35 sacks of sand.
- 3) Set RTTS tool at 6100' and squeeze perfs. 6256-6540' with 300 sacks expanding cement. Pull RTTS tool.
- 4) Drill out cement to 6550' and test squeeze job. Clean out to 6807'.
- 5) Run internally-coated tubing, load casing annulus behind tubing with water treated with inhibitors and set packer at 6500'.
- 6) Hook up wellhead and resume injection.

16.1 nereby certi		-	te to the best of	my knowledge and belief.	
SIGNED			TITLE	Lead Clerk	DATE NOV. 14, 1972
APPROVED BY CONDITIONS OF	APPROVAL, IF ANY:	Orig. Signed by Joe D. Ramey Dist. I, Supv.	TITLE		DATE NOV 20 1972

REPENED

.

S 1972

OIL CONSERVATION COMM, house in ML