NC. OF COPIES RECEIVED	-	Form C-103
		Supersedes Old
		C-102 and C-103
ANTAFE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
ILE	_	So Indigato Tuno of Land
.\$.G.S.		Sa. Indicate Type of Lease State X Fee
AND OFFICE		State A Fee S. State Oil & Gas Lease No.
PERATOR		<b>B</b> 9311
DO NOT USE THIS FORM FOR P	DRY NOTICES AND REPORTS ON WELLS	
USE "APPLIC	ATION FOR PERMIT -** (FORM C+101) FOR SUCH PROPUSALS.)	7. Unit Agreement Name
OIL K GAS WELL	OTHER-	
Name of Operator	VINCA.	8. Farm or Lease Name
Skelly Oil Company		Mexico "J"
Address of Operator		9. Well No.
P. O. Box 1351, Mid	land, Texas 79701	5 \$
Location of Well		10. Field and Pool, or Wildeat
UNIT LETTER	1980 South 660	Dollarhide Fusselman
yayı yayının araşının sanaşır fanaş		
THE LINE, SEC	32 245 RANGE	NMPM. ())))))))))))))))))))))))))))))))))))
THITTHIN THIN THE	15. Elevation (Show whether DF, RT, GR, etc.) 3157' DF	12. County Lea
	Appropriate Box To Indicate Nature of Notice, Report	
RFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB	ALTERING CASING PLUG AND ABANDONMENT
ULL OR ALTER CASING	Plugged bac	ck and reperforated
<u>ب</u>	Tusselman	
OTHER		
work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, i	including estimated date of starting any propose
<ul> <li>work) SEE ROLE 1103.</li> <li>1) Moved in workow</li> <li>2) Set CIBP at 860</li> <li>3) Perforated 5-1/ with 6 shots, 8</li> <li>4) Treated perfs.</li> <li>5) Swabbed and tea</li> <li>6) Treated perfs.</li> <li>54 bbls. treated</li> <li>7) Swabbed and tea</li> <li>8) Set CIBP at 849</li> <li>9) Perforated 5-1/ with 8 shots, 8</li> <li>8462-8470' with</li> <li>10) Spotted 250 gain</li> <li>NE acid with 9</li> </ul>	<pre>rig December 2, 1975. 00' with cemant to plug back to 8580'. /2" OD casing at 8502-8510' with 16 shots, 853 8560-8564' with 8 shots, two shots per foot, 8502-8564' with 2000 gallons 15% NE acid using sted 4 hrs., no oil, 70 bbls. load water. 8502-8564' with 4000 gals. 15% NE acid and 9 ed water. sted perfs. 8502-8564' 7 hrs., no oil, 93 bbl 94' with 2 sacks cement 8480-8494' PBTD. /2" OD casing 8282-8285' with 6 shots, 8328-8 8358-8362' with 8 shots, 8410-8416' with 12 s h 16 shots, 2 shots per foot, total of 66 sho 1s. 15% NE acid 8261-8471'. Treated perfs. 8 0 ball sealers in 4 stages. Flushed with 54 sted perfs. 8282-8470' for 5 hrs., no oil, 11</pre>	26-8530' with 8 shots, 8550-8 total of 38 shots. ng 45 ball sealers. 0 ball sealers. Flushed with s. load water. 332' with 8 shots, 8338-8342' thots, 8438-8442' with 8 shots ots. 3282-8470' with 3500 gallons 1 bbls. treated water.
<ol> <li>Moved in workow</li> <li>Set CIBP at 860</li> <li>Perforated 5-1/ with 6 shots, 8</li> <li>Treated perfs.</li> <li>Swabbed and tea</li> <li>Treated perfs.</li> <li>Swabbed and tea</li> <li>Set CIBP at 849</li> <li>Perforated 5-1/ with 8 shots, 8</li> <li>Set CIBP at 849</li> <li>Perforated 5-1/ with 8 shots, 8</li> <li>Set CIBP at 849</li> <li>Perforated 5-1/ with 8 shots, 8</li> <li>Set CIBP at 849</li> <li>Spotted 250 gain NE acid with 90</li> <li>Swabbed and tea</li> <li>Treated perfs. ball sealers in</li> </ol>	<pre>rig December 2, 1975. 00' with cemant to plug back to 8580'. /2" OD casing at 8502-8510' with 16 shots, 85: 8560-8564' with 8 shots, two shots per foot, 8502-8564' with 2000 gallons 15% NE acid usin ated 4 hrs., no oil, 70 bbls. load water. 8502-8564' with 4000 gals. 15% NE acid and 9 ed water. sted perfs. 8502-8564' 7 hrs., no oil, 93 bbl 94' with 2 sacks cement 8480-8494' PBTD. /2" OD casing 8282-8285' with 6 shots, 8328-8 8358-8362' with 8 shots, 8410-8416' with 12 s h 16 shots, 2 shots per foot, total of 66 sho 1s. 15% NE acid 8261-8471'. Treated perfs. 8 O ball sealers in 4 stages. Flushed with 54 sted perfs. 8282-8470' for 5 hrs., no oil, 11 8282-8470' with 6000 gals. 15% NE acid, 500f n 4 stages.</pre>	26-8530' with 8 shots, 8550-8 total of 38 shots. ng 45 ball sealers. 0 ball scalers. Flushed with s. load water. 332' with 8 shots, 8338-8342' hots, 8438-8442' with 8 shots ts. 282-8470' with 3500 gallons 1 bbls. treated water. 9 bbls. load water. benzoic acid flakes and 33
<ul> <li>work) SEE RULE 1103.</li> <li>1) Moved in workow</li> <li>2) Set CIBP at 860</li> <li>3) Perforated 5-1/ with 6 shots, 8</li> <li>4) Treated perfs.</li> <li>5) Swabbed and tea</li> <li>6) Treated perfs.</li> <li>54 bbls. treate</li> <li>7) Swabbed and tea</li> <li>8) Set CIBP at 849</li> <li>9) Perforated 5-1/ with 8 shots, 8</li> <li>8462-8470' with</li> <li>10) Spotted 250 gai NE acid with 90</li> <li>11) Swabbed and tea</li> <li>12) Treated perfs. ball sealers in</li> </ul>	<pre>rig December 2, 1975. O' with cemant to plug back to 8580'. '2" OD casing at 8502-8510' with 16 shots, 853 3560-8564' with 8 shots, two shots per foot, 8502-8564' with 2000 gallons 15% NE acid using sted 4 hrs., no oil, 70 bbls. load water. 8502-8564' with 4000 gals. 15% NE acid and 9 ad water. sted perfs. 8502-8564' 7 hrs., no oil, 93 bbl 94' with 2 sacks cement 8480-8494' PBTD. /2" OD casing 8282-8285' with 6 shots, 8328-8 358-8362' with 8 shots, 8410-8416' with 12 s h 16 shots, 2 shots per foot, total of 66 sho 1s. 15% NE acid 8261-8471'. Treated perfs. 8 0 ball sealers in 4 stages. Flushed with 54 sted perfs. 8282-8470' for 5 hrs., no oil, 11 8282-8470' with 6000 gals. 15% NE acid, 500% n 4 stages. D. R. Crow Lead Clerk </pre>	26-8530' with 8 shots, 8550-8 total of 38 shots. ng 45 ball sealers. 0 ball sealers. Flushed with s. load water. 332' with 8 shots, 8338-8342' hots, 8438-8442' with 8 shots ts. 282-8470' with 3500 gallons 1 bbls. treated water. 9 bbls. load water. benzoic acid flakes and 33
<ul> <li>avork) SEE ROLE 1103.</li> <li>1) Moved in workow</li> <li>2) Set CIBP at 860</li> <li>3) Perforated 5-1/ with 6 shots, 8</li> <li>4) Treated perfs.</li> <li>5) Swabbed and tea</li> <li>6) Treated perfs.</li> <li>54 bbls. treated</li> <li>7) Swabbed and tea</li> <li>8) Set CIBP at 849</li> <li>9) Perforated 5-1/ with 8 shots, 8</li> <li>8462-8470' with</li> <li>10) Spotted 250 gai NE acid with 90</li> <li>11) Swabbed and tea</li> <li>12) Treated perfs. ball sealers in</li> </ul>	<pre>rig December 2, 1975. 00' with cemant to plug back to 8580'. /2" OD casing at 8502-8510' with 16 shots, 85: 8560-8564' with 8 shots, two shots per foot, 8502-8564' with 2000 gallons 15% NE acid usin ated 4 hrs., no oil, 70 bbls. load water. 8502-8564' with 4000 gals. 15% NE acid and 9 ed water. sted perfs. 8502-8564' 7 hrs., no oil, 93 bbl 94' with 2 sacks cement 8480-8494' PBTD. /2" OD casing 8282-8285' with 6 shots, 8328-8 8358-8362' with 8 shots, 8410-8416' with 12 s h 16 shots, 2 shots per foot, total of 66 sho 1s. 15% NE acid 8261-8471'. Treated perfs. 8 O ball sealers in 4 stages. Flushed with 54 sted perfs. 8282-8470' for 5 hrs., no oil, 11 8282-8470' with 6000 gals. 15% NE acid, 500f n 4 stages.</pre>	26-8530' with 8 shots, 8550-8 total of 38 shots. ng 45 ball sealers. 0 ball sealers. Flushed with s. load water. 332' with 8 shots, 8338-8342' shots, 8438-8442' with 8 shots ots. 282-8470' with 3500 gallons 1 bbls. treated water. 9 bbls. load water. benzoic acid flakes and 33

CONDITIONS OF AT	PROVAL, I	ANY
------------------	-----------	-----

~

Mexico "J" Well No. 5 - Continued

.

13) Flowed and swabbed 13 hrs., no oil, 201 bbls. load water, 29 bbls. formation water.14) Workover completed. Well shut in pending further evaluation.

١