norm 3160-5 June 1990)	UNITED STA DEPARTMENT OF TH		FORM APPROVED Sudget Bureau No 1004-0135 Expires: March 31, 1993 S Lease Designation and Serial No LC-060944		
June 1770	BUREAU OF LAND MA	ANAGEMENT			
Do not use thi	SUNDRY NOTICES AND RE s form for proposals to drill or to d Use "APPLICATION FOR PERMI	o it Indian. Allottee or Tribe Name			
	SUBMIT IN TRIF	If Unit or CA. Agreement Designation			
Type or Well			8 Well Name and No.		
Quil Quil Quil Quil Quil Quil Quil Quil	Well Other	South Justis Unit" C" #16			
	Dild Gas Company		30-025-20032		
Address and Telepi P. O. B	ox 1610, Midland, Texas	9702-1610 <b>915 688-5672</b>	10. Field and Pool. or Exploratory Area Justis Blbry-Tubb-Dkrd		
+ Location of Well ( 231	FOOLAGE, SEC., T., R., M., OF SURVEY DESCRIPTION) OFNL& 1650 FEL (Unit	Lea			
	14-255-37E				
CHE	CK APPROPRIATE EOX(S) TO IN	NDICATE NATURE OF NOTICE. REP	ORT. OR OTHER DATA		
	OF SUBMISSION	TYPE OF ACTIO			
X N	ionice of Intent	Abandonment Recomptetion	Change of Plans		
s	ubsequent Report	Plugging Back Casing Repair	Water Shut-Off		
	Final Abandonment Notice	Conversion to injection Dispose Water Note: Report results of multiple completion on Well Completion of Recompletion Report and Log form (			
13. Describe Propose give subsurf	a or Completed Operations (Clearly state all pertinent of ace locations and measured and true vertical depths to	petalls, and give pertinent dates, including estimated date of sta or all markers and zones pertinent to this work.)*	irting any proposed work. If well is directionally drilled.		
1. POI 2. Dr: 3. Dr:	e to workover wellbore as f H w/CA ill out fill & cmt to 5650' ill new formation from 5650	(total depth) -6100' (ne <b>w</b> total depth)	<b>.</b>		
	d Blinebry-Tubb-Drinkard pe	rfs	-		
	idize in two stages H w/CA				
Signed	en an Gostell	Agent	Date5-25-94		
(This space to	(ORIG. SGD.) JOE G. LARA		EER_ Date 6/21/94		

----

<u>\*</u>

۲

Г

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictishous or fraudulent statements or representations as to any maker widea its surisdiction.

## WORKOVER PROCEDURE

DATE: May 9, 1994

WELL & JOB: SJU C-16 - Deepen and add perfs				<b>DRILLED:</b> 1963				
LAST WORKOVER: 9/78 Cleaned out fill to 5513'			3'	FIELD: South Justis		COUNTY: Lea County, New Mexico		
BY: D. C. Bretches		<b>TD:</b> 5650'	PBD:	5513'	DATU	<b>M:</b> 10' R	KB	
CASING: SURFACE: PROD:	<u>SIZE</u> 8-5/8 4-1/2"	<u>WEIGI</u> 24.0# 9.5/11.6		<u>GRAD</u> K-55 K-55	<u>E</u>	<u>SET @</u> 930' 5650'	520 830	TOC Surface 1200' (TS)

## PERFORATIONS: Blinebry 5128-5466'

TUBING:SIZE: 2-3/8" WEIGHT: 4.7 GRADE: J-55 THREAD: EUE AB Mod JOINTS:183 BTM'D @ 5491

HISTORY AND BACKGROUND: This well was drilled and completed in 1963 as a Blinebry producer. Additional Blinebry perforations were added in 1969. During a workover in 1978, hard fill was encountered at 5371', covering some of the Blinebry perfs. The fill was drilled out to 5513 where the bit plugged. No further attempts were made to drill deeper since the existing perforations were uncovered.

SCOPE OF WORK: Pull completion assembly, deepen well to 6100', add perforations to Blinebry interval, acidize open hole and new perforations, and rerun completion assembly.

## PROCEDURE

\*Prior to MIRU, shoot fluid level of well to determine proper pump spacing for Adaptable Tool.

- 1. MIRU PU. Pull rods and pump. ND THAF. NU BOPE. POH w/ 183 jts 2-3/8" 4.7# J-55 TBG, SN, Perf nipple, and 1 jt 2-3/8" TBG w/ BP.
- PU and RIH w/ 3-7/8" drag bit. Adaptable Tool, and 3-1/8" DC's on 2-3/8" N-80 WS to ±5513' (Expected PBD). RU power swivel and while pumping 1/4 BPM gelled BW (Vis @ ±30 sec/qt), drill out fill f/ 5513 to 5650' (TD). Drill new formation with same tool f/ 5650-6100'. POH laying down Adaptable Tool and DC's.
- 3. RU Wedge WL. Perforate 4-1/2" CSG w/ 3-1/8" select fire gun 1 SPF @ 5536, 5546, 5564, 5566, 5586, 5595, and 5602'. RD WL.
- 4. PU and RIH w/ Ret PKR on 2-3/8" WS. Treat Tubb/Drinkard open hole as per pending treatment procedure. Rlse PKR and TOH. TIH w/ RBP and PKR. Treat Blinebry perfs as per pending treatment procedure. Rlse PKR and RBP. TOH and lay down WS.
- 5. RIH w/ 2-3/8" CA, rods, and pump as per Production Dept. recommendation. RD PU. Clean location. TOTPS

D. **C**/Bretches

J. E. Shields

