Form 3160-5 UI ED (December 1989) DEPARTMENT O BUREAU OF LAN		FORM APPROVED Budget Bureau No. 1004-0135 Expires September 10, 1990 5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND	DREPORTS ON WELLS	NM-05254
Do not use this form for proposals to drill or t Use "APPLICATION FOR PE	o deepen or reentry to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUBMIT IN TR	RIPLICATE	7. IF UNIT OR CA, AGREEMENT DESIGNATION
	THER	8. WELL NAME AND NO.
2. NAME OF OPERATOR		South Justis Unit "C" #23
ARCO Oil & Gas Company 3. ADDRESS AND TELEPHONE NO.		9. API WELL NO. 30-025-21057
P.O. Box 1610, Midland, TX 79702	(015) 699 5670	10. FIELD AND POOL, OR EXPLORATORY AREA
4. LOCATION OF WELL (Footage, Sec., T., R., M., or Surve	(915) 688-5672	Justis Blbry-Tubb-Dkrd
	, - ,	11. COUNTY OR PARISH, STATE
330 FNL & 1650 FEL (Unit Letter B) 26-25S-37E		Lea
CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPO	
TYPE OF SUBMISSION		
XNOTICE OF INTENT		CHANGE OF PLANS
L SUBSEQUENT REPORT		NON-ROUTINE FRACTURING
FINAL ABANDONMENT NOTICE		
		vellbore South Justis Unit
	(NOTE: Report res Completion	ults of multiple completion on Well
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (proposed work. If well is directionally drilled, give subsu 	Clearly state all portinget details and the	
Propose to work over wellbore for South Jus		
repose to work over wendore for Solidi Jus	sus Unit as follows:	
1. POH w/CA.		Aug CAF
2. CO well to 5982 PBD.		REAL C
3. Run csg integrity test.		μ α α α α α α α α α α α α α
4. Add perforations and stimulate.		
5. RIH w/CA.		
		36 IV
•		
14. I hereby certify that the foregoing is true and correc	t	
N C. I el. 10		
signed <u>Len W Loinelf</u>	TITLERegulatory Coordina	tor date <u>8-17-93</u>
(This space for Federal or State office use)	and the second	COT DATE <u>8-17-93</u> 9/1/63
APPROVED BY	TITLE	9/1/9
CONDITIONS FOR APPROVAL, IF ANY:	······································	DATE/

APPROVED BY		_	
CONDITIONS FOR	R APPROVAL,	İF	ANY:

19964 2993 30T 3 1383

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

WORKOVER PROCEDURE

DATE:6/01/93

WELL & JOB: SJU "C" #23 - clean out to 5982' and bring into unit DRILLED: 7/64							
LAST WORKO	VER: 4/5/89 - repla	ce split jt of tubing		FIELD: Sout	th Justis Unit	COUN	TY: Lea, NM
BY: B. G. Voig	ŗt	TD: 6050'		PBD: ?		DATUM: ? (assu	
TUBINGHEAD:			SIZE: 7-	1/16"		PRESS RATING	: 2000 psi
CASING: SURFACE: INTER:	<u>SIZE</u> 8-5/8"	WEIGHT 24 lb	<u>GRADE</u> J-55	<u>SE1</u> 965		<u>SX CMT</u> 350 sx	TOC circ.
PROD:	5-1/2"	15.5 lb	J-55	605	50'	825 sx	2470' (TS)
LINER:	SIZE	WEIGHT	GRADE	TO	<u>P</u>	<u>BTM</u>	<u>TO</u>

PERFORATIONS: Paddock: 4851-69, 4907, 19, 28, 32, 41, 48, 55, 90, 98, 5008, 20' (squeezed 11/64 & 3/67) Blinebry: 5092, 5116, 29, 77, 5244, 75, 5320, 28, 69, 78, 5460, 5503, 10, 48, 52, 63, 65, 67, 5635' Tubb/Drinkard: 5747, 82, 5803, 43, 73, 5911, 21, 28, 55, 62'

IUBING:	SIZE: 2-3/8"	WEIGHT: ?		
BTM'D@?			GRADE: ?	THREAD: 7
Sim De .		JOINTS: 191	MISC: MA, perf sub, & SN	

PACKER AND MISC:

HISTORY AND BACKGROUND: This well was drilled in July of 1964. In November 1964 the Paddock perforations from 4851-4955' were squeezed with 200 sx cement. In March of 1967, the remainder of the Paddock perfs were squeezed, and the Drinkard, Tubb, and additional Blinebry perfs were perforated. According to the early records, a CIBP was set at 5965', and two RBP's were set at 5673' & 5710'. These were set to abandon the Tubb/Drinkard perforations. There were no records of these plugs being removed. but on 4/5/89, a workover log showed that there was 6000'+ tbg (192 jts) in the hole. According to this data, the well should be clean

SCOPE OF WORK: Verify well is cleaned out to 5982+. Test casing, & bring into unit

PROCEDURE

- 1. MIRU PU. POOH with rods and pump. ND WLHD. NU BOP.
- Pick up 2-4 jts of 2-3/8" tbg and lower CA to tag PBD. POOH w/ additional tubing and CA (SLM). 2.
 - a. If measurements show well is cleaned out past 5982', continue with Step 3.
 - b. If measurements show well is not cleaned out past 5982', RIH with 4-3/4" MT bit, DC's, and WS. Clean out well to
- RIH with Model "G" RBP and set at 5050'. Perform casing integrity test to 500 psi. POOH with 3.
- Add perforations and stimulate
- RIH with CA (MA, perf sub, SN, TAC, & 2-3/8" tbg.) per F/P Engineering design. 4.
- ND BOP. NU WLHD. RIH with pump and rods per F/P Engineering design. RD PU. TOTPS. 5.

Permian Drilling Team Leader

