Submit 3 Copies to Appropriate District Office	State of New Energy, Minerals and Nat	v Mexico ural Resources Department	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 874	Santa Fe, New M	ox 2088 lexico 87504-2088	WELL API NO. 30-025-21354 5. Indicate Type of Lease STATE FEE X 6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR I DIFFERENT RE	PROPOSALS TO DRILL OR TO DE SERVOIR. USE "APPLICATION FO I C-101) FOR SUCH PROPOSALS	EPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name SOUTH JUSTIS UNIT "B"
2. Name of Operator ARCO Permian			8. Well No. 20
 Address of Operator P.O.BOX 1610, MIDLAND, 4. Well Location 			9. Pool name or Wildcat JUSTIS BLBRY-TUBB-DKRD
Unit Letter F: 19 Section 23	Township 25S	Line and 2309 Range 37E whether DF, RKB, RT, GR, et	Feet From The WEST Line NMPM LEA County c.)
	Appropriate Box to Indi INTENTION TO:	cate Nature of Notice,	Report, or Other Data SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK	—
OTHER: ADD B-T-D PERFS	and the second	OTHER:	ates, including estimated date of starting any proposed
 Describe Proposed or Completed work) SEE RULE 1103. PROPOSE TO: 	Operations (Clearly state all perti	ant team, and see per ment a	

- PROPOSE TO: 1. POH W/PROD CA. 2. CO TO 6067 PBD. CIBP AT 5780. MOD D PKR AT 5785. 3. ADD B-T-D PERFS.

 - 4. ACID TREAT. 5. RIH W/PROD CA.

I hereby certify that the inform	nation above is true and complete to the best of m	y knowledge and belief.	_	
SIGNATURE Ken U	Losnel	TITLEA	GENT	DATE 05-04-95
TYPE OR PRINT NAME Ken	W.Gosnell			TELEPHONE NO.915 688-5672
(This space for State Use)	ORIGINAL SIGNED BY GARY WINK			MAY 10 1935
APPROVED BY	FIELD REP. II			DATE

WORKOVER PROCEDURE

DATE: April 6, 1995

WELL & JOB: SJU B-20

DRILLED: 1965

LAST WORKOVER: 10/93 CO to 5800', Added Perfs & Stimulate FIELD: Justis COUNTY: Lea. NM

BY: W.C. Heard		TD: 6100'	PBD: 5780'		DATUM: GL			
CASING: SURFACE: PROD:	SIZE 9-5/8" 7"	<u>WEIGHT</u> 32.3/36# 23/26#	GRADE H40/J55 J55/N80	<u>SET @</u> 956' 6100' DVT @ 3968'	<u>SX CM</u> 500 360 700	T TOC surf-circ DVT-circ 550'-TS		
PERFORATIONS: Open Perfs: Blinebry 5126-5760'								
TUBING: SIZE: 2-7/8" WEIGHT: 6.5# GRADE: MISC: TAC @ 5023' w/ 12,000# T			THREAD: H	EUE 8r JOIN	FS: 185	BTM'D@ 5743'		

HISTORY AND BACKGROUND: During workover of 1993, cleaned out to 5800', set CIBP at 5780', added perfs and acidized. No other work has been done since October, 1993. (Note: check Production files to verify CA)

SCOPE OF WORK: Pull CA, clean out, add perfs, stimulate old and new perfs.

PROCEDURE

- 1. MIRU, pull CA. Visually inspect tubing and determine if work string is needed.
- 2. Clean out to original PBD 6067' (Model D packer at 5785' from original completion records indicate i was not recovered during 1993 workover but well was cleaned out to 5800').
- 3. RU WL and add attached perfs. Correlate to _____
- 4. Acidize as per Engineering recommendation.
- 5. Run CA as per Production Department design and TOPS.

W. C. Heard J. E. Shields

SJU B-20 WELLBORE SCHEMATIC



9-5/8" 32.3/36# casing at 956' with 500 sacks. TOC at surface - circulated

DVT at 3968' with 700 sacks. TOC at 550' - TS. Holes in casing 4134-4195' - cemented with 475 sacks

Production tubing -185 joints 2-7/8" 6.5# EUE 8rd TAC at 5023' with 12,000# T

Blinebry perfs 5126-5760'

CIBP at 5780' Mod D packer at 5785' with blanking plug

Tubb/Drinkard perfs 5814-5975'

7" 23/26# casing at 6100' with 360 sacks. TOC at DVT at 3968' - circulated.

TD 6100', PBD 5780'



6.00 0 138**85**

OFFICE