<u> </u>		
Subject 3 Copies State of New 1 to Appropriate Energ finerals and Natural District Office	Mexico Resources Department	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 WELL API NO. 20 0/25 21 271		
		WELL API NO. 30-025-21371
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		S. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		STATE XX FEE
		U State Off & Gas Lease NU
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name
1. Type of Well:		
WELL         WELL         OTHER           2. Name of Operator		Continental State 8. Well No.
Chevron U.S.A. Inc.		1
3. Address of Operator		9. Pool name or Wildcat
P.O. Box 670, Hobbs, NM 88240 4. Well Location		Stateline Ellenburger
Unit LetterB_:1980 Feet From TheEast	Line and860	Feet From The North Line
Section 5 Township 24S Range 38E NMPM Lea County		
10. Elevation (Show wheth	er DF, RKB, RT, GR, etc.) 3286	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
OTHER:		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Work performed: 4-30-89 thru 5-7-89		
MIRU, unbridle pmpg unit. POH w/rods. Attempt to release TAC. Work stuck prod. tbg. Freepoint indicates 100% free at 5575 and 95% stuck at 5605'. GIH w/ chemical cutter. Cut at 11867' and at 5587'. GIH w/ BHA to 5580'. Wash to 5713'. Engage fish at 5587'. Jar fish loose, POH w/ cut jt and 50 jts of fish. POH, LD prod. tbg. TIH, work thru tight spot f/6170-6494. Tag bottom at 1,758'. POH wet, Wellbore standing full. TIH w/ OE tbg, tag at 11,700. Cmt Plug #1 f/11,085 to 11,710 80sx (tagged) Cmt Plug #2 f/ 8,666 to 9,012 35sx Cmt Plug #3 f/ 4,460 to 5,696 125sx		
Cmt Plug #4 Perf 5 1/2" csg at 4100, set CICR at 3994'. Sqz 8 5/8" csg shoe at 4107 w/50sx, cap CICR w/ 8 sx. Cmt Plug #5 f/ 1,296 to 1,592 30sx top of salt at 1480'.		
(Continued next page)		
I hereby certify that the information above is true and complete to the best of my knowledge		5 10 °0
SKINATURE 2	me Statt Drilli	ng Engineer DATE 5-10-89
TYPE OR PRINT NAME		TELEPHONE NO.
(This space for State Use)		INSPECTOR FEB 0 5 1990

P&A Well

Cmt Plug #6

Perf 5 1/2" & 8 5/8" csg at 425'. Set CICR at 348'. Circ cmt up 8 5/8 x 5 1/2" csg and 11 3/4" x 8 5/8" csg using 155sx. Closed surface csg valves and sqz'd additional 75sx into formation. Cap CICR w/8 sx. Cmt Plug #7 f/surface to 60' w/30sx. Cmt Plug #8 squeezed 11 3/4" x 8 5/8" and 8 5/8" x 5 1/2" csg annulus w/130sx

when they started flowing at surface WOC.

\*P&A mud circulated to surface after setting cement plug #1.

RD pulling unit and clean location. WOC 14 hrs. finish cutting off WH. Install P&A marker, fill in cellar, cut off anchors.