STATE OF NEW MEXICO

ITIONS OF APPROVAL IF ANY

iGγ	ANC	MINERALS	DEPARTMENT

ne. er centes ecctives	UIL CONSERV	ATION DIVISION		
FILE		W MEXICO 87501		Farm C-103 - Revised 10-1-73
U.S.G.S. LAND OFFICE OFERATOR			State X State Oil 6 G	Fee
SUNDRY N	OTICES AND REPORTS O	N WELLS		
SIL GAS	CS TO DRILL OR TO DELPEN OR PLUC GR PERMIT -" (FORM C-101) FOR S	SACE TO A DIFFERENT RESERVOIR UCH PROPOSALS.)	7. Unit Agreemen	nt Name
Chevron U.S.A. Inc.			3. Fam or Lease	
P.O. Box 670 Hobbs,	NM 88240		Continenta 3. Weil No.	1 State
UNIT LETTER B . 198	30 FEET FROM THE East	LINE AND860	10. Fleid and Po	Ellenburger
THE North LINE, SECTION	5 TOWNSHIP	24S RANGE 38E .	_ *MPM.	
	15. Elevation (Show whether 3286		12. County Lea	
Check Appr NOTICE OF INTER	opriate Box To Indicate	Nature of Notice, Repor	t or Other Data	
ORM REMEDIAL WORK PORARILY ASAMDOM OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING OPHS. CASING TEST AND CEMENT JOB OTHER	<u> </u>	ING CASING
escribe Proposed or Completed Operationary SEZ RULE 1703.	ns (Clearly state all pertinent de	tails, and give pertinent dates,	including estimated date of s	starting any proposed
Work performed 11-4-8	38 thru 11-18-88	TD: 12,161' P	B: 12,158'	
POOH w/production equipher at 10,433'. Load 4753-4858. Chemical set pkr at 4751'. Load CBW. Swb back chemical 50bbls 8.6 CBW thru leadlow to settle. Set out 2x tbg capacity, to 4682'. Circ clean 2 7/8", 6.5#, production 250gallons petrosett bg and pmp action	tbg w/62bbls and test squeeze csg leak 475 ad annulus w/1000psi al load. Inj. test it eak. TIH to 9000'. CICR at 4650'. Bate rec back 25sx cmt. It sobres to 12,141'. sol, displace to EOT	st RBP to 1000psi, h. 3-4858 w/6bbls 50/50. Sqz chemical mixt leak (4753-4858) 1/2 Dump 3sx frac sand the mix 150sx Cl C. WOC 19 hrs. Drill ov circ to RBP. Rec. ND BOP, set TAC w/1. Run pump and rods	eld ok. Isolate I FW, bypass plugge ure, flush to btm bpm at 1700psi. I down tbg to cover Sting out of ret. ut CICR at 4650's cmt, sand, scale 0,000# tension. I Space out, hans	leak f/ ec off. of pkr w/ Pumped RBP. Rev and cmt . Run NUWH. g on.

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT | SUPERVISOR

STATE OF NEW MEXICO IRGY AND MINERALS DEPARTMENT

44. 47 COPIES ACCEIVES		
DISTRIBUTION		i
SANTA FE		ı
FILE		i -
U.S.G.S.	T	i
LAND OFFICE		
PERATOR		1

TIONS OF APPROVAL, IF ANY:

SUNDRY NOTICES AND REPORTS ON WELLS ***SUNDRY	SANTA FE. NEW MEXICO 87501 SANTA FE. NEW MEXICO 87501 SUNDRY NOTICES AND REPORTS ON WELLS Continents State C		CIL CONSERVAT	TON DIVISION	
SANTA FE. NEW MEXICO 37501 SANTA FE. NEW MEXICO 37501 Source of a Goat Lease 100. SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS SOURCE of a Goat Lease 100. SUNDRY NOTICES AND REPORTS ON WELLS SOURCE OF A Lease 100. SUNDRY NOTICES AND REPORTS ON WELLS SOURCE OF A Lease 100. North und. section 5 100. Sox 370 Hobbs, NM 88240 State Line 31lenbur SUBSEQUENT REPORT OF: S	SANTA FE. NEW MEXICO 87501 2.13. Innicine Type of Lower Source Control of Source Co	DISTRIBUTION			Form C-103
SUNDRY NOTICES AND REPORTS ON WELLS Continent Notices of Continent Name P.O. Box 670 Hobbs, NM 88240 State Line 1980	St. Duncas Type o. Lease Store III St. Success Type o. Lease Store III See State St. St. Success Type o. Lease Store III See State St. St. Success Type o. Lease Store III See State St. St. Success Type o. Lease Store III See State St. St. Success Type o. Lease Store III See State St. St. Success Type o. Lease Store III See State St. St. Success Type o. Lease Store III See State St. St. Success Type o. Lease Store III See State St. St. Success Type o. Lease Store III See State St. St. Success Type o. Lease Store III See State St. St. Success Type o. Lease Store III See State St. S		SANTA FE. NEW N	MEXICO 87501	Revised 10-1-
SUNDRY NOTICES AND REPORTS ON WELLS SOURCE OF A GOVERNMENT OF THE STATE OF THE STA	SUNDRY NOTICES AND REPORTS ON WELLS SUBJECT AND SURVEY OF THE SURVEY				(so to
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS CHARGE STATE OF THE TABLE STATE OF THE STATE OF	SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS STATE OF THE STATE OF				
SUNDRY NOTICES AND REPORTS ON WELLS The control of	SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS Chevron U.S.A. Inc. 1. Form of Lense 150me Chevron U.S.A. Inc. 1. Form of Lense 150me Continental State P.O. Box 570 Hobbs, NM 88240 1. Services B 1980 recry from the East 1860 recry for the Policy of Wilder Policy of				
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data North Out. Series Dispensed Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Notice of Intention To: Subscoulant Remort Of: Subscoulant Subscoula	The proposes of Computed Operations (Clearly state all pertinent details, and give pertinent dates, inclining estimated date of statute and perf 5 1/2" cag at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Active Act	3.3.3.			5, State Oll & Gas Lease No.
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data North Out. Series Dispensed Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Notice of Intention To: Subscoulant Remort Of: Subscoulant Subscoula	Chevron U.S.A. Inc. ***********************************	SI MORY	NOTICES IN DESCRIPTION		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data North Out. Series Dispensed Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Notice of Intention To: Subscoulant Remort Of: Subscoulant Subscoula	The proposes of Computed Operations (Clearly state all pertinent details, and give pertinent dates, inclining estimated date of statute and perf 5 1/2" cag at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Active Act	SUNDKY	NOTICES AND REPORTS ON W	ELLS	
**************************************	Chevron U.S.A. Inc. P.O. Box 570 Hobbs, NM 83240 State Line Ellenburgh of the state of the sta	USE APPCICATION	FOR PERMIT -1" (FORM C-101) FOR SUCH !	PROPOSALS.	
Chevron U.S.A. Inc. Chevron U.S.A. Inc. Chevron U.S.A. Inc. Continental State State 100. Continental State State Line State State Line Ellenbur State Line Line State Line State Line Line State Line Line State Line Lin	Chevron U.S.A. Inc. Chevron U.S.A. Inc.				7. Unit Agreement Name
Continenta State P.O. Box 370 Hobbs, NM 88240 15. Field one of Foot, or Wildow 15. Field one Pool, or Wildow 15. County 15. Co	Continenta. State P.O. Box 570 Hobbs, NM 88240 State Line Ellenbur State Line Ellenbur Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: STATE Line CAMPLE PROBLEM OF PARTY OF THE ABOUT CONTINENT OF		OTHER-		
Continental State P.O. Box 370 Hobbs, MH 88240 State Line 21 Lend St	P.O. Box 570 Hobbs, NM 88240 P.O. Box 570 Hobbs, NM 88240 State Line Bilenburg Committee B 1980 State Line Bilenburg Committee B 1980 Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subscount Report of: NOTICE OF INTENTION TO: State Line Bilenburg Committee Box To Indicate Nature of Notice, Report or Other Data Subscount Report of: State Line Bilenburg Committee Committee Box To Indicate Nature of Notice, Report or Other Data Subscount Report of: State Line Bilenburg Committee C	Chevron U.S.A. Inc.			8. Farm or Lease Name
P.O. Box 370 Hobbs, NM 88240 State Cline Ellenbur State Cline State Cl	P.O. 80x 370 Hobbs, MM 88240 Total of Well North North North Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NoTICE OF INTENTION TO: State Line Ellenbur Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice, Report of Other Data SUBSEQUENT REPORT OF: ***Check Appropriate Box To Indicate Nature of Notice,				Continenta State
Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: ***********************************	Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: Check Appropriate Box To Indicate Nature of Notice, Report of Other Data Notice Proposed of Countries of Notice Nature of Nature of Notice Nature of Nat		NM 88240		9. Weil No.
North LIME, SECTION 5 10 AND ARMOOD ACTION AND A	Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Statistic Statistic Of Notice and Appropriate Statistic Of Notice Statistic Of Notice Statistic Of Notice				1
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: CHARGE PLANS CH	Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Counter Fish, Cate To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Counter Fish, Cate To Indicate Nature of Notice, Report or Other And All Path Indicate Indica		-		10. Field and Pool, or Wildcat
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: CHARGE PLANS CH	Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Counter Fish, Cate To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Counter Fish, Cate To Indicate Nature of Notice, Report or Other And All Path Indicate Indica	B 19	80 FEET FROM THE East	860	State Line Ellenbur
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: **CLUCIAL WORK** **CLUCIAL PRODUCTION ACTION AND ASSISTED AND CLUCIAL WORK** **CLUCIAL PRODUCTION ACTION AC	Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Subsequent Rep				minimini il
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: **CLUCIAL WORK** **CLUCIAL PRODUCTION ACTION AND ASSISTED AND CLUCIAL WORK** **CLUCIAL PRODUCTION ACTION AC	Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Subsequent Report of: Subsequent Rep	ME North LINE, SECTION	5 24S	38F '	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPOR	Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ***********************************			MANGE NMP	···(
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPOR	Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ***********************************			RT. GR. etc.)	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: STATICE CASHE CHANGE PLANS CHANGE	Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: ***********************************				
SUBSEQUENT REPORT OF: ***ALTERNACE AND ADMINIST TOPS: ***COMMERCE PLANS*** ***COMMERC	SUBSEQUENT REPORT OF: ***PLUE AND ABANDON** ***PLUE AND ABANDON** ***CANTLE CASINE** ***CHARLE PLANS** CHARLE CASINE** CHARLE PLANS** CHARLE CASINE** CHARLE CASINE** CHARLE CASINE** CHARLE PLANS** CHARLE PLANS** CHARLE PLANS** CHARLE CASINE** CHARLE PLANS** CHARLE PLANS** CHARLE CASINE** CHARLE CASINE** CHARLE CASINE** CHARLE CASINE** CHARLE CASINE** CHARLE CASINE** CASINE PLANS** CASINE PLANS** CASINE PLANS** CASINE TO ALLIES OF ALLIES	Check Ap	propriate Boy To Indiana Na		
POOR w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	POOR W/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. **COMMENCE OFFICE RY LERGY CEVICAL STREET RESIDENCE OF AUGUST 180. AUGUST 18	NOTICE OF INT	ENTION TO		
COMMENCE OFFICE CASING PUGG AND ASSESSMENT TO CASING ON THE PUGG AND ASSESSMENT TO CASING ON THE FISH, perf, acdz, rtn to prod. X SECULAR FISH, perf, acdz, rtn to p	**************************************	NO FIGE OF INT	ENTION TO:	SUBSEQUE	NT REPORT OF:
COMMENCE OFFICE CASING PUGG AND ASSESSMENT TO CASING ON THE PUGG AND ASSESSMENT TO CASING ON THE FISH, perf, acdz, rtn to prod. X SECULAR FISH, perf, acdz, rtn to p	**************************************	-u -cucou			
PACTICE CASING CASHING TEST AND CLINICATION OF THE FISH, perf, acdz, rtn to prod. CASHING TEST AND CLINICATION. Fish, perf, acdz, rtn to prod. Exprise Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose its starting any propose its pertinent dates. Including estimated date of starting any propose its pertinent dates. The performed 7-20-88 thru 7-31-88 POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	POOR W/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143". Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. **RONGER AND ORIGINAL SIGNED BY JERCY CEXTON.** **TITLE: Staff Drilling Engineer** **August 8, 198** **ORIGINAL SIGNED BY JERCY CEXTON.**	=	PLUG AND ABANDON R	EMEDIAL WORK	ALTERING CASING
retite Processed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose is see Nulls 163. Reperformed 7-20-88 thru 7-31-88 TD: 12,161 PB: 12,158 POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	ornes fish, perf, acdz, rtn to prod. [Statistics fish, performed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of statistic any propositions of the performed of the pe	≻ =<		OMMENCE ORILLING OPHS.	PLUG AND ABANDONMENT
POOD w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 11,868. Circ hole clean. Fish, catch fish, work fish free. GH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose its performed 7-20-88 thru 7-31-88 TD: 12,161 PB: 12,158 POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHFF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	OR ALTER CASING	CHANGE PLANS	ASING TEST AND CEMENT JOB	
POOD we rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	Proposes of Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any propose styles are set incl. 163. Experiment 7-20-88 thru 7-31-88 POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHFF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.			other fish, perf.a	cdz, rtn to prod. x
POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. The Staff Drilling Engineer August 8, 198 ORIGINAL SIGNED BY JERSY SEXION.	HER			
POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. The Staff Drilling Engineer August 8, 198 ORIGINAL SCONED BY JERRY CEXICAL	Scribe Proposed or Completed Opera	Hone (Clearly seems all and		
POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. **TOTAL STATE OF THE INCOMPAGE AND STATE OF THE PROPERTY STATES.** **TOTAL STATES** STATES** **TOTAL STATES** *	rk) SEE RULE 1 (01.	tions (Clearly state all perlinent details	, and give pertinent dates, includi	ng estimated date of starting any proposed
POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	POOH w/ rods. Ran free point, tbg 100% free at 11,903. 100% stuck at 11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. **TOTAL STATE OF THE INCOMPAGE AND STATE OF THE PROPERTY STATES.** **TOTAL STATES** STATES** **TOTAL STATES** *	rk nerformed 7-20-8	9 +hru 7-31-00	mp. 12 161 pp	10 100
11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	in periormed / 20 8	0 tillu /-31-66	TD: 12,101 PB	12,158
11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	11,923. Made chemical cut at 11,865. Wash from 11,861 - 11,868. Circ hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	DOOR w/ rodg B	an free noint the 1	200 F 11 002	1000
hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	hole clean. Fish, catch fish, work fish free. GIH w/ 3 1/8" csg gun and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	11 022 M-Jh	an free point, the fi	00% free at 11,903	100% stuck at
and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	and perf 5 1/2" csg at 12,042 - 12,066 w/ 1 JHPF, 24 holes, 180° phase. Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	11,923. Made cn	emical cut at 11,865	. Wash from 11,86	1 - 11,868. Circ
Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	Acdz new perfs w/3000 gallons 15% NEFE HCL, dropping 1 - 1.3 SG RCNB's every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. **TOTAL STATE OF BY JERRY CANICAL THREE STATE OF THE PROPERTY OF T	noie clean. Fish	, catch fish, work fi	ish free. GIH w/	3 1/8" csg gun
every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	every 2 bbls, swab. Attempt to latch onto RBP. Release RBP, unable to release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. **REPLY CERTLY THAT THE INformation above is true and complete to the best of my knowledge and belief. **ORIGINAL SIGNED BY JERRY CEXTON.** **ORIGINAL SIGNED BY JERRY CEXTON.** **ORIGINAL SIGNED BY JERRY CEXTON.**	and perf 5 1/2"	csg at 12,042 - 12,0	66 w/ 1 JHPF, 24 h	oles, 180° phase.
release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. **Recovery that the information above is true and complete to the best of my knowledge and belief. **TITLE: Staff Drilling Engineer** August 8, 198 **ORIGINAL SIGNED BY JERRY CEXTON!				
release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	release, sheared top sleeve off RBP. RU swivel, work over and latch fish. Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. **Recovery that the information above is true and complete to the best of my knowledge and belief. **TITLE: Staff Drilling Engineer** August 8, 198 **ORIGINAL SIGNED BY JERRY CEXTON!	every 2 bbls, sw	ab. Attempt to late!	n onto RBP. Relea	se RBP, unable to
Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	Pull RBP free, full recovery. Swab test. Run 2 7/8" to 12,143'. Pump 30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. Telly certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY JERRY SEXICAL	release, sheared	top sleeve off RBP.	RU swivel, work	over and latch fish.
30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88.	30bbl CBW, 500gal 15% NEFE. Run pump and rods, test tbg and pump action to 500psi. RDPU, clean location, turn over to production dept. NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. The certify that the information above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY JERRY SEXTON.	Pull RBP free, f	ull recovery. Swab	test. Run 2 7/8"	to 12.143'. Pump
NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. THE Staff Drilling Engineer August 8, 1988	NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. The configuration above is true and complete to the best of my knowledge and belief. ORIGINAL SIGNED BY JERRY SEXICAL				
NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. reby certify that the information above is true and complete to the best of my knowledge and belief. m. E. Alexin 1988	NOTE: Procedure was changed during operations and verbal approval was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. Teby certify that the information above is true and complete to the best of my knowledge and belief. TITLE: Staff Drilling Engineer OATE August 8, 198 ORIGINAL SIGNED BY JERRY SEXICAL				
was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. Teby certify that the information above is true and complete to the best of my knowledge and belief. M. E. Alexin Title: Staff Drilling Engineer Oare August 8, 1988	was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. reby certify that the information above is true and complete to the best of my knowledge and belief. M. E. Alexin river: Staff Drilling Engineer OATE August 8, 198 ORIGINAL SIGNED BY JERRY SEXTON!	co ocopat. Rai o	, cream rocacrom, c	arm over to produc	cron dept.
was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. Teby certify that the information above is true and complete to the best of my knowledge and belief. M. E. Alexin Title: Staff Drilling Engineer Oare August 8, 1988	was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. reby certify that the information above is true and complete to the best of my knowledge and belief. M. E. Alexin river: Staff Drilling Engineer OATE August 8, 198 ORIGINAL SIGNED BY JERRY SEXTON!				
was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. Teby certify that the information above is true and complete to the best of my knowledge and belief. TITLE: Staff Drilling Engineer OATE August 8, 1988	was received for adding perfs from Evelyn Downs with NM OCD 7-21-88. repy certify that the information above is true and complete to the best of my knowledge and belief. M. E. Alexin river Staff Drilling Engineer ource August 8, 198 ORIGINAL SIGNED BY JERRY SEXTON!	NOTE: Procedure	was changed during	anorations and war	hal approval
7-21-88. reby certify that the Information above is true and complete to the best of my knowledge and belief. m. E. Akin ritle: Staff Drilling Engineer Oare August 8, 1988	7-21-88. reby certify that the information above is true and complete to the best of my knowledge and belief. M. E. Alberia TITLE Staff Drilling Engineer OATE August 8, 198 ORIGINAL SIGNED BY JERRY SEXTON!				
reby certify that the information above is true and complete to the best of my knowledge and belief. M. E. Akin ritle: Staff Drilling Engineer OATE August 8, 1988	original Signed by Jerry Sextical		ved for adding peris	TIOM EVELYH DOWNS	WILL NET OCD
m. E. alenn Time: Staff Drilling Engineer August 8, 1988	ORIGINAL SIGNED BY JERRY SEXTON	,-21-88.			
m. E. alenn Staff Drilling Engineer August 8, 1988	ORIGINAL SIGNED BY JERRY SEXTON				
m. E. alemin Staff Drilling Engineer August 8, 1988	ORIGINAL SIGNED BY JERRY SEXTON				
m. E. alenn Time: Staff Drilling Engineer August 8, 1988	ORIGINAL SIGNED BY JERRY SEXTON	reby certify that the information abo	ve is true and complete to the hear of m	k knowledge and but of	
	ORIGINAL SIGNED BY JERRY SEXTON		/	wredge and bettet.	
	ORIGINAL SIGNED BY JERRY SEXTON	m & al	,)		
	ORIGINAL SIGNED BY JERRY SEXTON	1.2.000	rine Staf	t Drilling Enginee	er 🔐 August 8, 1988
	- TOTAL SOMEO BY JERSY SEXTON				