		Oil Co
	NITED STATES	1980 FORM APPROVED
June 13007	F LAND MANAGEMENT	S, NM 88241 Budget Bureau No. 1004-0135
		Expires: March 31, 1993
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		5. Lease Designation and Serial No. LC032592B NM-14218
		6. If Indian, Alottee or Tribe Name
	FOR PERMIT " for such proposals	
SUB	MIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well: Xell OIL GAS WELL WELL	OTHER	8. Well Name and Number FRISTOE, C. CB- FED. NCT-2
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.		10
3. Address and Telephone No. 205 E. Bender, HOBBS, NM 88240 397-0432		9. API Well No. 30 025 21413
4. Location of Well (Footage, Sec., T., R., M., or	Survey Description)	10. Field and Pool, Exploaratory Area
Unit Letter P : 660 Feet From	The SOUTH Line and 989 Feet From Th	
EAST Line Section 26	Township 24S Range 37E	11. County or Parish, State
		LEA , NEW MEXICO
^{12.} Check Appropriate	e Box(s) To Indicate Nature of Notice	, Report, or Other Data
TYPE OF SUBMISSION		TYPE OF ACTION
	Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair Casing Casing	Water Shut-Off Conversion to Injection
Final Abandonment Notice	OTHER:	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)
 Describe Proposed or Completed Operations (C work. If well is directionally drilled, give subsu 	learly state all pertinent details, and give pertinent date rface locations and measured and true vertical depths f	s, including estimated date of starting any proposed
11-22-96: Miru From North String pull & lay do	wn rods & pump. Install BOP. Pull & lay down tubing	. Shut in. Rig down.
12-04-96. Mild. Clean out on south string wiNz 12-05-96: In North String spot 35 sx cement fro 6040' to 5100'. Pull tbg to 5100'. Circulate 5 sx	to 6040'. POH. Shut in. Rig up on North string. Clope 6040' to 5100'. Circulate 5 sx cement to pit. POH cement to pit. POH. Rig down.	. Rig up on South String. Spot 35 sx cement from
12-06-96: WOC.		the production
minutes. Pressure down to 100 psi in 9.5 minut string. Load casing w/1.7 bbls 2% KCL fresh wa	ressure casing to 700 psi. Pressure dropped to 300 p es. No communication to South string. No communic ater. Pressure casing to 1000 psiVery Slight leak are	ation to Bradenhead Shut in Rig up on SOUTH
communication to Bradenhead. Prep to make re 03-07-97: On NORTH string: Tag cement @ 03-10-97: Test North String to 2000 psi-Held	5223'. Ran & set 2 7/8" CIBP @5135'. Dumped 35' o	cement, 5100' (New PBTD). hold 500 psi; starts leaking at pressure above 500 psi.
Shut in.		
4908"-5002 (3226" holes). Shut in.	from 5108' to 4100'. Ran Orientated Perforating Gun.	
pres on 2 7/8" casing=930 psi. ISIP=920 psi. 1	al 15% NE-FE in 1 stage. Flush w/25 bbls 2% Kcl fr 5 Min SIP=860 psi. Avg rate=1.0 BPM. Shut in. SO this am=340 psi. Flowing 1 hr on 18/64" choke. No	esh water. Max pres on 2 7/8" casing=1490 psi. Min IUTH STRING: No pressure; no work.
measurement on Gas. Shut in. SOUTH STRIN	IG: Shut in. Casing pressure=0 psi.	
STRING: Shut in. Casing pressure=0 psi.		50 psi flowline pressure in 5 minutes. Shut in. SOUTH
05-11-97: NORTH STRING: Shut in 24 hrs. C 05-12-97: NORTH STRING: =175 psi. Bled do	asing pressire=175 psi. Left shut in. SOUTH STRIN wn in 5 minutes. Recovered gas only. Shut in. SOU	NG: Shut in. TH STRING: Shut in.
		OVER
14. Thereby cartify that the foreating is true and correct SIGNATURE	TITLE Engineering Assistant	DATE 10/16/97
TYPE OR PRINT NAME CCEPTED FOR HEC	o yes	
(This space for Federal or State office Use)		
APPROVED BY CONDITIONS OF APPROVAL, IN ANY 199		DATE
Title 18 U.S.C. Section 1001 makes it a crime for any perso representations as to any matter within its presentation	n knowingly and willfully to make to any department or agency of the	United States any false, fictitious or fraudulent statements or
	2 -1 - 2 -	DeSoto/Nichols 12-93 ver 1.0 5 232

05-14-97: NORTH STRING: Shut in. Casing poressure=70 psi. SOUTH STRING: Shut in. Casing pressure=0 psi.

05-15-97: NORTH STRING: Casing pressure=90 psi. Open to Test Tank. Bled down in 30 minutes. Recovered 0 Oil, 24 Water, & Fair Gas. Very slight contineous gas flow. SOUTH STRING: Shut in. Casing pressure=0 psi.

05-16-97: NORTH STRING: Shut in. Casing pressure=65 psi. SOUTH STRING: Shut in. Casing pressure=0 psi.

05-17-97: NORTH STRING: Casing pressure=110 psi. Flow to Test Tank. Bled down in 30 minutes. Recovered 0 Oil, 28 Water, & Fair Gas. Very slight contineous gas flow. SOUTH STRING: Shut in. Casing pressure=0 psi

05-19-97: NORTH STRING: Shut in. Casing pressure=60 psi. SOUTH STRING: Shut in. Casing pressure=0 psi.

05-20-97: NORTH STRING: Shut in. Casing pressure=60 psi. SOUTH STRING: Shut in. Casing pressure=0 psi.

05-21-97: NORTH STRING: Casing pressure=0 psi. Miru Swab Unit. Swab 3 hrs (6 runs). Recovered 0 Oil, 32 Water, & Fair Gas. Rig down. Shut in. SOUTH STRING: Shut in. Casing pressure=0 psi.

05-26-97: NORTH STRING: Shut in. Casing pressure=120 psi. SOUTH STRING: Shut in. Casing pressure=0 psi.

05-27-97: NORTH STRING: Shut in. Casing pressure=120 psi. <-8 BLW> SOUTH STRING: Shut in. Casing pressure=0 psi.

05-28-97: Shut in. Workover unsuccessful. Change status from Workover to Shut In-Oil (Paddock Zone) effective 5-28-97. Recommend Plug & Abandon. FINAL REPORT.

P014-21173...901

2月市 ∀ 22.12111