State of New Mexico Energy: terals and Natural Resources Department	Form C-103 Revised 1-1-89
to Appropriate	WELL API NO.
DISTRICT I OIL CONSERVATION DIVISION DISTRICT I P.O. BOX 2088	30-025-22204
P.O. Box 1989. Hobbs. NM 88248	5. Indicate Type of Lease
Santa Fe, New Mexico 87504-2008	
P.O. Drawer DD, Artesia, NM 88210	STATE X FEE
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	NMJ-540
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	7. Lease Name or Unit Agreement Name Eaton SW J. H.
i. Type of Well: OIL GAS	Lawii 5 II V. II.
WELL X WELL other 2. Name of Operator	8. Well No.
ARCO OIL and GAS COMPANY	10
3. Adress of Operator	9. Pool Name or Wildcat
P.O. Box 1610, Midland, Texas 79702	Justis Blinebry- Duntin T/DI
Unit Letter N : 500 Feet From The South Line and 1650	Feet from The <u>West</u> Line
Section 12 Township 25S Range 37E NMPM	Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
11. Check Appropriate Box To Indicate Nature of Notice, Report,	or Other Data
NOTICE OF INTENTION TO: SUBSI	EQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	EQUENT REPORT OF: ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING TEST AND CEMENT JO	ALTERING CASING PLUG AND ABANDONMENT DB X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING COMMENCE DRILLING OPNS. (Other) (Other)	ALTERING CASING PLUG AND ABANDONMENT X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING CASING TEST AND CEMENT JO (Other) (Other) 12. Describe Proposed or completed Operation/Clearly state allpertinent dates, including estimated date of starting awark) SBE RULB 1103.	ALTERING CASING PLUG AND ABANDONMENT X Any proposed 10. RDPU. "H" f/1039-surf. Circ cmt out uccess. Spot 100' C1 "H" cmt
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING (Other) (Other) 12. Describe Proposed or completed Operation/Clearly state all pertinent dates, including estimated date of starting a work) SBB RULE 1103. 6-28-91. RUPU. Unable to pull stuck tbg, chem cut at 5110. Fish w/no success. Set CIBP at 505 9-03-91. RUPU. Isolated holes in casing f/surf-1009. Holes in 8-5/8 csg at surf. Spot 375 sx 5-1/2 x 8-5/8 and 8-5/8 x ground. WOC. tag TOC at 70°. DO cmt 1050. Press test csg w/no s	ALTERING CASING PLUG AND ABANDONMENT X Any proposed 10. RDPU. "H" f/1039-surf. Circ cmt out uccess. Spot 100' C1 "H" cmt
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING (Other) (Other) 12. Describe Proposed or completed Operation/Clearly state all pertinent dates, including estimated date of starting a work) SBE RULB 1103. 6-28-91. RUPU. Unable to pull stuck tbg.chem cut at 5110. Fish w/no success. Set CIBP at 505 9-03-91. RUPU. Isolated holes in casing f/surf-1009. Holes in 8-5/8 csg at surf. Spot 375 sx 5-1/2 x 8-5/8 and 8-5/8 x ground. WOC. tag TOC at 70°. DO cmt 1050. Press test csg w/no s f/3630-3530. Pkr fluid f/3530-2200. Spot 100° cmt f/2290-2190 (BOS). Pkr fluid f/2190-1000	ALTERING CASING PLUG AND ABANDONMENT X Any proposed 10. RDPU. "H" f/1039-surf. Circ cmt out uccess. Spot 100' C1 "H" cmt
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING (Other) (Other) 12. Describe Proposed or completed Operation(Clearly state allpertinent dates, including estimated date of starting a work) SBE RULE 1103. 6-28-91. RUPU. Unable to pull stuck tbg, chem cut at 5110. Fish w/no success. Set CIBP at 505 9-03-91. RUPU. Isolated holes in casing f/surf-1009. Holes in 8-5/8 csg at surf. Spot 375 sx 5-1/2 x 8-5/8 and 8-5/8 x ground. WOC. tag TOC at 70°. DO cmt 1050. Press test csg w/no s f/3630-3530. Pkr fluid f/3530-2200. Spot 100° cmt f/2290-2190 (BOS). Pkr fluid f/2190-1000 9-10-91. Temporarily Abandon.	ALTERING CASING PLUG AND ABANDONMENT X Any proposed 10. RDPU. "H" f/1039-surf. Circ cmt out uccess. Spot 100' C1 "H" cmt
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOURNAL COMMENCE DRILLING OPNS. (Other) (Other) (Other) 12. Describe Proposed or completed Operation/Clearly state all pertinent dates, including estimated date of starting a work) SBE RULE 1103. 6-28-91. RUPU. Unable to pull stuck tbg.chem cut at 5110. Fish w/no sucess. Set CIBP at 505. 9-03-91. RUPU. Isolated holes in casing f/surf-1009. Holes in 8-5/8 csg at surf. Spot 375 sx 5-1/2 x 8-5/8 and 8-5/8 x ground. WOC. tag TOC at 70'. DO cmt 1050. Press test csg w/no s f/3630-3530. Pkr fluid f/3530-2200. Spot 100' cmt f/2290-2190 (BOS). Pkr fluid f/2190-1000 9-10-91. Temporarily Abandon.	ALTERING CASING PLUG AND ABANDONMENT X Any proposed 10. RDPU. "H" f/1039-surf. Circ cmt out success. Spot 100' C1 "H" cmt ont content of the content of
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING (Other) (Other) 12. Describe Proposed or completed Operation(Clearly state allpertinent dates, including estimated date of starting a work) SBE RULE 1103. 6-28-91. RUPU. Unable to pull stuck tbg, chem cut at 5110. Fish w/no success. Set CIBP at 505 9-03-91. RUPU. Isolated holes in casing f/surf-1009. Holes in 8-5/8 csg at surf. Spot 375 sx 5-1/2 x 8-5/8 and 8-5/8 x ground. WOC. tag TOC at 70°. DO cmt 1050. Press test csg w/no s f/3630-3530. Pkr fluid f/3530-2200. Spot 100° cmt f/2290-2190 (BOS). Pkr fluid f/2190-1000 9-10-91. Temporarily Abandon.	ALTERING CASING PLUG AND ABANDONMENT X Ty proposed 10. RDPU. "H" f/1039-surf. Circ cmt out uccess. Spot 100' C1 "H" cmt D. Spot cmt f/1050-surf. RDPU
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOURNAL COMMENCE DRILLING OPNS. (Other) (Other) (Other) 12. Describe Proposed or completed Operation/Clearly state all pertinent dates, including estimated date of starting a work) SBE RULE 1103. 6-28-91. RUPU. Unable to pull stuck tbg.chem cut at 5110. Fish w/no sucess. Set CIBP at 505. 9-03-91. RUPU. Isolated holes in casing f/surf-1009. Holes in 8-5/8 csg at surf. Spot 375 sx 5-1/2 x 8-5/8 and 8-5/8 x ground. WOC. tag TOC at 70'. DO cmt 1050. Press test csg w/no s f/3630-3530. Pkr fluid f/3530-2200. Spot 100' cmt f/2290-2190 (BOS). Pkr fluid f/2190-1000 9-10-91. Temporarily Abandon.	ALTERING CASING PLUG AND ABANDONMENT X Any proposed 60. RDPU. "H" f/1039-surf. Circ cmt out out out out out out out out out ou

APPROVED BY __

CONDITIONS FOR APPROVAL, IF ANY:

This Approval of Temporary
Abandonmer: Expires

1-13 96

DATE _

MAR 23