

ALL WORK RECOMMENDATIONS
Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

AUG 12 1 42 PM '69

Lease: Fristoe Well No. 7Field: Langlie MattixCounty: Lea State: New MexicoRECOMMENDED PROCEDURE:

1. Drill the well 90' deeper from T.D. of 3360' to 3450'.
2. Run a Gamma Ray - Neutron Log from the new T.D. of 3450' through the minimum logging interval.
3. Wash the new open hole section (3,360' - 3,450' - 90') with 500 gals of 15% non-emulsion, iron stabilized, HCl acid.
4. Run 2", acid resistant, cement-lined tubing and an injection packer. Load the tubing-casing annulus with fresh water treated with 10 gals of Certon 2207 per 1000 gals of water. Set the packer approximately 50' above the top of the injection interval.
5. Put the well on injection. - Pump into well. get volume + rate + pressure.
W. Niederhofer
John E. Smith
6-23-69