

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instruction re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM 0559805

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Fairview Mills-Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wolfcamp Gas

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 14, T-25-S, R-34-E

12. COUNTY OR PARISH 13. STATE

Lea

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Exxon Corporation

3. ADDRESS OF OPERATOR

Box 1600, Midland, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

990' FSL and 1,980 FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3332' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☒MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

1. Run a plug on wireline and set in profile nipple.
2. Release tubing from packer and cap packer with 35' of cement.
3. Freepoint cut and pull 7-5/8" casing.
4. Spot a 55 sx cement plug across 7-5/8 cut point.
5. Load the hole with mud consisting of 25 sx (100# ea.) of salt gel per 100 bbls of 9.5# brine.
6. Freepoint 10-3/4" casing.
7. If freepoint is below 500' \pm cut and pull casing. Spot a 75 sx cement plug across 10-3/4" casing cut and a 75 sx cement plug from 950'-1050' across top of salt section.
8. If freepoint is above 500+ perforate casing and circulate cement to surface.
9. Cap well with 10' cement. Plug at surface.
10. Install dry hole marker and clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED

W. M. Platon

TITLE

Unit Head

DATE

10-12-76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
AS AMENDED
OCT 19 1976ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side