

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM C-101 FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator <u>Amerada Hess Corporation</u>	8. Farm or Lease Name <u>L. M. W. U.</u>
3. Address of Operator <u>Drawer D. Monument, New Mexico 88265</u>	9. Well No. <u>#9</u>
4. Location of Well UNIT LETTER <u>I</u> <u>1330</u> FEET FROM THE <u>South</u> LINE AND <u>135'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>24S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat <u>Langlie Mattix 7 RO</u>
11. Elevation (Show whether DF, RT, GR, etc.) <u>3202' GR</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER ☐

SUSSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	OTHER ☒ <u>Progress report</u>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 2-15-85 to 2-25-85 - Ran gauge ring & junk basket in 7" csg. to 4040'. Set CI bridge plug in 7" csg. at 4020' & dumped 2 sks. cement on top of bridge plug. Calculated top of cement at 4000'. Ran 2-7/8" tbg. to 3583' & circ. hole clean using produced water. Spotted perf. acid & perf. 7" csg. opposite Penrose fr. 3541' to 3567' & fr. 3571' to 3580' w/2 SPF. Ran pkr. & tbg. & set pkr. at 3488' & ran GR & temperature log in 7" csg. fr. 3600' to 3530'. Acidized Penrose zone thru 7" csg. perf. fr. 3541' to 3567' & fr. 3571' to 3580' w/15% MMR radio active acid w/nitrogen pad using ball sealers as diverter. Ran GR & temp. log. Swabbed load. Released pkr. & ran pump & rods & started pumping. Test of 2-27-85: Pumped 8 b.o. & 46 b.w. in 24 hrs. on 6-144" SPM. 3-4-85 to 3-9-85 - Pulled rods & pump & 2-7/8" tbg. Perf. 7" csg. opposite Penrose zone fr. 3582' to 3592' w/2 SPF. Ran PPI pkr. & tbg. Ran GR & temp. log fr. 3714' to 3480'. Set pkr. at 3600' & acidized Penrose zone thru 7" csg. perf. fr. 3582' to 3592' w/15% MMR radio active acid using PPI pkr. Release dpr. & ran to 3724' & ran GR & temp. log fr. 3714' to 3150'. Re-set pkr. at 3519' & swabbed load. Ran pump & rods and resumed pumping. Test of 3-10-85: Pumped 25 b.o. & 383 b.w. in 24 hrs. on 6-144" SPM. 3-11-85 to 3-14-85 - Pulled rods, pump & tbg. Set retrievable bridge plug in 7" csg. at 3529' & spotted 2 sks. sand on top of bridge plug. Spotted perf. acid & perf. 7" csg. opposite Queen zone fr. 3425' to 3428', 3435' to 3539', 3457' to 3471' w/2 SPF. Ran pkr. & tbg. & set pkr. at 3341'. Ran GR & temp. log fr. 3521' to 3200'. Acidized Queen zone thru 7" csg. perf. fr. 3425' to 3428', 3435' to 3439' & 3457' to 3471' w/1000 gal. MMR radio active acid using ball

Continued

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED E. B. Fisher TITLE Supv. Adm. Ser. DATE 4-17-85

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT 1 SUPERVISOR

SEP 17 1985

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: