LLING PROGNOSIS

I. Well Identification:

Lease Name:_	Odessa Langlie Federal
Well No.:	1
Location: _	1650 FSL and 660 FEL Section & 14
	T-25-S, R-37-E
County: _	Lea
State: _	New Mexico
Elevations:	3098.5 G.L. (3108.5 RKB)

II. <u>Drilling Objective</u>:

Zone:	Queen-Penrose	
Total Depth:	3700	
Pool Name:	Langlie Mattix	
Productive In	nterval: 3040-3250	

III. <u>Formation Tops</u>:

Zone	Top Drilling Depth	os Subse a Depth	Gross Interval Drilled	Probable Fluid Production
Rustler Anhydrite	870	+2238	105	
Salado Salt	975	+2133	1265	
Tansil	2240	+ 868	150	
Yates	2390	+ 718	250	
Seven Rivers	2640	+ 468	430	
Queen	3070	+ 38	100	Gas
Penrose	3170	- 62	190	Gas
Grayburg	3360	- 252	340	
TOTAL DEPTH	3700	- 592	3700	

IV. <u>Hole Size</u>:

Hole	Bit Size	T.D.	Gross <u>Interval</u>
Conductor	15	40	40
Surface	12 1/4	800	760
Production	7 7/8	3700	2900

V. <u>Casing Program</u>:

A. Casing Design

String	0.D.	asing Si Wt.	<u>ze</u> Grade	Threads	Amount	Cond.
Conductor	13 3/8	33	В	8 Rd	30	New
Surface	8 5/8	28	В	8 Rd	800	Used
Production	5 1/2	17.0	J-55	8 Rd	3700	New

. B. Float Equipment:

Surface Casing: _	8	5/8-inch	guide-shoe	and	8	5/8-inch	insert	float.
						•		
Production Casing	g: <u>5</u>	1/2-inch	guide-shoe	and	5	1/2-inch	float	collar
with automatic fi	11.							

C. Centralizers:

Surface Casing:	One centralizer	at	the	float	collar	and	one	centralizer
two joints above	e float collar.			ı				
				* 4.	<u> </u>			
			•					

Larkin 8 5/8 x 5 1/2 Fig 92 Casinghead. Larkin 5 1/2 x 2 3/8 Type TH tubinghead complete with slips and bell nipple. Mud Program		Production Casing: tall a total of 8 centralizers. Prace one centrali
D. Wellhead Equipment: Larkin 8 5/8 x 5 1/2 Fig 92 Casinghead. Larkin 5 1/2 x 2 3/8 Type TH tubinghead complete with slips and bell nipple. A. Surface Hole: Drill surface hole with a fresh water gel (approximately 8.5 lb/gal) while maintaining a high enough viscosity to adequately clean hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working		at the guide shoe and one centralizer at the float collar with the
Larkin 8 5/8 x 5 1/2 Fig 92 Casinghead. Larkin 5 1/2 x 2 3/8 Type TH tubinghead complete with slips and bell nipple. A. Surface Hole: Drill surface hole with a fresh water gel (approximately 8.5 lb/gal) while maintaining a high enough viscosity to adequately clean hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working		remaining being placed 80 to 90 feet apart or every other joint.
Larkin 8 5/8 x 5 1/2 Fig 92 Casinghead. Larkin 5 1/2 x 2 3/8 Type TH tubinghead complete with slips and bell nipple. A. Surface Hole: Drill surface hole with a fresh water gel (approximately 8.5 lb/gal) while maintaining a high enough viscosity to adequately clean hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working		
Larkin 8 5/8 x 5 1/2 Fig 92 Casinghead. Larkin 5 1/2 x 2 3/8 Type TH tubinghead complete with slips and bell nipple. A. Surface Hole: Drill surface hole with a fresh water gel (approximately 8.5 lb/gal) while maintaining a high enough viscosity to adequately clean hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working	D.	Wellhead Equipment:
Type TH tubinghead complete with slips and bell nipple. A. Surface Hole: Drill surface hole with a fresh water gel (approximately 8.5 lb/gal) while maintaining a high enough viscosity to adequately clean hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working		
A. Surface Hole: Drill surface hole with a fresh water gel (approximately 8.5 lb/gal) while maintaining a high enough viscosity to adequately clean hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working		
Drill surface hole with a fresh water gel (approximately 8.5 lb/gal) while maintaining a high enough viscosity to adequately clean hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working		Type III tubinghead complete with slips and bell nipple.
Drill surface hole with a fresh water gel (approximately 8.5 lb/gal) while maintaining a high enough viscosity to adequately clean hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working		
Drill surface hole with a fresh water gel (approximately 8.5 lb/gal) while maintaining a high enough viscosity to adequately clean hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working		
Drill surface hole with a fresh water gel (approximately 8.5 lb/gal) while maintaining a high enough viscosity to adequately clean hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working	Mud	Program
while maintaining a high enough viscosity to adequately clean hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working	Α.	Surface Hole:
hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working		Drill surface hole with a fresh water gel (approximately 8.5 lb/gal)
hole. Add paper as needed to control excess seepage. Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working		while maintaining a high enough viscosity to adequately clean
Before drilling below surface pipe, jet cuttings out of working pit into reserve pit and then switch from circulating through working		
into reserve pit and then switch from circulating through working		
into reserve pit and then switch from circulating through working		Before drilling below surface pipe, jet cuttings out of working nit
,		
		pro to encurating through reserve pro.
. Production Hole:	В.	Production Hole:
Before entering salt section, switch mud system to a saturated salt		Before entering salt section, switch mud system to a saturated salt
system (10.1 lb/gal). At 2925, switch back out of reserve pit and		· · · · · · · · · · · · · · · · · · ·
back into working pit. Also at this point, start adding starch and		
		brine gel to lower water loss and raise viscosity. The mud shall have
a water loss of 10 cc/30 min and a viscosity of 34 to 36 sec. before	•	

	reaching 3040 (top of Queen pay).
	In order to protect the drill string, sufficient lime shall be
	added to the mud to maintain a safe PH level.
Cem	enting Program
Α.	Surface Pipe:
	Cement surface pipe with approximately 500 sacks (or as required)
	of API Class-C cement containing 2% Calcium Chloride. Before resuming
	drilling operations, allow cement to set for a sufficient time to
	gain a 500-psi compressive strength (18 hours). Also before
	drilling plug, the pipe shall be tested to 700 psi for 30 minutes.
В.	Production String:
	Cement long string with approximately 350 sacks API Class-C cement
	containing 3% Halliburton Econolite mixed to a slurry weight of
	11.3 lb/gal followed by 250 sacks of a 50-50 blend of Pozmix "A"
	and API Class-C cement containing 18% salt and 2% gel and having a slurry
	weight of 14.1 lb/gal. Pump 30 barrels of water ahead of the
	cement to help remove the mud filter cake.
	N.
	Once top plug is bumped, pressure test casing to 1500 psi.
	The total specified cement volume of 600 sacks provides for an

VII.

		excess that should be sufficient to bring the cement top back to
		the surface. Before the cement job is actually performed, the
		required cement volume will be checked against the open hole caliper
		log to determine the actual amount of cement necessary to bring the
/III.	Fox	cement back to the surface.
1111.		Drilling Rate:
	Λ.	1. The drilling rate shall be monitored with a geolograph from
		the surface to total depth.
		the surface to total depth.
		2. As part of their farmout agreement, El Paso Natural Gas Company
		requires that the penetration rate be tabulated in 10-feet
		increments over the entire hole.
	В.	Well Cutting Samples:
	υ.	• . '
		One set of well cutting samples shall be gathered every 10 feet from the surface to total depth. Each sample is to be cleaned,
		bagged, and tagged and then grouped into bundles of ten samples per
•		bundle with one bundle representing each 100-feet drilled.
		build te writi one buildre representing each 100-reet driffed.
		After the drill cuttings have been reviewed by the wellsite geologist,
		they shall be delivered weekly to Midland Sample Cut, 704 S. Pecos Street
		Midland, Texas.
		, , , , , , , , , , , , , , , , , , ,
		If requested by the wellsite geologist, a second set of samples shall
		be gathered over the Queen-Penrose-Grayburg interval.

C. Mud Logging:ne		-	
D. Drill-Stem Testing: None		* .	
E. Coring: None			
F. Well Logging:			
Open II			
	ole Logs Inte	mua l	
Log	2" = 100'	5" = 100'	
CDL-Neutron-GR	T.D Surface	T.D 2150	
Guard -Forxo	T.D 2150	T.D 2150	
		·	
		• • • • • • • • • • • • • • • • • • •	
Cased-	Hole Logs		
Log	Inte	rval	
	2" = 100'	5" = 100'	
GRN-CCL	T.D 2150	T.D 2150	
		·	
Log Dis	tribution		
Company	No. of Copies		
	Field Prints	Final Prings	
Doyle Hartman 508 C & K Petroleum Building Midland, Texas 79701	5	5	
United States Geological Survey P. O. Box 1157 Hobbs, New Mexico 88240	2	2	

Company	No. o Jopies				
	Field Prints	Final Prints			
El Paso Natural Gas Company	2	4			
P. O. Box 1492					

Attention: Land Department

El Paso, Texas 79978

Note: Logs shall be delivered to the above parties within 24 hrs. after becoming available.


IX. Blowout Preventer System:

A 10 3/4 2000-psi rotating head will be used while drilling the surface			
hole. Before drilling out from under the surface pipe, the well will be			
equipped with a 3000-psi 10-inch series 900 double-ram hydraulic			
preventer. The blowout preventer shall be used through the running of			
the production string.			
Attached is a diagram of the required BOP system.			
,			
\(\frac{1}{4}\)			


Χ.	And and the second seco	
۸.	Hazardous Zones:	
	None anticipated.	
	to thated.	
		-
	Ouration of o	
XI.	Ouration of Operations:	
-	the talks	
-	ne total elapsed time required	
S	ubject woll:	
	he total elapsed time required for drilling and completing ubject well is expected to be thirty days	the
	ubject well is expected to be thirty days.	
		-
	·	

X

!



Shaffer Type E Series 900 Hydraulic B.O.P.



3000 PSI WORKING PRESSURE BLOWOUT PREVENTER HOOK-UP

Series 900 Flanges, or Better.

Note: B.O.P system will meet the conditions of drilling approval required by the USGS District Office in Hobbs, New Mexico.