

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP.
(Other instructions
verse side)

RECEIVED

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM H0515036

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

OLSON FEDERAL

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

HARDIN TANK STRAWN

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

Sec. 35, T-25-S, R-34-E

12. COUNTY OR PARISH

Lea

13. STATE
New Mexico

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Mobil Producing TX. & N.M. Inc.

3. ADDRESS OF OPERATOR

P. O. Box 633 Midland, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit J, Sec. 35, T-25-S, R-34-E
1980' from South line and 1980' from East line,
Lea County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, ST, GR, etc.)

KB 3328'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 393 3612
1. Notify BLM (505)887-6544, prior to MIRU. Post P&A Form 3160-5 will be filed and all cement used will be either API Class H or Class C.
 2. Kill well w/9 ppg gelled brine, set CIBP @ +/- 14,220' + 4 sxs (35') cmt cap w/bailer.
 3. Spot 25 sxs (100') cmt plug across line top, 12665' - 12555'. TAG PLUG
 4. Freepoint and cut 9-5/8" csg +/-200' above freepoint, pull and lay down.
 5. Spot 50 sxs (100') cmt plug across 9-5/8" csg stub, 50' in / 50' out. TAG PLUG
 6. Spot 50 sxs (100') cmt plug across 13-3/8" csg shoe, 50' in / 50' out. TAG PLUG
 7. Spot 65 sxs (100') cmt plug across top salt, 1120' - 1020'. TAG PLUG
 8. Spot 65 sxs (100') cmt plug across 20" csg shoe, 592' - 492'. TAG PLUG
 9. Spot 35 sxs (50') cmt plug at surface, cut csg 3' below surface. Weld on plate + 4' BLM spec P&A marker.
 10. Backfill all pits, clean location, reseed location to BLM specs. Well P&A'd.
 11. 9 PPG gel Brine mud will be placed between all plugs.

Procedure discussed w/Adam Salameh (BLM) on 09-24-90.

18. I hereby certify that the foregoing is true and correct

SIGNATURE

TITLE Environ/Regulatory Tech

DATE

09-28-90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

12-5-90

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side