

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☒ gas well ☐ other ☐

2 NAME OF OPERATOR
Phillips Petroleum Company

3. ADDRESS OF OPERATOR Room 401
4001 Penbrook St., Odessa, Texas 79762

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: (H) 1980' FNL & 660' FEL

AT TOP PRCD. INTERVAL: same

AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDONED

(other)

SUBSEQUENT REPORT OF:

3. LEASE

NM 16364

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Custer B Fed

9. WELL NO.

10. FIELD OR WILDCAT NAME

Custer Tansil

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 12, T-25-S, R-35-E

12. COUNTY OR PARISH Lea	13. STATE New Mexico
-----------------------------	-------------------------

14. API NO.

30-025-27890

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3211'DF, 3199'GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Recommended procedure to plug and abandon well is:

MI & RU DDU. Install BOP. Pull joint of tubing.

GIH with 2 3/8" tubing open ended. Tag bridge plug at 3495 and spot 16 sacks of Class "C" neat cement mixed to 14.8 ppg to cover perforations and top of Tansil. Displace cement in tubing with 13 bbls. 9.6 ppg mud laden fluid. Pull tubing up to 3200'. Estimated top of plug 3340'.

Load hole with 9.6 ppg mud laden fluid while reverse circulating. COOH
with tubing.

Determine casing free point.- Cut and pull 5-1/2" casing at free point:
5-1/2" TOC @ 3130' based on temperature survey. SEE REVERSE 9

Subsurface Safety Valve: Manu. and Type N/A Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Ray J. Mueller ^{for} W. J. Mueller TITLE _____ DATE June 18, 1984

(This space for Federal or State office use)

APPROVED BY R. J. Silke
CONDITIONS OF APPROVAL IF ANY:

*See Instructions on Reverse Side

RECEIVED
JUN 27 1984
HOBBS & COMPANY

GIH with 2-3/8" tubing to 60' below casing cut-off and spot 32 sacks of Class "C" cement with 2% CaCl₂ mixed to 14.8 ppg. Displace cement in tubing with 9.6 ppg mud laden fluid to 60' above casing cut-off. Estimated top of plug 60' above casing cut-off. *Tag*

Pull tubing up + 200' and reverse circulate tubing clean with mud laden fluid. WOC 2 hours. Tag top of plug, and record depth. Plug must be at least 50' above casing cut-off. Pull up to 1560'.

Spot 34 sacks of Class "C" cement with 2% CaCl₂ mixed to 14.8 ppg to cover the top of salt and 8 5/8" casing shoe. Displace cement in tubing with 9.6 ppg mud laden fluid. Pull tubing up to 1300'. Reverse casing clean. WOC 2 hrs. Tag top of plug and record depth. Top of plug must be at least 1450'. Estimated top of plug 1430'. *Tag*

Pull up to 60'. Spot 16 sacks of Class "C" cement with 2% CaCl₂ mixed to 14.8 ppg from 60' to surface. Displace cement in tubing with 9.6 ppg mud laden fluid. COOH with tubing.

Set casing a minimum of three feet below ground level. Weld steel plate over casing. Install well marker as required for permanent abandonment and clean location.

Procedure verbally approved in phone conversation with Bob Pittscoke (BLM Certified) 6/11/84.