

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-30152

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-9311

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Sirgo Operating, Inc.

3. Address of Operator

P.O. Box 3531, Midland, Texas 79702

8. Well No.

97

9. Pool name or Wildcat

Dollarhide Queen

4. Well Location

Unit Letter K : 2607 Feet From The South Line and 2457 Feet From The West Line

Section 32 Township 24S Range 38E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3183' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 3-1-90 MI&RU PU. Bridle off pumping unit. Take off horsehead. Unseat pump. Flange up WH & SION.
- 3-2-90 Welded adjusting bolts on unit. Hang well on. Attempt to pump acid down backside - can't. SI
- 3/4-90 No Activity.
- 3-5-90 MI&RU PU. POH w/rods & pump. Attempt to circ - can't. Pull 80,000# on tbg. Won't move. Pump 5 bbls acid down tbg. Flush out. Bleed pressure off. Pull 65,000# on tbg & SION.
- 3-6-90 Tbg still stuck. RU wireline & run freepoint. Found freepoint @ 1970'. POH. RIH w/ backoff tool & backoff tbg @ 1952'. POH w/6 jts of tbg & SION.
- 3-7-90 POH w/tbg. RIH & catch fish @ 1960'. POH. RIH w/4-3/4" bit & scraper, clean csg to 3962'. Circ clean. PU to 3789' & spot 5 bbls acid. SI for 30 min. Reverse out acid. POH w/tbg & scraper. SION.

CONTINUED ON BACK.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Bonnie Atwater

TITLE

Production Technician

DATE

4-10-90

TYPE OR PRINT NAME

Bonnie Atwater

TELEPHONE NO. 915/685-0878

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR

TITLE

DATE

APR 13 1990

CONDITIONS OF APPROVAL, IF ANY:

3-8-90 RIH w/2-7/8" tbg, SN & 2-1/2" x 2" x 16' RWAC pump & BHA. Set SN @ 3630',
tbg @ 3628'. Space out & hang on. Back on production.
3-9-90 Testing
3-10-90 TEST: 70 BO 324 BW.

RECEIVED

MAR 11 1990