

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 30230
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-9613
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	96
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>E</u> : <u>1480</u> Feet From The <u>NORTH</u> Line and <u>150</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>24S</u> Range <u>38E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐ ACIDIZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-25-00: MIRU. BLED DN WELL. UNSET PUMP & TOH W/RDS & PMP. UNFLANGE WH & REL TAC. NUBOP.  
9-26-00: TIH TO 6845' W/CSG SCRAPER. TIH W/RBP & PKR. SET RBP @ 6375'. PSA 6370'. TEST RBP W/500 PSI. REL PKR & RESET PKR @ 5957'. LOAD & TEST CSG W/500 PSI-OK.  
9-27-00: ACIDIZE W/3000 GALS NEFE ACID. CHEMICAL SQUEEZE PERFS W/2 DRUMS TH793 & FLUSH W/100 BBLS 2% KCL @ 2 BPM @ 1700 PSI.  
9-28-00: UNSET PKR & TIH W/2 JTS. FLOWING THROUGH CSG & DIED. WASH OVER SALT ON RBP & CIRC CLN. LATCH ONTO RBP & REL. TIH W/MUD JT, SN, 2 7/8" TBG, TAC.  
9-29-00: NDBOP. SET TAC. FLANGE UP WH. TIH W/PMP W/GAS ANCHOR, SNKR BARS, RDS. SPACE OUT & LOAD & TEST W/500 PSI-OK. RIG DOWN & CLEAN LOCATION. PLACE ON PUMP.  
10-03-00: ON 24 HR OPT. PUMPED 37 BO, 86 BW, & 26 MCF.  
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 1/4/01

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: TITLE

DATE