Submit 3 Copies to Appropriate District Offices

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICT I	OIL CONCEDUAT	TON DIVICION				
P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206		WELL API NO. 30-025-30287			
DISTRICT II						
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mer	nta Fe, New Mexico 87503		5. Indicate Type of Lease		
DICTRICT III				STATE F	EE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & G	as Lease No.		
			Fed Agee 8910084910			
SUNDRY NOT	ICES AND REPORTS ON W	/FLLS				
(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO DEE	PEN OR PLUG BACK TO A		TI ** A A ANT		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name West Dollarhide Queen			
(FORM C-101) FOR SUCH PROPOSALS.)			Unit	uo accom	,	
1. Type of Well:					,	
OIL WELL GAS WELL OTHER WIW				`		
2. Name of Operator			8. Well No.			
Saga Petroleum LLC			110			
3. Address of Operator			9. Pool name or Wildcat			
415 W Wall, Suite 1900, Midland, TX 79701			Dollarhide Queen			
4. Well Location 82	0	15-	7D			
Unit Letter C .750	Feet From The N	Line and <u>500</u>	Feet From	m The <u>W</u>	Line	
			memor LEA			
Section 32	Township 24S	Range 38E N	NMPM LEA		County	
	10. Elevation (Show w.	hether DF, RKB, RT, GR, etc.)				
11. Check A	ppropriate Box to Indicate	Nature of Notice, Rep	ort, or Other	Data		
***			SEQUENT F	REPORT OF:		
NOTICE OF INT	ENTION TO.	COD		CEI OICI OI .		
PERFORM REMEDIAL WORK	PLUG AND ABANDON 📖	REMEDIAL WORK		ALTERING CASING		
TEMPORARILY ABANDON L	CHANGE PLANS	COMMENCE DRILLING	OPNS.	PLUG AND ABANDON	· L	
DULL OF ALTER CASING		CASING TEST AND CEI	MENT JOB			
PULL OR ALTER CASING		1			\mathbf{x}	
OTHER:		OTHER: Sqz & Add p	репѕ		_ 🗠	
12. Describe Proposed or Completed Opework) SEE RULE 1103.	erations (Clearly state all pertin	ent details, and give pertinent o	lates, including esti	mated date of starting any	proposed	
7-27 Unset AD-1 pkr, RIH & tag by 7-29 RIH w/bailer & WS, tag up 3 8-1 Op BOP POOH w/WS, LD bas bbls dwn tbg, set retainer, test tbg break circ, clean BS, sting into retainer have full communication. So Class C w/1% CaCl, maintain preretainer. Sting out reverse out, rew/tbg, top psi 1500, holding press 8-2 RIH w/bit, tag up @ retainer, pkr (set w/14K tension) & inj strin EOT 3526.8', ND BOP. Circ 75 brepack WH. Test csg & pkr to 500 8-4 Press test tbg to 1150 psi, pre 8-9 Injected 153 BW	ar60', bail to 3784' hiler & bit, PU cmt retainer & g to 2000 psi, good. Rotate of etainer, start pumping to obta hut BS, establish rate @ 1 B less on csg w/pump trk, displate c approx 15 sx good slurry, of s before stinging out. POOH w/WS & bit, LD all the g 113 jts 3524' 2-3/8" J55 cn bls pkr fluid dwn csg. Unpact to psi, backside holding good ep to start injection	TIH to 3753', pump 15 but of retainer, ain press & PM. Pump 75 sx ace to 3/4 bbl above clean up tbg. POOH g, RIH w/5-1/2" AD-1 nt lined tbg k WH, set pkr,	†	DATE: 08/15/200	00	
SIGNATURESUMMUS	histand	TITLE Production Analys	t	DATE 08/15/200	U	
TYPE OR PRINT NAME Bonnie Husba	ind	TELEPHONE NO. (915)684-4293				
(This space for State Use)			TIDIS WILLIAM	IS		
ARREQUED BY		ORIGINAL SIGNED BY C	CHVISOR	DATRETO 4 () (onaa	

