Form 3160-5 (November 1983) (Formeriy 9-331)	DEPART BUREAU	JN SD STA ME. , OF TH JOF LAND MAN	IE INTERIC	Verae 3100)	\TE* 1 re-	Form approved. Budget Bureaus Expires August 3 5 LEASE DESIGNATIONAN (8910084910) L (6 F NDAN ALLOTTEE OR	1, 1985 DSETIAL NO. COG7968
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)						7. UNIT AGREEMENT NAME	
2 NAME OF OPERATOR OXY USA INC.						& FAFM OR LEASE NAME W. DOLLARHIDE QN SD UT 9 WELLING	
ADDRESS OF OPERATOR P.O. BOX 50250 MIDLAND, TX 79710 A LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*						153 10 FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface 570 FSL 1790 FEL Sec 30 T24S R38E						DOLLARHIDE QUEEN 11. SEC, T. R. M., OR BLK AND SURVEY OR AREA Sec. 30 T24S R38E	
14. PETINIT NO. 30-025- 3035		15 ELEVATIONS (Show	3132'			12 COUNTY OR PARISH	12 STATE NM
Check Appropriate Box To Indicate Nature of Notices, Report, or NOTICE OF INTENTION TO: SUBSE							
TESTWATER SHUT-OF FRACTURE THEAT SHOOT OR ACIDIZE REPAR WELL (Other)	X ABA	LORALTER CASING JTPLE COMPLETE NDON" NGE PLANS		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report re Overland the second		REPARING ALTERING C ABANDONM f multiple completion on V letion Report and Log for	XASING HAND
proposed work. nent to this work.)	hf well is d ►	PBTD - 3840	give subsurface k	nent details, and five pertine cations and measured and t 36051-37571		ical depths for all marker	s and zones perti-
		SEE OTHER	SIDE			Mar 23 8 52 AN 53	S V
18. Thereby certify that the f	stopping is type and		TITLE PRO	D. ACCT.		DATE	24/93
(This space for Federal of APPROVED BY CONDITIONS OF	, and by Ad					DATE	23/93

*See Instructions on Reverse Side

~

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fradulent statements or representations as to any matter within its jurisdiction.

WDQSU 153 Procedure to clean out, add perfs and acidize Page 2

- 1. MIRU PU. ND WH. NU BOP. Rel pkr, TIH & tag 3840' PBTD. TOOH. If fill is present, DO w/ a 4-3/4" RB & 4 - 3-1/8" DCs on 2-7/8" tbg to PBTD. CHC. Recover a scale sample for analysis. TOOH. TIH w/ 4-3/4" RB, 4 - 3-1/8" DCs & 5-1/2" CS on 2-7/8" tbg to PBTD. CHC. TOOH.
- RU wireline. Install lubricator. Using a 4" csg gun loaded 2 SPF w/ premium charges, perf 3589 - 97', 18 shots.
- 3. TIH w/ RTTS pkr on 2-7/8" workstring. Set pkr @ 3546' and test csg to 500#. Rel pkr & TIH to 3757'. Spot 210 gal 15% NEFE HCl* 3757 3540'. TOOH to 3540' & set RTTS. Pres csg to 500#. Az Queen (3589 3757') w/ 2290 gal 15% HCl in 3 stages pumping 400 gal gelled 10# brine carrying 400# rock salt between each stage (the total treatment comprises 2500 gal acid, 800 gal gelled brine, 800# rock salt). Flush to perfs w/ produced water. Swab or flow back load. Rel pkr & TOOH.
- 4. TIH w/ Baker AD-1 pkr on 2-3/8" PL tbg to 3540'. Circ annulus w/ pkr fluid & set pkr. Put well on injection, monitoring injection rate and pressure at the wellhead.
- * 15% HCL to contain per 1000 gal (use BJ equivalents):
 1 gpt CI-23 (corrosion inhibitor)
 1 gpt NE-15 (non-emulsifier)
 10 gpt FE-300L (iron sequestrant)
 10 ppt FE-200 (iron sequestrant)
 2 gpt Clatrol 6 (clay control)
- *Gelled 10# brine to contain per 1000 gal: 20 ppt GW-27 (gelling agent) 1 gpt NE-15 (non-emulsifier) OXY will supply the brine water.