- Submit 3 Copies to Appropriate District Office					Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240				WELL API NO. 30-025-30458	R
DISTRICT II Santa Fe, New Mexico 87504-2088				5. Indicate Type of	Tassa
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & O				6. State Oil & Gas	STATE FEE X
SUNDRY NOTICES AND REPORTS ON WELLS					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					Juit Agreement Name
1. Type of Weil: OL CAS WEL WELL	X other		· · · · · · · · · · · · · · · · · · ·	- PITCHFORK "10	J.
2. Name of Operator MERIDIAN OIL INC.				8. Well No.	
3. Address of Operator 9. Pool name or					ildcat
P.O. Box 51810, Midla 4. Well Location	nd, TX 79710–1810		<u></u> .	PITCHFORK RA	NCH (MORROW)
Unit Letter <u>C</u> :	660 Feet From The NORTH		Line and	1980 Feet From	The WEST Line
Section 10	Township 25-S	Ra	nge 34-E	NMPM LEA	County
	10. Elevation (Show) 3342° GR	whether i	DF, RKB, RT, GR, etc.)		<i>\////////////////////////////////////</i>
11. Che	ck Appropriate Box to Ind	licate N	Nature of Notice, R	leport, or Other	Data
	INTENTION TO:		•	SEQUENT RI	
	PLUG AND ABANDON	X	REMEDIAL WORK		
	CHANGE PLANS		COMMENCE DRILLIN	g opns.	
PULL OR ALTER CASING]		CASING TEST AND C	EMENT JOB	
OTHER:			OTHER:		O
12. Describe Proposed or Completed C	perations (Clearly state all pertinent of	details, an	d give pertinent dates, incl	uding estimated date of	starting any proposed
work) SEE RULE 1103. 1. M: W	[RU pulling unit, plugging equ ell. ND WH, NU BOP.	ipment.	Load tubing w/10# t	rine to kill	
2. Pi Pi	ull on 3 1/2" 10.3#/ft N-80 1 DOH laying down 3 1/2" tubing a	ubing t nd seal	o pull seal out of P assembly.	BR @ 12,878'.	
	J & RIH with spear, drill c orkstring. Fish RLA and POOH ars, collars & RLA.	ollars a w/tubing	and jars, on 2 7/8" , jars, collars and R	6.5#/ft N-80 LA. Lay down	
1	IRU wireline unit. RIH with 4,050'. POH. RDMO wireline un	it.			ION MUST BE NOTIFIED 2
Ĩ	IH with 2-7/8" N-80 workstri /10#/gal mud laden fluid, and 3,760' and spot 20 sxs class " 3,350'.	ng to 1 cap CIBP H" cemen	4,050' and tag CIBP P w/10 sxs class "H" ce t from 13,760' to 13,	Literation Relief Control of Cont	CATIONS FOR THE C-103
6. Spot 20 sxs class "H" cement containing 2% CaCl (across 7" casing shoe @ 13,299') from 13,350' to 13,250'. PUH to 13,000', reverse circulate tubing clean, HOC and tag plug @ ±13,250'. PUH to 12,948'.					CONTINUED ON Page -2-
I hereby certify that the information above	- VI				
SIGNATURS Maria	a - pag	m	PRODUCTION SER	RVICES	DATE 5-6-92
TTHE OR PRINT NAME MARIA L. P	EREZ				TELEPHONE NO. 915-688-6
	n na ny isyena kanima. Na isyenakana				MAY 11'92
			12		DATE

÷ .

Page -2-C-103 Sundry Notice of Intent to Plug and Abandon

Meridian Oil Inc. Pitchfork "10" No. 1

Continued

7. Spot 35 sxs class "H" cement (across 4 1/2" liner top @ 12.878') from 12.948' to 12.848'. PUH to 10.865', reverse circulate tubing clean, WOC and tag plug @ ±12.848'. PUH to 12.740'.

8. Spot 50 sxs class "H" cement from 12,740' to 12,640'. PUH to 9600'.

- 9. Spot 40 sxs class "H" cement from 9600' to 9500'. PUH to 6600'.
- 10. Spot 35 sxs class "H" cement from 6600' to 6500'. PUH to 5500', reverse circulate tubing clean. POOH with 2 7/8" N-80 workstring.
- ND BOP and wellhead. Weld on 7" pull nipple. Pull on casing to remove slips and determine casing freepoint. Top of cement by temperature survey is @ ±5000'.
- 12. MIRU wireline unit. Jet cut the 7" 26#/ft P-110 casing @ freepoint. RDMO wireline company. POOH and lay down casing.
- 13. RIH with 2 7/8" N-80 workstring open-ended to 5350'. Fill hole w/10#/gal mud laden fluid. Spot 140 sxs class "H" cement containing 2% CaCl from 5350' to 4950'. PUH to 4000', reverse circulate tubing clean, WOC, tag plug @ ±4950'. If necessary, spot additional cement to provide 50' plug above top of cut 7" casing, and tag plug. PUH to 4600'.
- 14. Spot 60 sxs class "H" cement (across base of salt @ 4550') from 4600' to 4500'. PUH to 3250'.
- 15. Spot 55 sxs class "H" cement (across top of salt @ 3200'), from 3250' to 3150'. PUH to 662'.
- 16. Spot 45 sxs class "H" cement (across surface casing shoe @ 612'), from 662' to 562'. PUH to ±400', reverse circulate tubing clean. POOH laying down 2 7/8" N-80 tubing.
- 17. Cut off casing 3' below ground level. Spot 10 sxs class "H" cement from 27' to top of casing. Weld steel plate with dry hole marker on casing stub. RDHO pulling unit and plugging equipment.
- Meridian personnel to cut anchors, clean location and perform location rehabilitation as per operating agreement.



· ...

TD: 15026'



PBTO: 14670'