

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31759
5. Indicate Type of Lease STATE ☐ FEB ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name South Justis Unit "E"
8. Well No. 202
9. Pool name or Wildcat Justis Bly Tubb Drkd

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER Water Injection	
2. Name of Operator ARCO Permian	
3. Address of Operator P.O. Box 1710, Hobbs, New Mexico 88240	
4. Well Location Unit Letter E: 1450 Feet From The N Line and 330 Feet From The W Line Section 24 Township 25S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3084' GR 3098' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Add Perfs & Acidize ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6050' PBD: 5240' CIBP INJECTION INTERVAL: 5015-5226

11/21/96: POH w/2-3/8" IPC tbg & 4-1/2" Guiberson G VI Pkr. WIH w/bit, sub, scraper, and 2-3/8" workstring to 5934', POH.
11/22/96: WIH & set Alpha CIBP @ 5240'. RIH w/2 3-1/8" perf guns. Perf select fire 120 degrees offset, 2 SPF 5015-5038, 24 holes. WIH w/PPI tool, 2-3/8" workstring to 5240'. Pmp 18 bbls 2% KCL, set PPI tool @ 5220' press to 4000#, held OK. Acidize perfs 5197-5120' w/550 gals 15% NEFE HCL. Pulled above perfs pmp 1100 gals 15% and 24 bbls 2% KCL. Press up to 4000#. Bled off & released PPI pkr.
11/23/96: Set PPI tool @ 5109' and acidize 22 perfs w/50 gals/ft 15% NEFE from 5109-5015'. Released tool & POH. WIH w/4-1/2" Guiberson G VI pkr & 2-3/8" IPC tbg. Set pkr @ 4886' Loaded csg & press est 510#, held OK. Chart attached
bbls 2% KCL. Press up to 4000#. Bled off & released PPI pkr.
~~11/23/96: Set PPI tool @ 5109' and acidize 22 perfs w/50 gals/ft 15% NEFE from 5109-5015'. Rel field~~

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Asst. DATE 3-25-97
TYPE OR PRINT NAME KELLIE D. MURRISH TELEPHONE NO. 394-1649

(This space for State Use)

ORIGINAL SENT TO PERRY SEXTON
RECEIVED 3-27-97

MAR 28 1997

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: