

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
CITY	
SANTA FE	
FILE	
U.S.C.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/> Injection Well	7. Unit Agreement Name Cooper Jal Unit
Name of Operator Texaco Producing Inc.	8. Farm or Lease Name
Address of Operator P. O. Box 728, Hobbs, NM 88240	9. Well No. 144
Location of Well UNIT LETTER <u>H</u> <u>2310</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>24S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool or Wildcat Langlie Mattix Seven Rivers Queen
11. Elevation (Show whether DF, RT, GR, etc.) 3295' DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Repair Casing

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU. Pull 2 3/8" cement lined tbg. install BOP.
- 2) TIH with workstring, packer, and CIBP and locate casing leak. Set CIBP @ 3359'±.
- 3) Establish an injection rate out of the 5 1/2" casing using produced water if possible. POH.
- 4) TIH with 5 1/2" cement retainer and set the retainer above the casing leak.
- 5) Squeeze the casing leak with 300 sx of class H cement.
- 6) Pull out of the retainer and reverse out excess cement.
- 7) POH and WOC.
- 8) TIH with workstring and 4 3/4" bit and drill out retainer and cement to the CIBP.
- 9) Test casing and resqueeze if necessary.
- 10) Drill out the CIBP and c/o fill. POH.
- 11) Test workstring and TIH set packer at 3331'.
- 12) Pressure upon annulus upto 700 PSI.
- 13) Acidize open hole (3389'-3490') with 2,000 gals 20% NEFE Acid with rock salt as a diverting agent.
- 14) TOH with workstring and packer.
- 15) TIH with injection tubing and place well on injection.
- 16) Run injection profile after injection rate has been established.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. B. Loh TITLE Dist. Oper. Mgr. DATE 01/20/86

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JAN 23 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 22 1986

O.C.D.
HOBBS OFFICE