

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-09710
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1167

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Langlie "A" State
2. Name of Operator Meridian Oil Inc.	8. Well No. 1
3. Address of Operator P.O. Box 51810, Midland, TX 79710	9. Pool name or Wildcat Langlie Mattix SR-QN-GB
4. Well Location Unit Letter I : 1980 Feet From The S Line and 660 Feet From The E Line Section 36 Township 24 S Range 36E NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3255' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify OCD prior to starting work. MIRU PU. ND wellhead, NU BOP. Deliver workstring to location. PU workstring and RIH with casing scraper to 3350', POOH. Set CIBP on workstring at + 3320'. Spot 5 sxs of cement on CIBP. Pull up above plug and circulate hole with 9 ppg gelled brine.
2. Pull up to 2270' and set cement plug across base of salt at 2600' to 2720'. Use 15 sxs of cement. Pull up to 1290' and set a cement plug across the top of the salt at 1170' to 1290'. Use 15 sxs of cement. POOH laying down tubing.
3. Perforate 4 squeeze hole at 410'. Open bradenhead valve and establish circulation through perforations. Pump 100 sxs of cement down casing allowing circulation out bradenhead. Do not displace. RDMO PU. Cut off casing 3' below ground level and install P & A monument. Clear, rip, and reseed location.

NOTE: All cement to be class C with 2% CaCl₂ added

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Williams TITLE Production Assistant DATE 12-7-92
TYPE OR PRINT NAME Donna Williams TELEPHONE NO. _____

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

DEC 10 '92

RECEIVED

DEC 09 1992

OCD HOBBS OFFICE