

12. Obtain SI pressures. SI 30 mins. RU Swab. Swab FL down to pit. RD Swab.
13. Rlse PKR. RIH to RBP. Rlse RBP. POH w/ RBP and PKR. LD WS.
14. RIH w/ 2 3/8" 4.7# J-55 EUE 8rd production TBG as follows: (Will need to pick up 2 jts 2 3/8" TBG)

QTY	ITEM	LENGTH	DEPTH
TUBING			
84	Jts 2 3/8" 4.7# J-55 eue 8rd TBG	2582'	2593'
1	4 1/2" TAC	3'	2596'
5	2 7/8" J-55 6.5# EUE 8 RD TBG	155'	2751'
1	JT 2 7/8" J-55 6.5# IPC EUE 8RD TBG	31'	2782'
1	2 3/8" SN	1.1'	2783'
1	2 3/8" x 4' Perf Sub	4.0'	2787'
1	Jt 2 3/8" J-55 BPMA	31'	2818'

15. ND BOP. NU WH.
16. RU swab. Swab well until clean fluids or no fluid recovery to pit. RD Swab.
17. Run rod string as follows: (Will need to pick up +/- 4 - 3/4" rods)

RODS

99	3/4" D Pony Rods	19'
110	3/4" D Rods w/SHSM couplings	2750'
1	2" x 1 1/4" x 14' Pump	14'

18. Load tbg and pressure test pump. Space out & hang well on.
19. Monitor production and fluid levels.

