

## **SOUTH MATTIX UNIT FEDERAL NO. 21 – RECOMMENDED PROCEDURE**

- 1) MI x RU. POH with tubing and packer.
- 2) RIH with tubing, packer, and tail pipe and spot cement across Yeso perforations from 5105' – 5642'. Cement squeeze Yeso perfs.
- 3) RIH with bit and drill out cement to below Yeso perfs and circulate well clean. Pressure test squeezed perfs to 500 psig.
- 4) Drill out cement retainer at 5750' and clean out wellbore to 6600'.
- 5) Selectively perforate the Drinkard in the interval from 6050' – 6300'.
- 6) RIH with tubing and packer and swab test perforations. Acidize perforations if necessary to establish production.
- 7) Frac well down tubing.
- 8) Clean up well and place on production.