

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-24167
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name J. R. Holt NCT-A
2. Name of Operator Chevron U.S.A. Inc.	8. Well No. 4
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Pool name or Wildcat Fowler-Tubb
4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>2080</u> Feet From The <u>East</u> Line Section <u>16</u> Township <u>24S</u> Range <u>37E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 7676 PB: 6284 Work performed: 5/8/89 thru 5/16/89

POH w/production equipment. Set RBP at 5962'. Pkr at 5930'. Tst tools to 1000psi,ok. Set pkr at 5204'. Spot 3sx sand on top of RBP. Set CIGR at 5200'. Batch mix 100sx C1 H cmt and 50sx C1 H. Sting out. Reverse out 3 1/2 bbls to pit. WOC 24 hrs. Drill cmt and CIGR to 5776'. Circulate clean. TIH, tag sand at 5955'. Swab. Wash sand to 5962'. Circ sand off RBP. TIH w/2 3/8" tbg to 6233'. SN 6197'. TAC at 5258'. Turn over to production dept.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Tech. Asst. DATE 5-17-89
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

MAY 19 1989

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: