NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	✓	
FILE	✓	✓
U.S.G.S.		
LAND OFFICE		
OPERATOR	✓	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED BY
FEB 25 1987
O. C. D.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State [X] Fee [ ]

5. State Oil & Gas Lease No.
L-6292

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL [X] GAS WELL [ ] OTHER-

7. Unit Agreement Name

2. Name of Operator
Wood & Locker, Inc. 30-015-23795

8. Farm or Lease Name
Moore State

3. Address of Operator
505 N. Big spring Suite 600 Midland, Texas 79701-8602

9. Well No.
1

4. Location of Well
UNIT LETTER G, 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 23 TOWNSHIP 25-S RANGE 27-E NMPM.

10. Field and Pool, or Wildcat
Wildcat - Bone Spring

15. Elevation (Show whether DF, RT, GR, etc.)
3052" RKB, 3040' GR

12. County
Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK [ ] PLUG AND ABANDON [ ]
TEMPORARILY ABANDON [ ]
PULL OR ALTER CASING [ ] CHANGE PLANS [ ]
OTHER [ ]

SUBSEQUENT REPORT OF:

REMEDIAL WORK [ ] ALTERING CASING [ ]
COMMENCE DRILLING OPNS. [ ] PLUG AND ABANDONMENT [X]
CASING TEST AND CEMENT JOB [ ]
OTHER [ ]

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up unit and pull out of hole with rods and tubing.
2. Rig up wireline truck and set CIBP @ 5807'. Cap with 5 sks. of cement.
3. Run in hole with tubing and circulate hole with mud. Pull out of hole with tubing.
4. Cut & pull casing - 4½" from 3888' and run in hole with tubing to 4035'.
5. Spot 35 sks. of cement . Wait on cement. Tagged plug @ 3780'.
6. Pull tubing to 2299' and spotted 35 sks. of cement. Wait on cement. Did not tag.
7. Spotted 35 sks. of cement @ 2299'. Wait on cement. Tagged @ 2289'.
8. Spotted 35 sks. of cement @ 2289'. Wait on cement. Tagged @ 2168'. Lay down tubing.
9. Spotted 35 sks. of cement @ 460'.
0. Spotted 10 sks. of cement @ 54'.
1. Clean cellar, cut off wellhead and install plate & P & A marker. Cut off anchor.
2. Rig down unit and clean location.

Post ID-2
2-27-87
P&A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale May Dale May TITLE Baber Well Servicing Co. P & A Supervisor DATE 2-19-87

APPROVED BY Darell Moore TITLE Geologist DATE 12/14/89

CONDITIONS OF APPROVAL, IF ANY: