Submit 1 Copy To Appropriate District Office
District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

HOBBS OCD

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
OCT 1 0 2013   Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

WELL API NO. 30-025-29360	
5. Indicate Type of Lease STATE ☒ FEE ☐	
6. State Oil & Gas Lease No. E-6002	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒   Gas Well ☐   Other

2. Name of Operator
NADEL AND GUSSMAN PERMIAN, LLC

3. Address of Operator
601 N. MARIENFELD, SUITE 508, MIDLAND TX, 79701

7. Lease Name or Unit Agreement Name

B. LEE STATE

8. Well Number 8

9. OGRID Number
155615

10. Pool name or Wildcat
SCHARB; WOLFCAMP

4. Well Location

Unit Letter ___A___ : ___467___ feet from the ___NORTH___ line and ___660___ feet from the ___EAST___ line

Section 5   Township 19S   Range 35E   NMPM   LEA   County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3919 GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENT
PERFORM REMEDIAL WORK ☐
TEMPORARILY AB... ☐
PULL OP... ☐

Approved for Plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Specifically for Subsequent Report of Well Plugging) which may be found at OCD web page under forms/ www.emnrd.state.nm.us/ocd

SUBSEQUENT REPORT OF:
REMEDIAL WORK	☐	ALTERING CASING	☐
COMMENCE DRILLING OPNS.	☐	P AND A	☒
CASING/CEMENT JOB	☐		

OTHER: ☐

...ed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date ...ed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of ...mpletion or recompletion.

9/20/13 - 10/3/13

RIH W/ TBG TAG CIBP AT 10,318'. CIRCULATED 25 SX GEL W/ 10.0 PPG BRINE. TEST CASING TO 500 PSI AND HELD. SPOT 25 SX PLUG AT 7750-7530. ATTEMPT TO CUT CASING AT 6,000' AND COULD NOT. CALLED MAXEY BROWN W/ OCD OK'D CUTTING AT 4200. SPOT 25 SX PLUG AT 6050-5797'. TAG PLUG AT 5797'.
PERF CASING AT 5200, PRESSURE TEST TO 1500 PSI, CALLED MAXEY BROWN OK'D SETTING PLUG 50FT BELOW PERFS. SPOT PLUG AT 5252-4999, WOC AND TAG AT 4917'. NOTIFY OCD. CUT 5-1/2" CASING AT 4200 AND PULL CASING. SPOT 25 SX PLUG AT 4250-4022. WOC, TAG PLUG AT 4022, NOTIFY OCD. SPOT 30 SX PLUG AT 1900-1789. SPOT 30 SX PLUG AT 526-415. WOC TAG PLUG AR 390'. PERF AT 250', TEST PERFS AND HELD. FILL CASING TO SURFACE W/ 165 SX, CUT OFF WELLHEAD, INSTALL DRY HOLE MARKER, REMOVE ANCHORS.

Spud Date: [blank]   Rig Release Date: [blank]

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____   TITLE ___OPERATIONS ENGINEER___   DATE ___10/7/13___

Type or print name ___JASON GOSS___   E-mail address: ___JGOSS@NAGUSS.COM___   PHONE: 432-682-4429

For State Use Only
APPROVED BY: _____   TITLE _Dist. Mgr_   DATE _10-15-2013_
Conditions of Approval (if any):

OCT 1 5 2013