


Former Tank Battery



Legend:

- Excavation Extent
- Former AST
- Pipeline
- Sample Location

Figure 2
Site & Sample Location Map
BOPCO, L.P.
Poker Lake Unit #59 Battery
Eddy County, New Mexico

Basin Environmental Services

Prep By: JWL	Checked By: BJA
October 8, 2014	Scale 1"=10'

TABLE 1
CONCENTRATIONS OF BENZENE, BTEX, TPH & CHLORIDE IN SOIL

BOPCO, LP
 PLU #59 TANK BATTERY
 EDDY COUNTY, NEW MEXICO
 NMOCD REFERENCE #: 2RP-_____

SAMPLE LOCATION	SAMPLE DEPTH (BGS)	SAMPLE DATE	SOIL STATUS	METHOD: EPA SW 846-8021B, 5030					METHOD: 8015M			TOTAL	4500 Cl-B CHLORIDE (mg/Kg)
				BENZENE (mg/Kg)	TOLUENE (mg/Kg)	ETHYL-BENZENE (mg/Kg)	TOTAL XYLENES (mg/Kg)	TOTAL BTEX (mg/Kg)	GRO C ₆ -C ₁₂ (mg/Kg)	DRO C ₁₂ -C ₂₈ (mg/Kg)	ORO C ₂₈ -C ₃₅ (mg/Kg)	TPH C ₆ -C ₃₅ (mg/Kg)	
TT @ 2'	2'	4/1/2014	Excavated	<0.050	<0.050	<0.050	<0.150	<0.300	<10.0	155	<10.0	155	1,250
TT @ 4'	4'	4/1/2014	Excavated	-	-	-	-	-	-	-	-	-	1,360
TT @ 6'	6'	4/1/2014	In-Situ	-	-	-	-	-	-	-	-	-	2,000
TT @ 8'	8'	4/1/2014	In-Situ	-	-	-	-	-	-	-	-	-	2,320
TT @ 10'	10'	4/1/2014	In-Situ	-	-	-	-	-	-	-	-	-	1,840
TT @ 12'	12'	4/1/2014	In-Situ	-	-	-	-	-	-	-	-	-	2,160
TT-1a @ 14'	14'	10/6/2014	In-Situ	Pending	Pending	Pending	Pending	Pending	Pending	Pending	Pending	Pending	420*
TT-1a @ 16'	16'	10/6/2014	In-Situ	-	-	-	-	-	-	-	-	-	620*
TT-1a @ 18'	18'	10/6/2014	In-Situ	-	-	-	-	-	-	-	-	-	680*
TT-1a @ 20'	20'	10/6/2014	In-Situ	-	-	-	-	-	-	-	-	-	680*
TT-1a @ 22'	22'	10/6/2014	In-Situ	-	-	-	-	-	-	-	-	-	420*
TT-1a @ 24'	24'	10/6/2014	In-Situ	-	-	-	-	-	-	-	-	-	420*
North SP @ 5'	5'	10/6/2014	Excavated	-	-	-	-	-	-	-	-	-	2,040*
North SP @ 10'	10'	10/6/2014	In-Situ	-	-	-	-	-	Pending	Pending	Pending	Pending	620*
East SP @ 10'	10'	10/6/2014	In-Situ	-	-	-	-	-	-	-	-	-	1,356*
South SP @ 10'	10'	10/6/2014	In-Situ	-	-	-	-	-	Pending	Pending	Pending	Pending	<120*
West SP @ 5'	5'	10/6/2014	In-Situ	-	-	-	-	-	-	-	-	-	<120*
West SP @ 10'	10'	10/6/2014	In-Situ	-	-	-	-	-	-	-	-	-	<120*
NSW #1 @ 4'	4'	10/7/2014	In-Situ	-	-	-	-	-	-	-	-	-	180*
ESW #1 @ 4'	4'	10/7/2014	In-Situ	-	-	-	-	-	-	-	-	-	<120*
ESW #2 @ 4'	4'	10/7/2014	In-Situ	-	-	-	-	-	-	-	-	-	<120*
ESW @ 10' (Conf)	10'	10/7/2014	In-Situ	-	-	-	-	-	Pending	Pending	Pending	Pending	220*
SSW #1 @ 4'	4'	10/7/2014	In-Situ	-	-	-	-	-	-	-	-	-	<120*
SSW #2 @ 4'	4'	10/7/2014	In-Situ	-	-	-	-	-	-	-	-	-	<120*
WSW #1 @ 4'	4'	10/7/2014	In-Situ	-	-	-	-	-	-	-	-	-	320*
WSW #2 @ 4'	4'	10/7/2014	In-Situ	-	-	-	-	-	-	-	-	-	<120*
WSW @ 10' (Conf)	10'	10/7/2014	In-Situ	-	-	-	-	-	Pending	Pending	Pending	Pending	556*
NMOCD Criteria				10				50				5,000	1,000

- = Not analyzed.

* =Chloride Field Test Result



Photograph of excavation activities at the PLU #59 Tank Battery.



Photograph of excavation activities at the PLU #59 Tank Battery.



Photograph of excavation activities at the PLU #59 Tank Battery.



Photograph of the collection of soil sample WSW @ 10'.