

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Received 3/2/15  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Neff Federal #1 and #3 SWD Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	API No.30-015-28281(nearest well)

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	25	22S	31E					Eddy County, NM

Latitude N 32.36779° Longitude W 103.73335°

### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	650 bbls	Volume Recovered	550 bbls
Source of Release	Bad electrical storms caused line fuse on power pole to trip and trigger the tanks to run over from power loss to battery	Date and Hour of Occurrence	05/27/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, NMOCD and Jennifer VanCuren, BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	05/27/2014 @ 2:35 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Bad electrical storms caused the line fuse on the power pole to trip and trigger the tanks to run over spilling 650 bbls of produced water onto the ground. A vacuum truck recovered 550 bbls of produced water and the power to the pole was restored.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 200' x 180' east of the battery and west of the well head, but still on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 11/04/2015 and approved by Sol Hughes of the BLM via email on 10/30/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Christopher Jones	Approved by Environmental Specialist:		
Title: HES Specialist	Approval Date: 3/4/2015	Expiration Date: N/A	
E-mail Address: <a href="mailto:Christopher.Jones@oxy.com">Christopher.Jones@oxy.com</a>	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 02/03/2015	Phone: (575) 628-4121	FINAL	

\* Attach Additional Sheets If Necessary

2RP-2359