

Remuda Basin Fed #2 SWD

REMEDIATION WORK PLAN

API No. 30-015-28901

Release Date: June 13th. 2015

Unit Letter B, Section 19, Township 23 South, Range 30 East

July 14, 2015

Prepared by:

Environmental Department Diversified Field Service, Inc. 206 W. Snyder Hobbs, NM 88240 Phone: (575)964-8394

Fax: (575)393-8396

XTO 07/14/2015

Mike Bratcher Environmental Specialist NM Oil Conservation District-Division 2 811 S. First St. Artesia, NM 88210

RE: XTO, Remuda Basin 19 Fed #2 SWD – Remediation Work Plan UL/B, Section 19, T19S, R34E API No. 30-015-28901

Mr. Bratcher,

XTO has retained Diversified Field Service, Inc. (DFSI) to address environmental issues for the site detailed herein.

The site is located east of Loving, NM, in Eddy County. The leak site resulted from a hole, which developed in the injection line approximately 900' southwest of the well location. The impacted area is approximately 900' southwest of the well location in the pasture and ran west for approximately 300 yards. Approximately 160 bbls of produced water was released, and 0 bbls recovered. A C-141 was submitted to the NMOCD on July 14, 2015. The C-141 is attached.

Site Assessment and Delineation

On June 25, 2015 DFSI personnel delineated 8 sample points of the leak area. On June 26, 2015 DFSI personnel used an auger drill to fully delineate the spill site in three borehole areas. Each sample was tested for chloride levels as well as BTEX. The BTEX samples were performed using a Mini Rae Photoionization Detector (PID). The results and sample point locations are attached.

DFSI has conducted a groundwater study of the area and has determined that according to the New Mexico Office of the State Engineer the average depth to groundwater for this area is 83 + foot below ground surface. Therefore, no eminent danger of groundwater impact or threat to life is anticipated.

Conclusion

XTO 07/14/2015

After careful review DFSI on behalf of XTO would like to propose the following:

Remove 3' to 4' bgs of the contaminated soil in the pasture. Lab samples can be obtained when the site is excavated. Haul all contaminated material to an approved NM state disposal. We will backfill with clean native soil around the injection line and use surrounding terrain the backfill the rest. We will re-seed using a BLM approved seed mix.

Following the approval of the above plan, DFSI will submit all proper closure documentation to the NMOCD and BLM in accordance to the State and Federal Guidelines set forth.

Please feel free to contact me with any questions concerning this remediation plan request.

Sincerely,

Michael Burton

Environmental Operations Director Diversified Field Service, Inc. 206 West Snyder

Hobbs, NM 88240 Office: (575)964-8394 Mobile: (575)390-5454 Fax: (575)964-8396

Michael Buston 1


Email: Mburton@diversifiedfsi.com

cc Jim Amos

Attachments: Initial Form C-141

Site/Sample Map Sample Data Photo Page

Site Diagram





Remuda Basin Fed #2 SWD

PHOTO PAGE

6/17/2015









Company Name:XTOSP Date:6/25/2015

Location Name: REMUDA BASIN 19 FED #2 Rel Date:

CHL	PID	SP2	CHL	PID	SP3	CHL	PID	SP4	CHL	PID		SP5	CHL	PID
30,965	42.8	SURF	25,866	32.8	SURF	21,618	46.4	SURF	25,242	3	8.6	SURF	16,369	72.3
15,995	12.4	1'	10,996	14.4	1'	17,619	38.4	1'	16,244	2	2.4	1'	9447	68.4
		2'	10,121	14.1	2'	8622	12.2	2'	AUGER REF	USAL		2'	AUGER REF	USAL
		3'	AUGER REI	FUSAL	3'	AUGER RE	FUSAL							
	30,965 15,995	30,965 42.8	30,965 42.8 SURF 15,995 12.4 1' AUGER REFUSAL 2'	30,965 42.8 15,995 12.4 AUGER REFUSAL SURF 25,866 1' 10,996 2' 10,121	30,965 42.8 SURF 25,866 32.8 15,995 12.4 AUGER REFUSAL 2' 10,121 14.1	30,965 42.8 SURF 25,866 32.8 SURF 15,995 12.4 1' 10,996 14.4 1' 2' 2' 10,121 14.1 2'	30,965 42.8 SURF 25,866 32.8 SURF 21,618 15,995 12.4 1' 10,996 14.4 1' 17,619 AUGER REFUSAL 2' 10,121 14.1 2' 8622	30,965 42.8 SURF 25,866 32.8 SURF 21,618 46.4 15,995 12.4 1' 10,996 14.4 1' 17,619 38.4 2' 10,121 14.1 2' 8622 12.2	30,965 42.8 SURF 25,866 32.8 SURF 21,618 46.4 SURF 15,995 12.4 1' 10,996 14.4 1' 17,619 38.4 1' 2' 8622 12.2 2'	30,965 42.8 SURF 25,866 32.8 SURF 21,618 46.4 SURF 25,242 15,995 12.4 1' 10,996 14.4 2' 10,121 14.1 2' 8622 12.2 2' AUGER REF	30,965 42.8 SURF 25,866 32.8 SURF 21,618 46.4 SURF 25,242 3 3 3 3 4 4 5 5 5 5 5 5 5 5	30,965 42.8 SURF 25,866 32.8 SURF 21,618 46.4 SURF 25,242 38.6 15,995 12.4 AUGER REFUSAL 2' 10,121 14.1 2' 8622 12.2 2' AUGER REFUSAL	30,965 42.8 SURF 25,866 32.8 SURF 21,618 46.4 SURF 25,242 38.6 SURF 15,995 12.4 1' 10,996 14.4 2' 10,121 14.1 2' 8622 12.2 2' AUGER REFUSAL 2' 2' SURF 25,242 38.6 SURF 1' 16,244 22.4 1' 2' 2' SURF 25,242 38.6 SURF 25,242 SURF	30,965 42.8 SURF 25,866 32.8 SURF 21,618 46.4 SURF 25,242 38.6 SURF 10,996 14.4 2' 10,121 14.1 2' 8622 12.2 2' AUGER REFUSAL SURF 25,242 38.6 SURF 16,369 1' 9447 2' AUGER REFUSAL 2' AUGER REFUSAL

Lab Confirmation Sample
Field Sampling
Needs Delineation and confirmation samples

SP6	CHL	PID	SP7	CHL	PID	SP8	CHL	PID	SP9	CHL	TPH	SP10	CHL	TPH
SURF	37,238	84.4	SURF	33,614	52.4	SURF	27,991	44.8						
L'	22,118	32.2	1'	23,992	22.2	1'	21,368	12.4						
.'	AUGER REI	FUSAL	2'	11,121	34.8	2'	13,620	8.9						
			3'	AUGER REI	•	3'	AUGER RE	FUSAL						

Lab Confirmation Sample
Field Sampling
Needs Delineation and confirmation samples

Company Name: XTO SP Date: 6/26/2015

Location Name: REMUDA BASIN 19 FED #2 SWD Rel Date:

BH1	CHL	PID	BH2	CHL	PID	внз	CHL	PID	SP4	CHL	TPH	SP5	CHL	TPH
5'	3248	0	5'	1174	0	5'	1034	. 0						
10'	3124	0	8'	1034	0	10'	499	0						
15'	4673	0	10'	1274	0									
20'	1149	0	13'	1199										
22'	799	0	15'	1124	0									
			20'	999	0									
			25'	499	0									

Lab Confirmation Sample
Field Sampling
Needs Delineation and confirmation samples



New Mexico Office of the State Engineer Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a (R=POD has been replaced, O=orphaned,

& no longer serves a C=the file is water right file.) Closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest) (NAD83 UTM in meters)

(In feet)

POD Sub-

Sub- Q Q Q Code basin County 64 16 4 Sec Tws Rng

X Y

Depth Depth Water Well Water Column

POD Number C 02486

C ED 3 2 3 19 23S 30E

601304 3572832*

350

Average Depth to Water:

Minimum Depth: -

Maximum Depth: --

Record Count: 1

Basin/County Search:

County: Eddy

PLSS Search:

Section(s): 19 Township: 23S Range: 30E

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

* Attach Additional Sheets If Necessary

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			Rele	ase Notific	ation	and Co	rrective A	ction					
						OPERAT	OR			l Report	F	inal Report	
Name of Co	mnany VT	O Energy			(Contact	John Robinson						
Address 500	M Illinois S	9701	Telephone No. 575-394-2089										
Facility Nar	ne Remuda	Basin 19 Fed	#2 SWD		F	Facility Type Injection							
				136 -16		BLM			Lease N	To. 30-015-2	28901		
Surface Ow	ner BLM			Mineral C	Jwner	DLIVI							
				LOCA	ATION	OF RE	LEASE						
Unit Letter	Section	Township	Range	Feet from the	North/S	South Line	Feet from the	East/\	Vest Line	County			
В	19	23S	30E	510		N	1580]	3	Eddy			
			L				102 0174271						
			La	titude 32.29631	42	_ Longitud	le -103.9174271						
				NAT	TURE	OF REL	EASE						
Type of Rele	ose Drod-	iced Water				Volume of	Release 160	bbls PW	Volume	Recovered ()		
Source of Re	lease Fiber	glass Line	-				lour of Occurren	ce	Date and	Hour of Dis	covery		
Was Immedi	ate Notice G	iven?	_			If YES, To	Whom?						
			Yes 2	No Not R	Required								
By Whom?						Date and I	Hour olume Impacting	the West	eroniirge				
Was a Water	rcourse Reac		7 xz - E	T Ma		If YES, V	olume impacing	, the wa	Cicourse.				
		1_	Yes 2	I No									
If a Waterco	urse was Imp	pacted, Desc	ribe Fully	*									
											4		
D 7 C	use of Proble	am and Rem	edial Acti	on Taken.*		-							
Describe Ca	line develope	d hole A byd	rovac was	brought out to dig	around th	e area of the li	ine and replace the	line.					
Fibergiass	ime develope	d Hole. 11 Hyd	TOTAL TRAD										
Describe A	rea Affected	and Cleanun	Action T	aken.*						·C 1 T: -11 Co.	ari con vril	I handle the	
Spill occu	rea America red in pasture	e area about 9	00 feet sou	aken.* thwest of well. The	spill ran a	approximately	300 yards into the	e pasture	area. Divers	sified Field Sei	vices wii	i nandie die	
cleanup f	or this locatio	n.											
				ve is true and con	nelata ta	the best of m	v Imowledge and	1 unders	and that pu	rsuant to NA	AOCD r	ıles and	
I hereby cer	rtify that the	information	given abo	ve is true and con and/or file certain	npiete to	notifications	and perform con	rective a	ctions for r	eleases which	h may er	danger	
regulations	all operators	are required	ne accenta	and/or file certain nce of a C-141 re	nort by t	he NMOCD	marked as "Final	Report'	does not r	elieve the op	erator of	liability	
public near	m or the envi	have failed to	ne accepta	nce of a C-141 re	l remedia	te contamina	ition that pose a t	threat to	ground wa	ter, surface v	vater, hu	man nearm	
or the envir	conment. In	addition, NN	OCD acc	ely investigate and eptance of a C-14	1 report	does not reli	eve the operator of	of respon	isibility for	compliance	with an	omer	
federal, sta	te, or local la	ws and/or re	gulations.	_	×40	100	07 00	NICEP	VATTO	NI DIMICI	OM		
	11	1	2				OIL CO	NSER	VALIO	N DIVISI	VIN		
	1/1/1	(dist	Wn										
Signature:	Mon	000	VVVI			Approximal	y District Super	visor:					
D.1 13T-	Ioh	n Robinson				Approved	Jy District Buper						
Printed Na	me:								n	Thotas			
Title:	Maintenance	Foreman				Approval I	Date:		Expiration	on Date:	-		
		100 To . Continue -	MAC-CI - CONTRACTOR - CONTRACTO			Conditions	of Approval:			A 1	a m		
E-mail Ad	dress: john_	robinson@xte	oenergy.co	III.		Conditions	or exphrosar.			Attach	ea 📋		
n	5-5-15		Pho	ne: 575-441-5199									
Date:	J-J-10		FIIO	IIV, JIJ TTI JIJJ									