



Yates Petroleum Corporation Humidor State Unit #3 Lightning Strike

Section 14, T24S-R27E. Eddy County, NM

Description: The cause of the release was from a lightning strike that hit a produced water tank. Most of the release was contained within the bermed facility. Upon visiting the site on Monday 7/13/2015, I discovered signs that produced water escaped the berm and ran off the pad into the pasture.

New Mexico State Land Office Carlsbad District: Ian Dolly District Resource Specialist
7/17/2015

New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist

Photographs (1/8)



Photo Point 1

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (2/8)



Photo Point 2

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (3/8)



Photo Point 3: View of Spill Site #2 Lat: 32.709307° Lon: -104.199400°

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (4/8)



Photo Point 4: View of released water escaping via north side of berm

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (5/8)



Photo Point 5: View of produced water on northeast corner of pad.

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (6/8)



Photo Point 6

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (7/8)



Photo Point 7: View of produced water leaving pad

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (8/8)



Photo Point 8: View of produced water leaving pad

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Map (1/1)

