



# COG Operating, LLC. SRO State Unit #1H Line Break

Section 4, T26S-R28E. Eddy County, NM

**Description:** On Monday, 7/13/2015 I discovered evidence of a produced water release originating from a poly pipeline connected to the SRO State Unit #1H. The line has been repaired.

New Mexico State Land Office Carlsbad District: Ian Dolly District Resource Specialist  
7/17/2015

New Mexico State Land Office Carlsbad District  
Ian Dolly District Resource Specialist

Photographs (1/4)



Photo Point 1

**New Mexico State Land Office Carlsbad District  
Ian Dolly District Resource Specialist**

**Photographs (2/4)**



**Photo Point 2**

**New Mexico State Land Office Carlsbad District  
Ian Dolly District Resource Specialist**

**Photographs (3/4)**



**Photo Point 3: View of Spill Site #2 Lat: 32.709307° Lon: -104.199400°**

**New Mexico State Land Office Carlsbad District  
Ian Dolly District Resource Specialist**

**Photographs (4/4)**



**Photo Point 4: View of released water escaping via north side of berm**

# New Mexico State Land Office Carlsbad District Ian Dolly District Resource Specialist

Map (1/1)

