

Received 1/28/2016

NMOCD Dist 2

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-141
Revised October 10, 2003Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form**Release Notification and Corrective Action**

nAB1511048472

OPERATOR☐ Initial Report ☒ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N. Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Wigeon 23 Fed Com 2	Facility Type	Production
Surface Owner	Mineral Owner	Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	23	25S	26E	1350	N	1300	E	Eddy

Latitude 32.1189 Longitude -104.2591

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	15 bbls	Volume Recovered	1 bbl
Source of Release	Flowline	Date and Hour of Occurrence	4-7-15	Date and Hour of Discovery	4-7-15
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required				
By Whom?	Christine Alderman	If YES, To Whom?	Mike Bratcher/Sol Hughes		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
Date and Hour		4-8-15 9:53 a.m.			
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 4" poli line at the edge of location is connected to an 8" trunk line. The valve somehow got opened and the check valve failed. There was evidence of the line being run over by a truck which may have damaged the check valve. DFSI sampled the soil in the area and obtained a clean sample at 10' bgs.

Describe Area Affected and Cleanup Action Taken.*

The entire spill area was excavated to 4'bgs. DFSI personnel used the surrounding terrain to backfill and contour the area. More than five pounds of BLM #4 mix seed was then applied to area, and the site was restored to its previous state.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Christine Alderman

Approved by District Supervisor: *MBratcher*

Title: ESH Supervisor

Approval Date: 2/21/2016

Expiration Date: N/A

E-mail Address: calderman@cimarex.com

Conditions of Approval: N/A

Attached ☐

Date: 7-9-2015

Phone: 432-853-7059

FINAL

* Attach Additional Sheets If Necessary

2RP-2963