

FIELD SPILL REPORT

Distribution List: CJ Barry, TA Savoie, B. Biehl, JR Smitherman, SF Johnson, W Hanna, R Cottle
J Fuqua, C Giese, J Brooks, M Titsworth, A Ruth, A Thompson, B Blevins, D. Williams, J Wachsmann, K Bright

C. Boyd, R. Braun, M. Thompson, T. Carpenter

DATE: September 14, 2015

LOCATION OF SPILL SITE: PLU CVX JV BS 008H

API #: 3001539508

GPS COORDINATES (Lat & Long): 32.124005 -103.853969

ESTIMATED VOLUMES (Oil & Water Separately):

*If BBLs Recovered are not available at time of Initial Report: Send in Follow-up report when numbers are known

Volume spilled:		BBLs Spilled	*BBLs Recovered	Net Spilled		BBLs Spilled	*BBLs Recovered	Net Spilled
On ground /or earth berm -	Oil:			0	Water:	1	0	1
Contained in impervious liner -	Oil:			0	Water:	48	48	0
Total:	Oil:	0	0	0	Water:	49	48	1

HISTORICAL SPILLS:

07-23-13 - third party damage; transport left valve open; 2RP-1855; 42 bbls PW released; complete
11-15-14 - valve left closed on oil dump, non-reportable, 3 bbl oil 1 bbl PW - will remediate
12-15-14 - Process vessel pressure up causing fluid to go out flare; 2RP-2687; 8 bbl oil 1 bbl PW; will remediate
06-23-15 - A 4" hammer union failed on water transfer pump due to vibration; 2RP-3075 35 bbl PW released; will remediate

DESCRIPTION (What happened?):

EHS was notified of a release that occurred when the packing gland failed on the triplex pump.

SPILL RESPONSE (How was the spill cleaned up?):

Vacuum truck recovered 48 bbls of PW from the lined containment. The containment failed releasing 1 bbl PW to the ground surface. Remediation to be planned

PICTURE ATTACHMENT:

