

**From:** [Zack Thomas](#)  
**To:** [Patterson, Heather, EMNRD](#); [agroves@slo.state.nm.us](mailto:agroves@slo.state.nm.us); [Bratcher, Mike, EMNRD](#)  
**Subject:** Bebop 36 W1MD State #2H  
**Date:** Thursday, June 23, 2016 7:46:18 AM  
**Attachments:** image001.png  
image002.png  
C141- Bebop 36 W1MD State #2H (6-18-16) MOC signed initial.pdf

---

Heather, Mike, Amber

Attached is the C141 for the release I called and left a message about on Saturday June 18<sup>th</sup>. We have already Micro Blazed the pasture area. A vacuum truck was close by when this happened and got the standing fluid on the pad recovered very quickly. I don't believe there is any kind of depth to the contamination due to the compactness of the caliche on the pad, and the recovery time of the vac truck. The backhoe was having trouble digging on the pad because it was so hard. According the Chevron Texaco Eddy Co. Depth to Ground Water Map, ground water is 300 plus feet below surface. Due to these facts I don't believe any samples are necessary. I've also attached a picture of the pad after we scraped up a load from it. If there are any questions or concerns please let me know.



**Zack Thomas**  
Environmental Rep.  
Mewbourne Oil Company  
[PO Box 5270](#)  
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252  
(575) 602-2188  
Email: [zthomas@Mewbourne.com](mailto:zthomas@Mewbourne.com)

