Bratcher, Mike, EMNRD

From: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>

Sent: Friday, January 13, 2017 1:03 PM

To: Weaver, Crystal, EMNRD

Cc:Bratcher, Mike, EMNRD; 'stucker@blm.gov'Subject:RE: WPX RDX 15-11 - characterization planAttachments:WPX RDX 15-11 - characterization plan.pdf

Good afternoon,

Attached is the characterization plan for the RDX 15-11 spill/fire. Please let me know if you have any questions or suggestions. I'll proceed with the delineation when I receive your approval. Thank you,

Karolina Blaney

Environmental Specialist WPX Energy

Office: (575) 885-7514 Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]

Sent: Friday, December 16, 2016 10:08 AM

To: Blaney, Karolina < Karolina.Blaney@wpxenergy.com>

Cc: Patterson, Heather, EMNRD < Heather. Patterson@state.nm.us>; Bratcher, Mike, EMNRD

<mike.bratcher@state.nm.us>

Subject: RE: WPX RDX 15-11 - fire and spill notification

RE: WPX Energy/RKI 8 RDX 15-11 * 30-015-37093 * 2RP-4032

Karolina,

Attached are the Conditions of Approval for this C-141 Remediation Permit. The OCD tracking number for this event is 2RP-4032.

Thank you,

Crystal Weaver

Environmental Specialist OCD – Artesia District II 811 S. 1st Street Aretesia, NM 88210

Office: 575-748-1283 Fax: 575-748-9720 From: Patterson, Heather, EMNRD

Sent: Monday, December 5, 2016 11:05 AM

To: Weaver, Crystal, EMNRD < <u>Crystal.Weaver@state.nm.us</u>> **Subject:** FW: WPX RDX 15-11 - fire and spill notification

printed

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]

Sent: Monday, December 05, 2016 11:03 AM

To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'

Subject: WPX RDX 15-11 - fire and spill notification

Good afternoon,

On 12/4/16, WPX had a small fire on the RDX 15-11 well pad; API # 30-015-37093 located in qtr/qtr F, Section 15, T26S R30E. The fire did not spread beyond the SPCC containment berm and was most likely caused by malfunction of the heater treater. As a result, estimated 120 bbls of water and small amount of oil (approximately 1 bbls) got spilled. The majority of the spill was contained inside dirt SPCC berm. Approximately 1-2 bbls sprayed outside the containment. The C-141 report will be submitted within 15 days from the incident.

Please let me know if you have any questions or concerns.

Thank you and have a great day,

Karolina Blaney

Environmental Specialist WPX Energy

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com