

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nMLB1215031855

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Energy	Contact: Aaron Hickert
Address: 2130 W Bender, Hobbs, NM 88240	Telephone No. 432-363-9496
Facility Name: V L Foster #004	Facility Type: Oil

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-05203
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter J	Section 17	Township 17S	Range 31E	Feet from the 1650	North/South Line South	Feet from 1650	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-------------------	------------------------	----------------

Latitude: 32.8318352193832 **Longitude:** -103.888755956835

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 25 gal	Volume Recovered: 0
Source of Release: Polyline	Date and Hour of Occurrence 04/17/2012 1:00 PM	Date and Hour of Discovery 04/17/2012 1:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher – NMOCD, Terry Gregston – BLM	
By Whom? Joe Hernandez	Date and Hour: 04/29/2012 10:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

3" poly was cut and removed beside road. COG company cut polyline while building new pad. They never fused line together. Unit is not in service but still leak ½ barrel of water that was left in line.

Describe Area Affected and Cleanup Action Taken.

The impacted soils were scraped and properly disposed of at a NMOCD approved facility. The excavation was backfilled with clean, imported caliche to ground surface and contoured to the surrounding area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		OIL CONSERVATION DIVISION	
Signature:	Approved by Environmental Specialist: 		
Printed Name: Aaron Hickert			
Title: Sr EH&S Representative	Approval Date: 2/23/17	Expiration Date: N/A	
E-mail Address: ahickert@linenergy.com	Conditions of Approval: BLM Approval		Attached <input type="checkbox"/>
Date: 02/07/2017 Phone: 432-363-9496			

* Attach Additional Sheets If Necessary

2RP-1129