

FIELD SPILL REPORT

Distribution List: CJ Barry, TA Savoie, B. Biehl, JR Smitherman, SF Johnson, W Hanna
J Fuqua, C Giese, J Brooks, M Titsworth, A Ruth, A Thompson, B Blevins, D. Williams, K Bright
C. Boyd, C. Rasmussen, R. Braun, M. Thompson, T. Carpenter

DATE: June 22, 2015

LOCATION OF SPILL SITE: JRU -29 SWD (API 30-015-27735)

UL K, 36-22S-30E, Eddy Co.

GPS COORDINATES (Lat & Long): 32.346432 -103.835934

ESTIMATED VOLUMES (Oil & Water Separately):

*If BBLs Recovered are not available at time of Initial Report: Send in Follow-up report when numbers are known

Volume spilled:		BBLs Spilled	*BBLs Recovered	Net Spilled		BBLs Spilled	*BBLs Recovered	Net Spilled
On ground /or earth berm -	Oil:			0	Water:	90	20	70
Contained in impervious liner -	Oil:			0	Water:	20	20	0
Total:	Oil:	0	0	0	Water:	110	40	70

DESCRIPTION (What happened?):

A 4" by 2' threaded pipe connection cracked and parted along the threads where it connected to a T on the discharge side of the pump. NOTE: there was a piping stress issue corrected at the time the new fitting was installed on the discharge piping.

SPILL RESPONSE (How was the spill cleaned up?):

Vacuum truck recovered 20 bbls produced water from containment and 20 bbls produced water on ground. A portion of the impacted area was previously remediated and has a liner installed at a depth of approximately 3 feet. Remediation to be planned

PICTURE ATTACHMENT:

