

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NMOCD Dist 2

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1801755995

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Matador Resources	Contact Casey Snow
Address 500 N Main St Suite 1 Roswell NM 88201	Telephone No. (972) 371-5439
Facility Name Tiger Recycling Facility	Facility Type Produced Water Recycle Facility
Surface Owner Private	Mineral Owner Private
API No. n/a	

LOCATION OF RELEASE

Unit Letter P	Section 14	Township 24S	Range 28E	Feet from the 215	North/South Line South	Feet from the 915	East/West Line EAST	County EDDY
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude __ 32.211011° Longitude _ -104.052031°

NATURE OF RELEASE

Type of Release Produced Water and Crude Oil	Volume of Release 460bbbls	Volume Recovered 435 bbls
Source of Release Equipment Failure on Recycle Tank	Date and Hour of Occurrence 12/28/17 8:20 pm	Date and Hour of Discovery 12/29/17 12 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NM OCD Artesia District Office	
By Whom? Lucas Middleton (SMA)	Date and Hour 12/29/17 3:19pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Cause: Equipment Failed and allow the Recycle tank to over flow on to secondary containment and pad
Remedial Action: Stopped over flow of tank and began to vac all standing liquids.

Describe Area Affected and Cleanup Action Taken.*

The Affected area was predominately within secondary containment and approximately a 60' x 40' area affecting the production pad. At the time of spill the ground was frozen due to low temperature and initial inspection showed the release to remain surficial. The initial response was to vac all stand liquid on secondary containment and on production pad.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Casey Snow		Approved by Environmental Specialist: 	
Title: Manager Regulatory, Environmental, & Safety		Approval Date: Rec 1/17/2018	Expiration Date:
E-mail Address: csnow@matadorresources.com		Conditions of Approval: See COA's	Attached <input checked="" type="checkbox"/>
Date: 1/17/18	Phone: (972) 371-5439		

* Attach Additional Sheets If Necessary