

Received on 4/24/18

Artesia, NM

Form C-141

Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

Initial Report    X    Final Report

Name of Company: Lucid Energy Delaware	Contact: Kerry Egan
Address: 201 South Fourth Artesia, NM 88210	Telephone No.: 575 513-8988
Facility Name: Emma 8" Steel line	Facility Type: Pipeline ROW
Surface Owner: R. Houghtaling	Mineral Owner
API No.	

### LOCATION OF RELEASE

Unit Letter	Section 21	Township 19S	Range 24E	Feet from the	North/South Line	Feet from the	East/West Line	County EDDY
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.640143° Longitude -104.592043°

### NATURE OF RELEASE

Type of Release: Natural Gas, and pipeline liquids	Volume of Release: <500 Mcf of gas; < 10bbbls of pipeline liquids	Volume Recovered: None
Source of Release: Leaking flange in the line.	Date and Hour of Occurrence: 2/26/2018	Date and Hour of Discovery: 2/26/2018
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The source of the leak is suspected to have been an 8" steel gas line with internal corrosion. Upon discovery the line was immediately shut in to prevent further loss. The line remains down until repairs can be made.



Update 4/24/18: Line repaired and returned to service.

Describe Area Affected and Cleanup Action Taken.\*

The surface area around the source of the leak is approximately 15' x 10'. A portion of the liquids released made it onto a two track road that parallels the pipeline ROW, and ran for several hundred feet along the track. The affected area will be excavated and the two track will have the contamination scrapped off of the surface. Depending on the analysis of soil samples a work plan will be prepared to outline further cleanup action.

Update 4/24/18: The affected area, including the two track road, have been excavated and confirmation samples have been collected.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Kerry Egan	Approved by Environmental Specialist: 	
Title: Environmental Compliance Coordinator	Approval Date: 4/27/18	Expiration Date: N/A
E-mail Address: KEgan@lucid-energy.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 4/24/2018      Phone: 575 810-6021		

\* Attach Additional Sheets If Necessary

2RP-4646