Chevron U.S.A. Inc. C-147 Registration Application Package Hayhurst New Mexico T26S R27E

- Section 2 Recycling Containment
- Section 2 Recycling Facility



Jan 17, 2018

Chevron

Hayhurst New Mexico T26S R27E Section 2 U.S.A. Inc. | Recycling Containment and Facility

Contents

I.	INTRODUCTION3
II.	NMOCD FORM C-1473
III.	SITING REQUIREMENTS7
А	. DISTANCE TO GROUNDWATER7
В	. DISTANCE TO SURFACE WATER7
C	. DISTANCE TO PERMANENT RESIDENCE OR INSTITUTIONS7
D	. DISTANCE TO DOMESTIC AND STOCK WATER SUPPLIES8
Ε.	DISTANCE TO MUNICIPAL BOUNDARIES AND FRESH WATER FIELDS
F.	DISTANCE TO WETLANDS8
G	. DISTANCE TO SUBSURFACE MINES8
H.	DISTANCE TO CAVE / KARST FEATURES8
1.	DISTANCE TO 100-YEAR FLOODPLAINS8
IV.	DESIGN AND CONSTRUCTION PLAN9
A.	
	GENERAL SPECIFICATIONS9
Α.	GENERAL SPECIFICATIONS9 STOCKPILING OF TOPSOIL10
A. B.	GENERAL SPECIFICATIONS9 STOCKPILING OF TOPSOIL10 SIGNS10
A. B. C.	GENERAL SPECIFICATIONS 9 STOCKPILING OF TOPSOIL 10 SIGNS 10 FENCING 10
A. B. C. D.	GENERAL SPECIFICATIONS 9 STOCKPILING OF TOPSOIL 10 SIGNS 10 FENCING 10
A. B. C. D. E.	GENERAL SPECIFICATIONS 9 STOCKPILING OF TOPSOIL 10 SIGNS 10 FENCING 10 NETTING AND WILDLIFE PROTECTION 11
A. B. C. D. E. V.	GENERAL SPECIFICATIONS 9 STOCKPILING OF TOPSOIL 10 SIGNS 10 FENCING 10 NETTING AND WILDLIFE PROTECTION 11 OPERATING AND MAINTENANCE PLAN 11
A. B. C. D. E. V. VII.	GENERAL SPECIFICATIONS 9 STOCKPILING OF TOPSOIL 10 SIGNS 10 FENCING 10 NETTING AND WILDLIFE PROTECTION 11 OPERATING AND MAINTENANCE PLAN 11 CLOSURE PLAN 12
A. B. C. D. E. V. VII.	GENERAL SPECIFICATIONS 9 STOCKPILING OF TOPSOIL 10 SIGNS 10 FENCING 10 NETTING AND WILDLIFE PROTECTION 11 OPERATING AND MAINTENANCE PLAN 11 CLOSURE PLAN 12 FINANCIAL ASSURANCE REQUIREMENTS 13 VARIANCE REQUESTS 13
A. B. C. D. E. V. VII. VIII.	GENERAL SPECIFICATIONS 9 STOCKPILING OF TOPSOIL 10 SIGNS 10 FENCING 10 NETTING AND WILDLIFE PROTECTION 11 OPERATING AND MAINTENANCE PLAN 11 CLOSURE PLAN 12 FINANCIAL ASSURANCE REQUIREMENTS 13 VARIANCE REQUESTS 13 SECONDARY LINER SPECIFICATION 14
A. B. C. D. E. V. VI. VII. A.	GENERAL SPECIFICATIONS 9 STOCKPILING OF TOPSOIL 10 SIGNS 10 FENCING 10 NETTING AND WILDLIFE PROTECTION 11 OPERATING AND MAINTENANCE PLAN 11 CLOSURE PLAN 12 FINANCIAL ASSURANCE REQUIREMENTS 13 VARIANCE REQUESTS 13 SECONDARY LINER SPECIFICATION 14 FENCING 14

I. INTRODUCTION

Chevron U.S.A. Inc. (Chevron) requests registration under 19.15.34 NMAC of the following recycling containment and recycling facility in the Hayhurst New Mexico development area located in Township 26 South, Range 27 East.

- Section 2 Recycling Containment
- Section 2 Recycling Facility

Appendix 1 contains a survey plat identifying the location of the recycling containment and the recycling facility. Note that the Section 2 recycling containment is identified as "Proposed Frac Pond 4" and the Section 2 recycling facility is identified as "Proposed Recycling Facility", respectively on the plat.

Compliance with the requirements of 19.15.34.11 through 19.15.34.15 is described in this application. Note that Chevron is requesting a total of three variances from these requirements as noted in Section IV and fully described in Section VIII.

A copy of Form C-147 found in Section II has been submitted to the State Land Office, which is the surface land owner, as required under 19.15.34.10.A.

II. NMOCD FORM C-147

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr.

Form C-147 Revised March 31, 2015

Santa Fe, NM 87505

Recycling Facility and/or Recycling Containment			
Type of Facility: Recycling Facility Recycling Containment* Type of action: Registration Registration Modification Extension			
Closure Other (explain)			
* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.			
Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.			
Operator:(For multiple operators attach page with information) OGRID #:4323			
Address: _1400 Smith Street, Houston TX 77002			
Facility or well name (include API# if associated with a well): "HH NM Sec 2 Frac Pond and Recycle Facility"			
OCD Permit Number:(For new facilities the permit number will be assigned by the district office)			
U/L or Qtr/Qtr N Section 2 Township 26 South Range 27 East County: Eddy			
Surface Owner: Federal State Private Tribal Trust or Indian Allotment			
Z. ✓ Recycling Facility: (Location: U/L N, Section 2, T26S, R27E)			
Location of recycling facility (if applicable): Latitude 32.065644 Longitude -104.165003 NAD: 1927 1983			
Proposed Use: ☐ Drilling* ☒ Completion* ☐ Production* ☐ Plugging *			
*The re-use of produced water may NOT be used until fresh water zones are cased and cemented			
Other, requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on			
groundwater or surface water.			
☐ Fluid Storage			
Above ground tanks Recycling containment Activity permitted under 19.15.17 NMAC explain type			
Activity permitted under 19.15.36 NMAC explain type: Other explain			
For multiple or additional recycling containments, attach design and location information of each containment (see Part 3 below for Section			
10 recycling containment and bottom of page 3 for Section 9 recycling containment location)			
Closure Report (required within 60 days of closure completion): Recycling Facility Closure Completion Date:			
⊠ Recycling Containment:			
Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)			
Center of Recycling Containment (if applicable): Latitude <u>32.071130</u> Longitude <u>-104.166990</u> NAD: □1927 ☑ 1983			
For multiple or additional recycling containments, attach design and location information of each containment			
☐ Lined ☐ Liner type: Thickness 60 mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other			
☐ String-Reinforced			
Liner Seams: Welded Factory Other Field Volume: 587,330 bbl Dimensions: L_796' x W_683' x D_23'			
Recycling Containment Closure Completion Date:			

4.	
Bonding: ☐ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the web operated by the owners of the containment.) ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$	
Fencing: ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet ☐ Alternate. Please specify 8 ft. tall chain link with 3 strand barbed wire on top. Please see attached (Sec. V III.B) regarding proposed for the strand barbed wire on top.	fencing for details.
Signs: □ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers □ Signed in compliance with 19.15.16.8 NMAC	
Variances: Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, hu environment. Check the below box only if a variance is requested: □ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is request variance information on a separate page and attach it to the C-147 as part of the application. If a Variance is requested, it must be approved prior to implementation.	
Siting Criteria for Recycling Containment Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the applicant examples of the siting attachment source material are provided below under each criteria.	ation. Potential
General siting Ground water is less than 50 feet below the bottom of the Recycling Containment. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☒ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; written approval obtained from the municipality	□ NA □ Yes ☑ No □ NA
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division	☐ Yes ☑ No
 Within an unstable area. Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map 	☐ Yes ☒ No
Within a 100-year floodplain. FEMA map Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; visual inspection (certification) of the proposed site	☐ Yes ☒ No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; aerial photo; satellite image	☐ Yes ☒ No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site	☐ Yes ⊠ No
Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site	☐ Yes ☒ No

9.	
Recycling Facility and/or Containment Checklist:	
Instructions: Each of the following items must be attached to the applicati	ion. Indicate, by a check mark in the box, that the documents are attached.
Design Plan - based upon the appropriate requirements.	
Operating and Maintenance Plan - based upon the appropriate required Closure Plan - based upon the appropriate requirements.	ments.
Site Specific Groundwater Data -	
Siting Criteria Compliance Demonstrations – Certify that notice of the C-147 (only) has been sent to the surface	
Certify that notice of the C-147 (only) has been sent to the surface	owner(s)
Operator Application Certification:	
· · · · · · · · · · · · · · · · · · ·	plication are true, accurate and complete to the best of my knowledge and belief.
Name (Print): Tony Vallejo Title: HES Support	to the best of my knowledge and benefit.
Signature: Tay Valpo	
a mail address. VIIIA Q.I	
e-mail address:vjuA@cnevron.com	Telephone: <u>325-450-1413</u>
OCD Representative Signature: Bradford Billings	Approval Date: 3/27/2019
Title: Hydrologist	OCD Permit Number:
OCD Conditions	
Additional OCD Conditions on Attachment	

III. SITING REQUIREMENTS

A. DISTANCE TO GROUNDWATER

Appendix 2 / Figure 1, Appendix 3, and the discussion below demonstrates that depth to groundwater at the proposed location is greater than 50 feet beneath the bottom of the recycling containment. There were two sets of boring. Borings B-2, B-3, B-6, B-7 and B-8 (the final pond location) show ground water is greater than 50 feet beneath the bottom. Appendix 2 / Figure 1 is a geologic map based on a GIS database of geologic units and structural features in the general location.

The Hobbs Sheet of the Geologic Atlas of Texas locates the project site within sand, silt, and clay deposits (Windblown sand, alluvium, playa, and fluviatile terrace deposits, Qcs, Qp,) underlain by Blackwater Draw (Qbd) Formation consisting of caliche. The caliche and windblown deposits consist of sand and silt in sheets and may sometimes be associated with playa deposits that are generally associated with organics. The windblown cover sands are fine to medium grained, silty, calcareous, and include caliche nodules. Generally, these deposits are 20 to 50 feet thick. The caliche is a conglomerate of various materials such as clay, silt, sand, and gravel that included precipitated calcium carbonate. Often, the calcium carbonate cements the soil grains together. The level of cementation can vary and can be highly cemented to weakly cemented. These deposits can often be soft or loose, especially in the presence of groundwater. Our findings of the exploration are consistent with this within the depths explored.

On Sept 7, 2017, site-specific geotechnical boring was conducted to a depth of 75.5 feet with no detected or observed groundwater presence and the borehole remained dry for a period of at least 24 hours following drilling. The Test Boring Logs may be found in Appendix 3.

B. DISTANCE TO SURFACE WATER

Appendix 2 / Figure 2 illustrates that the recycling containment is not located within 300 feet of a continuously flowing watercourse or 200 feet of any other significant watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

No continuously flowing watercourses of other significant water features, as defined by NMOCD rules, are.

C. DISTANCE TO PERMANENT RESIDENCE OR INSTITUTIONS

Appendix 2 / Figure 3 illustrates that the recycling containment is not located within 1,000 feet of a permanent residence, school, hospital, institution, or church in existence at the time of this initial registration. The only development and structures in the prescribed setback area is associated with oil and gas production operations.

Hayhurst New Mexico T26S R27E Section 2 Recycling Containment and Facility

D. DISTANCE TO DOMESTIC AND STOCK WATER SUPPLIES

Appendix 2 / Figure 4 illustrates that the recycling containment is not located within 500 feet of a spring or fresh water well used for domestic of stock watering purposes at the time of this initial registration. Appendix 2 / Figure 4 identifies that the nearest water well listed in the NMOSE database.

E. DISTANCE TO MUNICIPAL BOUNDARIES AND FRESH WATER FIELDS

Appendix 2 / Figure 5 illustrates that the recycling containment is not within incorporated municipal boundaries or within defined municipal fresh water well fields covered under a municipal ordinance adopted pursuant to Section 3-27-3 NMSA 1978, as amended.

The nearest municipal community to the recycling containment are:

- Village of Malaga, which is not incorporated, located approximately 13 miles northeast;
- Village of Loving, which is incorporated but noes not operate any municipal fresh water well fields, located approximately 16 miles north/northeast; and
- City of Carlsbad, which is incorporated, located approximately 19 miles north/northwest and operates the Sheep Draw Well Field located southwest of the city and approximately 18 miles northwest of the recycling containment.

F. DISTANCE TO WETLANDS

Appendix 2 / Figure 3 illustrates that the recycling containment is not located within 500 feet of any identified wetland. The nearest identified wetland is approximately 5,300 feet southeast of the recycling containment.

G. DISTANCE TO SUBSURFACE MINES

General knowledge based on interaction with the Bureau of Land Management (BLM) Carlsbad Field Office (CFO) staff and a search of the NM EMNRD Mining and Minerals Division database confirms that there are no subsurface mines in proximity of the recycling containment. The only identified facilities in the general vicinity are surface caliche and aggregate pits.

H. DISTANCE TO CAVE / KARST FEATURES

The recycling containment is located within a BLM-identified medium potential karst zone. Appendix 2 / Figure 6, BLM inventory data of existing cave/karst features, and results of site-specific geotechnical studies as detailed in Appendix 6 verify that the recycling containment is not located within an unstable area.

I. DISTANCE TO 100-YEAR FLOODPLAINS

Available information from the Federal Emergency Management Agency indicates that recycling containment location is within the FEMA-identified Zone D, which is an area with possible but undetermined flood hazards where flood hazard analysis has not been conducted and mapped and generally considered to be of minimal flood risk. Field inspection and evaluation of topography in the

Chevron U.S.A. Inc.

Hayhurst New Mexico T26S R27E Section 2 Recycling Containment and Facility

general vicinity leads to a determination that the recycling containment is not within any floodplain and has minimal risk for flooding.

IV. DESIGN AND CONSTRUCTION PLAN

Appendix 4 contains the design drawings and details for the recycling containment, which were developed and stamped by a Professional Engineer licensed in the state of New Mexico. Appendix 5 contains the construction specifications to accompany the design drawings and details. These design and construction specifications meet or exceed NMOCD requirements for recycling containments. Appendix 6 contains the Geotechnical Engineering Study Report for the recycling containment site.

A. GENERAL SPECIFICATIONS

The following general specifications have been incorporated into the design and will be met during construction.

- The recycling containment is designed and will be constructed to ensure confinement of produced water, to prevent releases, and to prevent overtopping due to wave action or rainfall.
- The recycling containment, as designed, will be constructed with a proper foundation and
 interior slopes consisting of a firm, unyielding base, which is smooth and free of rocks, debris,
 sharp objects, and irregularities. In addition, 8 ounce non-woven geotextile will be installed
 under the secondary liner to provide additional protection from any protuberances in the
 foundation and reduction of localized stress-strain.
- The recycling containment will be constructed in a levee with inside and outside grades of three horizontal feet to one vertical foot (3H:1V), which is shallower and provides greater stability than the NMOCD 2H:1V specification for the inside grade.
- The recycling containment will be constructed with a 60 mil HDPE primary and secondary liner and an interstitial leak detection system. Note that the 60 mil HDPE secondary liner exhibits a hydraulic conductivity of less than 1 x 10⁻¹² cm/sec. Note that this is a variance from the specified 30 mil LLDPE string reinforced liner or equivalent with a hydraulic conductivity of 1 x 10⁻⁹ cm/sec and provides greater protection of fresh water, public health, and the environment. Please refer to Section VIII.A that provides a full description and basis for this variance request.
- The exterior edges of both liners will be anchored in the bottom of a 24-inch deep compacted earth-filled trench, which exceeds the NMOCD 18 inch specification.
- Liner seams will be minimized and oriented vertically rather than across all levee slopes.
 Factory welded seams will be utilized to the maximum extent possible. Sloped liner panels will extend a minimum of five feet beyond the point of grade change to prevent seams from resting on the grade break.

Chevron U.S.A. Inc.

Hayhurst New Mexico T26S R27E Section 2 Recycling Containment and Facility

- All field seams and welds will be subjected to non-destructive field testing by qualified
 personnel per the appropriate testing standard to ensure proper thermal sealing. Details on
 liner testing procedures may be found in Section 33 47 13 / Subpart 3.04 of the construction
 specification (Appendix 5). Field seams will be overlapped a minimum of six inches.
- The primary liner will be protected from excessive hydraulic force or mechanical damage from discharge or suction within the recycling containment. No discharge or suction lines penetrate the liners.
- The recycling containment will be constructed with a leak detection system between the
 primary and secondary liners comprised of a 200-mil geonet. The system is properly designed
 to facilitate effective drainage, collection, and removal of liquid above the secondary liner and
 leakage detection at the earliest possible time.
- The recycling containment is designed to prevent run-on of surface water. The minimal distance from the existing surface elevation to the top of the containment berm will be approximately four feet.

B. STOCKPILING OF TOPSOIL

Where topsoil is present, prior to constructing the recycling containment, it will be stripped and stockpiled on site for use as final cover or fill at time of closure.

C. SIGNS

An upright sign no less than 12 inches by 24 inches with lettering no less than two inches in height will be installed in a conspicuous place on the fence surrounding the containment. The sign will be installed in such a manner and location that a person can easily read the legend. The sign will include the following information:

- The operator's name;
- The location of the site by quarter-quarter or unit letter, section, township, and range;
- Emergency telephone number.

D. FENCING

The recycling containment will be constructed with an eight foot tall chain link fence equipped with three strands of barbed wire on top to deter unauthorized wildlife and human access. Note that this is a variance from the minimum required four foot fence with at least four stands of barbed wire evenly spaced in the intervals between one foot and four feet above ground level and provides equivalent or greater wildlife and human deterrence. Please refer to Section VIII.B that provides a full description and basis for this variance request.

The fence will be gated to provide access to Operations personnel and will be closed and locked when access is not required

Hayhurst New Mexico T26S R27E Section 2 Recycling Containment and Facility

E. NETTING AND WILDLIFE PROTECTION

The game fence, as described above, surrounding the recycling containment will be effective is excluding terrestrial wildlife. Due to infeasibility of installing netting on a recycling containment system of this size (750 feet by 900 feet), an audible avian deterrence system has been designed and will be installed as an alternative. This type of system is currently used by other recycling containment operators in southeast New Mexico and has been demonstrated as providing effective protection for avian species, including migratory birds. Note that this is a variance from the specified screening or netting and will provide equal protection of avian species. Please refer to Section VIII.C that provides a full description and basis for this variance request.

Containment inspections will be conducted at least once per week to include visual determination of any wildlife impacts. If any dead migratory birds or other wildlife is detected, notification to the New Mexico Department of Game and Fish and NMOCD District Office will provided as soon as practicable but no later than 30 days from the date of discovery.

V. OPERATING AND MAINTENANCE PLAN

The recycling containment will be operated in such a manner to contain liquids and solids and the integrity of the liner and leak detection system will be monitored in such a manner to prevent contamination of fresh water and protect public health and the environment as described below. The purpose of the recycling containment is to facilitate recycling of treated produced water from nearby oil and gas wells for new well completions. When treated produced water is not needed for well completion activity, produced water will be properly injected at one of Chevron's or third party's authorized SWDs. The recycling containment will not be used for disposal of produced water or other oilfield wastes.

The recycling containment and associated leak detection system will be inspected at least weekly while it contains any fluid and results of the inspection will be documented on an inspection checklist. These inspections will be performed by a third party contractor, which has been selected by Chevron to operate the recycling facilities and monitor the associated recycling containments. The contractor will continuously staff these facilities while in operation. The completed checklists will be retained and made available for review upon request.

These inspections will address, at a minimum, the following:

- Removal of any visible layer of oil from the liquid surface;
- Verification that a minimum of three foot freeboard is maintained;
- If a liner breach is identified above the liquid surface, the liner will be repaired or liner replacement will be initiated within 48 hours of detection. Alternatively, the NMOCD district office will be contacted within 48 hours to seek and extension for liner repair / replacement.

Chevron

Hayhurst New Mexico T26S R27E Section 2 U.S.A. Inc. | Recycling Containment and Facility

- If a liner breach is identified below the liquid surface, all liquid above the identified breach will be removed, the NMOCD district office will be notified, and liner repair / replacement shall be initiated within 48 hours of discovery.
- Visual inspection of berm integrity and condition to ensure the prevention of surface water run-
- Determination that an oil absorbent boom is present and in proper condition to contain an unanticipated release.

The recycling containment will be equipped with continuous liquid level monitoring and interstitial leak detection systems utilizing pressure transducers connected through a SCADA system to provide immediate notification to Chevron field personnel.

Treated produced water deposits into and withdrawals from the recycling containment will be measured and documented to determine when the system has ceased operations (less than 20% of the total fluid capacity is used during each rolling six month period following the initial withdrawal of produced water). The third party contactor will keep accurate records of total volumes of water received and treated through the recycling facility. Chevron will submit Form C-148 monthly to NMOCD within 30 days of the end of the calendar month listing: volumes of produced water received; volumes of fresh or brackish water received; and total volume of water leaving the recycling facility.

Upon cessation of operation, the NMOCD district office will be notified. Chevron will submit to NMOCD a completed Form C-148 within 30 days following the end of each calendar month. Each submittal will certify that the recycling containment has not ceased operation based on the 20% threshold described above.

VI. CLOSURE PLAN

After operations cease (less than 20% of the total fluid capacity is used every six months following the initial withdrawal of produced water), all fluids will be removed within 60 days and the recycling containment closed within six months.

All removed liquids, solids, and liner materials will be removed and transferred to an NMOCD-approved disposal facility within the six month period.

A five-point composite sample will be collected from beneath the containment and tested for contamination. The composite sample will include stained or wet soil areas, if any, and analyzed for constituents listed in Table I of 19.15.34.14 NMAC.

If any contaminant concentration exceeds the values listed in Table I (based on depth from bottom of containment to groundwater), the NMOCD district office will be contacted requesting approval before proceeding with closure activity.

Chevron U.S.A. Inc.

Hayhurst New Mexico T26S R27E Section 2 Recycling Containment and Facility

 If all contaminant concentrations are less than or equal to the values listed in Table I, closure will proceed by backfilling with non-waste containing, uncontaminated, earthen material.

Within 60 days of completing closure, a Closure Report on NMOCD Form C-147, including required attachments, will be submitted to document all closure activities including sampling results and details of any backfilling, capping, or covering, were applicable. The Closure Report will certify that all information in the report and attachments is correct and that all applicable closure requirements and conditions specified in NMOCD rules and directives have been met.

The recycling containment's locations will be reclaimed to a safe and stable condition that blends with the surrounding undisturbed areas. Topsoils and subsoils will be replaced to their original relative positions and contoured to achieve erosion control, long-term stability, and preservation of surface water flow patterns.

The location will be reseeded in the first favorable growing season following closure with the goal of substantially restoring the impact surface location to the existing condition prior to construction of the recycling containment. Surface reclamation will be deemed complete when: all ground surface disturbing activities have been completed; a uniform vegetative cover with a life-form ratio of plus or minus 50% of pre-disturbance levels has been established; and a total percent plant over of at least 70%, excluding noxious weeds, has been established.

Surface reclamation obligations imposed by the Bureau of Land Management or New Mexico State Trust Land on lands managed by those agencies will supersede these requirements, provided that these other requirements provide equal or greater protection of fresh water, human health, and the environment. NMOCD will be notified when reclamation and re-vegetation are complete.

VII. FINANCIAL ASSURANCE REQUIREMENTS

Chevron U.S.A. Inc. (OGRID 4323) has existing financial assurance in place with NMOCD as required by 19.15.8 NMAC and use of the recycling containment will be limited to support completion of only wells owned and operated by Chevron U.S.A. Inc. Therefore, no additional financial assurance associated with the recycling containment is required.

VIII. VARIANCE REQUESTS

This registration includes requests for three variances from the requirements for each recycling containment as described below.

Hayhurst New Mexico T26S R27E Section 2 Recycling Containment and Facility

A. SECONDARY LINER SPECIFICATION

The recycling containment has been designed and will be constructed with a 60 mil HDPE secondary liner rather than the prescribed 30 mil LLDPE secondary liner. Chevron has selected the 60 mil HPDE material for the following reasons:

- The 60 mil HDPE exhibits a maximum hydraulic conductivity of 1 x 10^{-12} cm/sec, which exceeds the specified performance of 1 x 10^{-9} cm/sec.
- The US Environmental Protection Agency identifies 60 mil as the recommended minimum thickness for HDPE as detailed in the EPA's Guide for Industrial Waste Management, Part IV, Chapter 7, Section B, page 7B-24 addressing protection of groundwater through proper design and installation of double liner systems.
- HDPE was selected as the preferred secondary liner material based upon weathering/aging characteristics, mechanical properties, and chemical resistance.
- HDPE liner life is expected to exceed twenty years, which is substantially longer than the
 anticipated age of the recycling containment to support well completion activities in the
 development area.
- The 60 mil HDPE liner is compliant with internal Chevron Global engineering design and environmental performance standards.

Chevron believes that this variance from the NMOCD prescribed liner specification is warranted and provides greater protection of groundwater resources. Liner hydraulic conductivity and performance specifications are found in Appendix 7.

B. FENCING

The recycling containment has been designed and will be equipped with an eight foot tall chain link fence equipped with three strands of barbed wire on top. This fence will not be installed with the specified four stands of barbed wire but offers equivalent entry deterrence to wildlife and unauthorized human without introducing the risk of injury resulting from unintended or incidental contact with the barbed wire.

C. NETTING


The recycling containment has been designed and will be equipped with an audible avian species protection system, which effectively deters birds from approaching the area. Due to the size of the proposed recycling containment structure (750 feet by 900 feet), design, construction, and maintenance of netting is not practicable. Chevron has evaluated multiple alternatives, determined that an audible system is the most effective and viable option, and selected the Bird-X Mega Blaster PRO for use. This particular product has been used by other operators with registered recycling containments in southeast New Mexico and proven effective.


Chevron

Hayhurst New Mexico T26S R27E Section 2 U.S.A. Inc. | Recycling Containment and Facility

IX. APPENDICES

Appendix 1 – Survey Plat





DISCLAIMER: At this time, C. H. Fenstermaker & Associates, L.L.C. has not performed nor was asked to perform any type of engineering, hydrological modeling, flood plain, or "No Rise" certification analyses, including but not limited to determining whether the project will impact flood hazards in connection with federal/FEMA, state, and/or local laws, ordinances and regulations. Accordingly, Fenstermaker makes no warranty or representation of any kind as to the foregoing issues, and persons or entities using this information shall do so at their own risk.

NOTE:

Please be advised, that while reasonable efforts are made to locate and verify pipelines and anomalies using our standard pipeline locating equipment, it is impossible to be 100 % effective. As such, we advise using caution when performing work as there is a possibility that pipelines and other hazards, such as fiber optic cables, PVC pipelines, etc. may exist undetected on site.

NOTE:

Many states maintain information centers that establish links between those who dig (excavators) and those who own and operate underground facilities (operators). It is advisable and in most states, law, for the contractor to contact the center for assistance in locating and marking underground utilities. For guidance, a few states with such programs are listed below: New Mexico One Callwww.nmonecall.org.

METES AND BOUNDS DESCRIPTION OF A PROPOSED FRAC POND LOCATED IN SECTION 2 OF TOWNSHIP 26 SOUTH-RANGE 27 EAST EDDY COUNTY, NEW MEXICO

Survey of a Proposed Frac Pond containing 15.50 acres, more or less, located on State of New Mexico property located in Section 2 of Township 26 South, Range 27 East, Eddy County, New Mexico and described as follows:

Commencing at the Southwest corner of said Section 2, Township 26 South Range 27 East at a Found 1 1/2" Iron Pipe with cap; Thence North 14 degrees 51 minutes 06 seconds East 2,238,43 feet to the Point of Beginning. Said Point of Beginning having the following coordinates: X = 551,348.50 and Y = 389,101.47 (New Mexico State Plane Coordinate System, East Zone, NAD 27).

Thence North 05 degrees 06 minutes 39 seconds West 900,00 feet to a point; Thence North 84 degrees 53 minutes 21 seconds East 750,00 feet to a point; Thence South 05 degrees 06 minutes 39 seconds East 900,00 feet to a point; Thence South 84 degrees 53 minutes 21 seconds West 750.00 feet back to the said Point of Beginning.

The bearings recited hereon are oriented to New Mexico State Plane Coordinate System, East Zone, NAD 27.

This description represents a survey made on the ground for a proposed frac pond and intended solely for that purpose. This description does not represent a boundary

FOR THE EXCLUSIVE USE OF CHEVRON U.S.A. INC. I, Robert L. Lastrapes, Professional Surveyor, do hereby state this plat is true and correct to the best of my knowledge.

EN MEXICO

Robert Lastapes Registration No. 23006

P	ROPOSED FRAC PO	OND			
COURSE	BEARING	DISTANCE			
1	N 05° 06' 39" W	900.00			
2	N 84" 53' 21" E	750.00'			
3	S 05" 06' 39" E	900.00'			
4	S 84° 53' 21" W	750.00			

PAGE 2 OF 2

FRAC POND PLAT


CHEVRON U.S.A. INC.

PROPOSED FRAC POND FRAC POND NO. 4 SECTION 2, T26S-R27E EDDY COUNTY, NEW MEXICO




C. H. Fenstermaker & Associates, L.L.C. 135 Regency Sq. Lafayette, LA 70508 Ph. 337-237-2200 Fax. 337-232-3299 www.fenstermaker.com


Ī	DRAWN BY: BOR		REVI	SIONS
	PROJ. MGR.: GDG	No. 3	DATE: 03/16/2018	REVISED BY: BOR
- 1	DATE: APRIL 07, 2017	No. 4	DATE: 03/21/2018	REVISED BY: GDG
	FILENAME: T:\2017\2175724\DWG\FRAC POND #4 SUP.dwg			




Chevron USA Inc. T26SR27 Section 2 Recycle Containment / Appendix 2/ Figure 1 : Geologic Map




Chevron USA Inc. 26S R27E Section 2 Proposed Recycling Containment / Proposed Recycling Facility Appendix 2 / Figure 2 – Surface Water Features and Water Courses




Chevron USA Inc. 26S R27E Section 2 Proposed Recycling Containment / Proposed Recycling Facility Appendix 2 / Figure 3 – Permanent Residences and Institutions, Wetlands




Chevron USA Inc. T26SR27 Section 2 Proposed Recycle Containment / Appendix 2/ Figure 4: Domestic Stock Water Supply



Chevron USA Inc. T26S R27E Sect 2 Recycle Containment, Appendix 2 / Figure 5 : Municipal Boundaries and Fresh Water Fields



Chevron USA Inc. T26S R27E Sec. 2 Recycling Containment, Appendix 2 / Figure 6 : Cave Karst Features



Chevron U.S.A. Inc.

Hayhurst New Mexico T26S R27E Section 2 Recycling Containment and Facility

Appendix 2 – Recycling Containment Figures



Hayhurst Section 2 Hydraulic Fracturing Ponds

Eddy County, New Mexico

August 2017

Report of Geotechnical Study Hayhurst Section 2 Hydraulic Fracturing Ponds

Eddy County, New Mexico

Prepared for:

Mr. Ruben Kopara
Chevron North America Exploration and Production
Company

6301 Deauville Blvd, Midland, Texas 79706 Phone: (432) 687-7215

Prepared by:

Tetra Tech

4000 North Big Spring Street, Suite 401 Midland, Texas 79705 Phone (432) 682-4559; Fax (432) 682-3946 **Texas Registered Engineering Firm 3924**

Tetra Tech Project No. 2026 MD St 848

Thomas A. Charlet Principal Engineer C. P. 27 17 Principal Engineer C. P. 27 17

Reviewed by: Don Grahlherr, P.E. Vice President

THE THOUSANT

August 2, 2017

TABLE OF CONTENTS

EXEC	UTIVE	SUMMARY	ii		
1.0	PUR	POSE AND SCOPE OF STUDY	1		
2.0	SITE	CONDITIONS	3		
3.0	PRO	POSED DEVELOPMENT	4		
4.0	GEOLOGIC CONDITIONS				
5.0	EXPLORATORY SOIL BORINGS				
6.0	SUBS	SURFACE CONDITIONS	7		
7.0	ENGI	NEERING ANALYSES AND RECOMMENDATIONS	8		
	7.1	Primary Geotechnical Considerations	8		
	7.2	Site Preparation	8		
	7.3	Excavation and Embankment Slopes	8		
	7.4	Fill Placement and Compaction	9		
	7.5	Proof Rolling	10		
	7.6	Geomembrane Liner Protection	11		
	7.8	Freeboard	11		
	7.9	Settlement of Subgrade and Embankment Materials	11		
	7.10	Permitting	11		
8.0	CONC	CLUSIONS	12		
9.0	REFE	RENCES	13		
10.0	LIMIT	ATIONS	14		

EXECUTIVE SUMMARY

Chevron North America Exploration and Production Company (Chevron) plans to construct hydraulic fracturing ponds at the Hayhurst, New Mexico, Section 2 property located in Eddy County, New Mexico. Chevron will construct two separate ponds, with a capacity of approximately 350,000 barrels (bbl) each to service well drilling operations. The ponds will be designed with a double liner and a leak detection system. The floor of each pond will be sloped to a sump where fluids can be collected, sampled, and pumped if needed.

The purposes of this study were to obtain information on subsurface conditions, and to provide geotechnical design criteria for the construction of the proposed ponds. The general site location is shown on the Site Location Map, Figure 1 and Topographic Map (Figure 2).

Between May 16th and 19th, 2017, Tetra Tech and a subcontractor mobilized to the site with a truck-mounted drilling rig to drill five (5) exploratory soil borings to identify subsurface conditions and collect samples. Borings B-1 and B-4 were drilled to a depth of approximately 45 feet below the existing ground surface (bgs). Borings B-2 and B-3 were drilled to a depth of approximately 40 feet bgs. Boring B-5 was drilled to a depth of approximately 73 feet. Water was encountered at approximate depths of 31, 28, and 31 feet (bgs) in B-1, B-4, and B-5 respectively, and rose to depths of 26, 26, and 29 feet when checked prior to backfilling the boreholes one to two days following the initial drilling. New Mexico Oil Conservation Division Rules published in the New Mexico Administrative Code (NMAC) have specific siting requirements for "pits" (ponds), associated with oil and gas exploration and production, which are within specified proximities to groundwater. A hydrogeological study to meet the requirements of the NMAC should be performed to determine whether the groundwater encountered is a perched layer or a continuous water bearing feature. Approximate locations of the borings are shown on Figure 4.

The borings encountered 3½ to 8½ feet of loose to very dense sand and silt over naturally cemented soil. The cemented soil extended to the maximum depth drilled of 40 feet in boreholes B-2 and B-3.Relatively less cemented soil was encountered starting at depths of 23.5, 28, and 33 feet, and continued to depths of 38.5, 40, and 60 feet respectively in B-1, B-4, and B-5 (located in the southern and central portions of the site). The poorly cemented layer continued to the maximum depth drilled of 45 feet in B-1. Strongly cemented soil was encountered in B-4 and B-5 to the maximum depths drilled of 45 and 73 feet respectively.

Review of mapping by the U.S. Geological Survey (Figure 3) indicates that the Rustler Formation, which is a carbonate based sedimentary rock with evaporates present, underlies the site, and can be prone to karst formation and dissolution leaving voids. No voids were encountered during our investigation, however this does not ensure that voids do not exist beneath the proposed site. Tetra Tech recommends that Chevron consider additional investigation to determine more conclusively if voids exist beneath the site.

Additional investigation and construction recommendations for development of the site are provided in the body of this report.

We have prepared this executive summary solely to provide a general overview, and it should not be used for any purpose except that for which it was intended. We recommend detailed review of the entire report for information about our findings, recommendations and other concerns related to geotechnical conditions for the site.


1.0 PURPOSE AND SCOPE OF STUDY

Chevron plans to construct hydraulic fracturing ponds at the Hayhurst New Mexico, Section 2 property located in Eddy County, New Mexico. Chevron will construct two ponds at the site. Each pond will have an approximate operational capacity of 350,000 barrels (bbls) and will service well drilling operations. We understand the hydraulic fracturing ponds will be designed with a double liner and a leak detection system. The bottom of the pond will be sloped and equipped with a sump and access port/riser at the low point of the floor of the pond.


The scope of the study for this project included the following.


- 1) New Mexico 811 Utility locate request;
- 2) Mobilize a CME 75 drilling rig to drill four (4) borings to a depth of 40 or 45 feet and one (1) boring to a depth of 73 feet to look for evidence of groundwater;
- 3) Perform Standard Penetration Tests (SPT) at every 5 or 10-foot interval to evaluate soil consistency and collect soil samples for evaluation;
- 4) Backfill borings with soil cuttings after completion of drilling and 24-hour measurements, as required; and
- 5) Provide geotechnical engineering design criteria and recommendations and prepare a geotechnical report.

The general location of the site is shown on the Site Location Map, Figure 1 and Topographic Map, Figure 2.



Joel Peters Path L KCADDVP1212C-MDV008481Ch 7/10/2017 2 01 39 PM User





2.0 SITE CONDITIONS

The site for the proposed hydraulic fracturing pond is identified as the Hayhurst Section 2 site. It is located adjacent to unpaved roads, 12½ miles southwest of Malaga, New Mexico in Eddy County at the intersection of County Road 775 and Whites City Road. GPS coordinates recorded at the site are 32.067930N and 104.167640W.

The site was wooded with mesquite trees and wild shrubs; clearing with a bulldozer was necessary to access the boring locations at the central and north ends of the site. The site appeared to be relatively flat. Surface utilities, fences, and access roads (on the site) were not observed to be present at the time of drilling, however two underground pipeline right-of-ways were observed at the west and south ends of the site adjacent to the south and west lease roads. In addition, an abandoned underground pipeline running from the southwest to northeast direction was noted. Care was taken to ensure the borings were not located near these underground lines. Drainage streams, swales, playa, or other potential issues were not observed. The existing ground surface appeared to be loose but it adequately supported the drilling rig during drilling. The immediate surrounding property was undeveloped.

3.0 PROPOSED DEVELOPMENT

Based on the information provided by Chevron via electronic mail, the proposed development will consist of two hydraulic fracturing ponds, constructed adjacent to each other, in accordance with the standards outlined in the Chevron Mid-Continent Business Unit General Standards for Brackish and Produced Water Containment Structures (MCBU General Standards) and New Mexico Oil Conservation Division (NMOCD), to service well drilling operations. Each pond will have an operational storage capacity of approximately 350,000 bbl and will be partially below ground. We understand Chevron prefers to balance cut and fill volumes using onsite soil for fill to construct the earthen berms. The ponds will be double lined and equipped with a leak detection system. The bottom of the ponds will be sloped to drain to an installed liquid leak detection sump.

4.0 GEOLOGIC CONDITIONS

Geologic mapping by the U.S. Geological Survey (USGS, 2005 and 2014) indicates the Rustler Formation is the foundation bedrock at the site (Figure 3). This sedimentary rock is primarily composed of carbonate from the Permian Period with evaporites also present. The contact with sediments of the underlying Permian Salado Formation is mapped about one mile west of the subject site.

Mapping by the Natural Resources Conservation Service (NRCS, 2017) identifies the site soils as the Reeves-Gypsum and Reeves-Reagan mapping units (Figure 4). These soils are both described as loam or clay loam derived as residuum weathered from gypsum.

The bedrock and soils described above can often be prone to karst formation and dissolution leaving voids, especially in the presence of groundwater. The size, orientation, extent and such voids is difficult to predict using conventional exploratory geotechnical drilling. Geophysical methods often provide a more effective means to identify potential karst features which can then be verified or ruled out using exploratory drilling.

Our findings of the geotechnical study are consistent with this characterization within the depths explored. No voids in the subsurface were encountered in our borings.

5.0 EXPLORATORY SOIL BORINGS

Tetra Tech drilled five (5) exploratory soil borings (B-1 through B-5) to identify subsurface conditions at the site between May 16 and 18, 2017. The boring locations were selected by a representative from Tetra Tech using a satellite image provided by Chevron. The proposed pond footprint was overlaid on the satellite image and GPS coordinates were obtained for each boring location. The boring locations were marked in the field by Tetra Tech using these GPS coordinates and a commercially available hand held GPS unit. The boring locations were cleared for drilling by comparing the proposed locations to buried utility locations marked by New Mexico 811 utility locating services. In addition, Chevron subcontractors cleared the boring locations using handheld pipeline locating instruments.

The borings were drilled by Enviro-Drill Company from Albuquerque, New Mexico using a truck mounted CME 75 drilling rig. After the necessary vegetation clearing, the ground surface was stable for the drilling rig to access the boring locations and no access issues were noted. Tetra Tech's representative was on site to observe site conditions and the drilling.

Hollow stem auger (HSA) drilling equipment was used to complete the borings. Borings B-1 and B-4 were drilled to a depth of approximately 40 feet below the existing ground surface (bgs) and borings B-2 and B-3 were drilled to a depth of approximately 45 feet bgs. Boring B-5 was drilled to an approximate depth of 73 feet bgs to investigate the presence or absence of groundwater. All borings were left open for a period of approximately 24 to 48 hours to let groundwater levels stabilize. Final water level measurements were taken in each boring after 24 or 48 hours (as applicable) and groundwater was sampled in B-5 and delivered to a commercial laboratory for purposes of analyzing for TPH, Chlorides and RCRA metals, as requested by Chevron.

Soil samples were collected using a split-spoon sampler in borings B-1 through B-4 at 5-foot intervals. In boring B-5 samples were collected at 5-foot intervals to a depth of 30 feet bgs, then the spacing interval was increased to 10-feet. Standard Penetration Tests (SPT) were performed during sampling in accordance with ASTM D 1586 where a 140-pound automatic hammer is repeatedly dropped from a height of 30 inches. The number of blows for each 6-inch increment was recorded on the logs to categorize the consistency of the soil. After drilling and sampling activities were complete the borings were backfilled with soil cuttings. The soil boring logs are presented in Appendix A, and approximate locations of the borings are shown on Figure 4.

6.0 SUBSURFACE CONDITIONS

The information from the borings indicate the subsurface conditions were relatively consistent within the area where the borings were drilled. Beneath minimal vegetation and topsoil, all five (5) borings encountered 3½ to 8½ feet of unconsolidated soil over naturally cemented soil. The cemented soil extended to the maximum depth drilled of 40 feet in boreholes B-2 and B-3 (located on the north side of the proposed site). Relatively less cemented soil was encountered starting at depths of 23.5, 28, and 33 feet, and continued to depths of 38.5, 40, and 60 feet in B-1, B-4, and B-5 (located in the southern and central portions of the site) respectively. The poorly cemented layer continued to the maximum depth drilled of 45 feet in B-1. Strongly cemented soil was encountered in B-4 and B-5 to the maximum depths drilled of 45 and 73 feet respectively. Free water appears to coincide with the relatively less cemented layers in B-1, B-4, and B-5 as described below.

A moisture content of 23.5% was measured on a sample recovered from B-4 at 3.5 feet that had a fines content (percent silt and clay sized particles) of 54.8% by mass. Standard Penetration Test (SPT) N-values in this stratum ranged from 25 bpf in B-4 at 3.5 feet to 62 blows per foot (bpf) in B-1 at 3.5 feet and 50 blows for 3 inches in B-5 at 3.5 feet. Cemented layers had in-situ moisture contents at ranged from 9.8 to 20.4% for 19 samples tested at depths of up to 45 feet. Deeper samples from B-5 at 48.5 and 58.5 feet had moisture contents of 33.1 and 28.8% respectively. Insitu dry densities ranged from 82.3 to 122.6 pounds per cubic foot (pcf). Eleven of the 22 cemented soils samples had a fines content less than 50% and were therefore classified as sand soils in accordance the Unified Soil Classification System (USCS). No consistent layering was observed among the cemented soils in relation to the fines content. Atterberg limits testing of the cemented soils indicated a liquid limit ranging from 33 to 83 and plasticity index ranging from 6 to 61. The sample from B-5 at 48.5 feet was anomalous with a much higher liquid limit of 83 and plasticity index of 61 than the rest of the cemented soils where the liquid limit ranged from 33 to 42 and the plasticity index ranged from 6 to 15. Based on these index properties three of the samples were classified as silty sand (SM) and three were classified as clayey sand (SC). The fines content of the cemented soils with 50% or more fines ranged from 50 to 92%. Atterberg limits testing of these samples indicated a liquid limit ranging from 29 to 62 and plasticity index ranging from 12 to 37. Five of the fine grained cemented soil samples were classified as low plasticity clay (CL) and two were classified as high plasticity clay (CH). N-values within this stratum ranged from 13 bpf to greater than 100 bpf with the lower N-values corresponding to clayey samples or zones where free water was prevalent.

Free water was encountered in three of the five borings at the time of drilling. Water was not encountered in borings B-2 and B-3 (both located on the northern side of the site). Depths to water at the time of drilling were 31, 28 and 31 feet in borings B-1, B-4, and B-5, respectively. Water levels rose to depths of 26, 26, and 29 feet when checked prior to backfilling the boreholes one to two days following the initial drilling. Our observations are only indicative of conditions at the time and boring locations indicated. Water levels can vary due to many factors, including seasonal changes, site topography, surface runoff, post development conditions, the layering and permeability of subsurface strata, water levels in waterways, utilities, and other factors that may not have been evident at the time this study. Long-term observations would be necessary to more accurately evaluate the groundwater behavior and fluctuations.

7.0 ENGINEERING ANALYSES AND RECOMMENDATIONS

7.1 Primary Geotechnical Considerations

The two primary concerns that could impact the proposed development are the presence of strongly cemented soil within the proposed depths of excavation and the possibility of voids due to karst/evaporite subsurface conditions.

Excavation of strongly cemented soil will be difficult for construction due to the high energy required to excavate and eventually pulverize the cemented soil into fragments small enough to use as fill as described below.

While no voids due to karst/evaporite soil and bedrock were encountered during our borehole exploration, they could exist beneath the construction site and could become evident as a result of additional loading or changes to groundwater conditions as a result of construction or through natural progression. Settlement of pond floors or sidewalls due to undetected voids could cause distress or failure of liner systems and discharge of the pond contents to the subgrade. We recommend a geophysical exploration program be considered to search for voids that may not have been identified by the exploratory drilling. Such a program was beyond the scope of the current investigation; however should Chevron decide to undertake a geophysical investigation, Tetra Tech is available to assist.

7.2 Site Preparation

To prepare the site for pond construction, an area larger than the proposed footprint by at least 10 feet in plan dimension on all sides should be stripped of vegetation, roots, organic material, existing construction materials, debris, and other unsuitable materials. A typical stripping depth is approximately 6 inches; however, the actual depth will vary and should be based on field conditions and observations. After stripping, we anticipate a moderately stable surface for support of construction equipment. Unsuitable areas (such as those with loose, wet, soft, yielding, and/or pumping subgrade) should be corrected before construction proceeds.

Obstructions that could hinder preparation of the site should also be removed, with special attention given to unknown or un-documented below ground appurtenances and any existing above and below ground flow lines. Care should be taken not to damage any existing buried utilities located within the footprint of the proposed construction. Any resulting utility trenches/excavations due to replacement or relocation of utilities should be backfilled as discussed in the Fill Placement and Compaction section of this report.

7.3 Excavation and Embankment Slopes

Based on the subsurface data, sandy soil is present to depths of 3½ to 8½ feet below the existing grade and then cemented soils were encountered. Conventional construction equipment can be used to excavate the soil, however excavation into the cemented soils will be more difficult and additional effort to excavate may be necessary. Heavy duty rock ripping equipment like a ripper mounted on a Caterpillar D8 bulldozer or equivalent may be necessary.

The earthwork contractor should review the subsurface conditions and appropriately select excavation equipment and initial slope of the excavation to minimize potential sloughing and to remain in compliance with OSHA Regulations 1926.651 and 1926.652 on excavation safety. Wetting of the exposed excavation sides to a moisture content near or slightly above optimum may be necessary to stabilize and maintain the slopes during construction.

During construction the excavation slopes should be inspected and kept under observation for safety purposes. Excavation slopes specified by OSHA are dependent on types of soil and groundwater conditions encountered. Based on our investigation the on-site soil is classified as Type C and the cemented soil can be considered to be Type B according to OSHA 1926, Subpart P, Appendix A. The contractor's "competent person" should identify the soils encountered in the excavation and refer to OSHA 1926.651 and 1926.652 to verify the conditions and classifications from our investigation and determine appropriate slopes. If deemed unstable, the excavation sides should be flattened or benched to remain in compliance. Stockpiles of soils and equipment should not be placed within a horizontal distance equal to one-half the excavation depth, from the edge of excavation. Excavations deeper than 20 feet should be designed by a Professional Engineer as recommended by OSHA.

Embankment slopes must be constructed slopes flat enough to prevent slope failures. For soil and embankment fill design parameters, an angle of internal friction of 30 degrees with no cohesion is recommended in lieu of design parameters based on shear strength testing. A compacted/improved subgrade soil unit weight of 120 pcf is appropriate. The pond will be lined and we have assumed the liner system will function to prevent development of a phreatic surface within the embankment. We understand that side slopes will be designed at 3 horizontal to 1 vertical (3H:1V), which is consistent with the New Mexico Administrate Code (NMAC) requirements for design of "pits" (or ponds) associated with oil and gas exploration and production operations and not considered temporary, which states that the maximum allowed pond embankment slope is 3H:1V for exterior slopes and 2H:1V for interior slopes. Although steeper slopes may be shown to be stable and acceptable per regulations, we recommend 3H:1V based on consideration of potential constructability issues, liner stability, seepage, and slope stability. We understand the MCBU General Standards have similar slope requirements. If Chevron would like to consider construction of slopes steeper than the 3H:1V recommended above Tetra Tech is available to conduct slope stability analysis to evaluate the feasibility of steeper slopes and liner system performance on those slopes. This analysis would be supported by slope stability modeling and hand calculations to present to the NMOCD in a variance request.

7.4 Fill Placement and Compaction

On-site soils free of rocks greater than 1-inch in diameter, organics, and debris are suitable for use as structural fill or backfill. The cemented soils will likely require additional processing beyond ripping to achieve a soil consistency and meet the maximum particle size dimension in the construction specifications. Fill and backfill should not be placed on organics or other deleterious materials such as soil or rock with soluble components such as gypsum. If additional fill is needed for construction of the embankment, imported fill should be a well-graded clayey sand (SC) or low plasticity clay (CL), or imported soils with engineering properties that are similar to on-site soils (depending on the intended use of the fill). For structural support, a uniform, granular material having 100% passing the 1-inch sieve, 30% to 70% passing the No. 4 sieve, and 3% to 15% passing the number 200 sieve is recommended. Prior to importation, samples of soils being considered as fill should be examined and evaluated by a geotechnical engineer for engineering properties to determine suitability of the material for its intended use.

The bases of fills in soil should be scarified at least 8 inches deep, moisture-conditioned or dried to within 2% of optimum moisture content, processed to a uniform condition, and then compacted to at least 95 percent of maximum dry density determined by standard Proctor (ASTM D698). For on-site and imported fill and backfill, moisture should be adjusted to within minus 1 to 3 percent above optimum moisture content as determined by standard Proctor and the soils thoroughly mixed prior to placement and compaction to provide uniform water content throughout the fill. Fill and backfill should be placed in uniform lifts of 8 inches or less in loose thickness and compacted to at least 95% of standard Proctor maximum dry density (ASTM D 698). Fill should be compacted using heavy vibratory equipment. In areas with limited space for heavy equipment, appropriate compaction equipment, such as a jumping jack or other hand tools should be used. Where smaller compacting equipment or hand tools are used, the fill lifts should be 6 inches or less in loose thickness. The contractor should select the equipment type based upon the fill soil conditions.

Placement and compaction of fill should be observed and tested by a qualified geotechnical engineer or their qualified representative during construction. Each vertical foot of compacted fill placed should be tested for compaction comparison to standard Proctor results. A minimum of one moisture/density verification test should be performed for every 5,000-square-feet of compacted area, or for every 150-lineal feet of utility trench backfill. For smaller areas, a minimum of three (3) verification tests should be conducted for every lift. Subsequent lifts should not be placed until the exposed lift has been tested to confirm compliance with the specified moisture and density. Lifts failing to meet the moisture and density requirements should be reworked to meet the required specifications prior to subsequent lifts being placed. Density and moisture verification testing is recommended to provide an indication that adequate earthwork is being performed. However, the quality of the fill and compaction is the sole responsibility of the contractor. Satisfactory verification testing is not a guarantee of the quality of the contractor's earthwork operations.

The specified moisture content must be maintained until compaction of the overlying lift, or until the cushioning sand layer or geotextile fabric and geomembrane liner are installed. Failure to maintain the specified moisture content could result in excessive soil movement resulting in embankment failure. The contractor must provide some means of controlling the moisture content (such as water hoses, water trucks, etc.). Maintaining subgrade moisture is always critical, but will require the most effort during warm, windy and/or sunny conditions.

7.5 Proof Rolling

Proof rolling of the subgrade prior to fill placement and liner installation should be used to detect areas of soft and/or pumping soil. Proof rolling should be conducted using a heavy, rubber-tired vehicle weighing at least 25 tons, with the tires inflated to the manufacturer's specified operating pressure. The entire area should be proof rolled, with each succeeding pass offset by not greater than one tire width. The geotechnical engineer or an experienced soils technician should be present during proof rolling activities to assist with the identification of unsuitable soil. Unsuitable soil should be undercut and reworked, or otherwise improved in a manner that is suitable to the design and approved by the geotechnical engineer.

7.6 Geomembrane Liner Protection

Where the exposed surface is rough, rock protrusions and sharp edges can potentially damage the geomembrane liner. Additionally an irregular foundation with voids can create localized stress points on the geomembrane liner. The subsurface conditions at this site indicate sandy soils to a depth of 3½ to 8½ feet deep which should suffice for geomembrane liner foundation, however, the pond bottom will likely be in the underlying cemented soil with rock-like protrusions and surface irregularities. If the protrusions are greater than ½-inch or if voids greater than 2 inches deep will exist below the liner, a cushion, such as a fine grained sand layer, approximately 6 inches thick or a properly designed cushion geotextile should be used to reduce the risk of damage to the liner. Liner requirements must meet those presented in the New Mexico Administrative Code (NMAC).

7.8 Freeboard

An important aspect of embankment stability and performance is maintaining the appropriate freeboard (the vertical distance from the water surface to the crest of the embankment). If the freeboard is insufficient, the embankment could overtop, leading to excessive erosion and possible failure. The NMAC requirements for operation of "pits" (or ponds) associated with oil and gas exploration and production and MCBU General Standards require a minimum freeboard of three feet which must be maintained at all times.

7.9 Settlement of Subgrade and Embankment Materials

Settlement of embankment material is another important aspect of embankment stability and total fluid storage potential over time. It is anticipated that the embankments will be constructed of fill consisting of on-site material or imported fill. The on-site sandy soils have a relatively low potential for post-construction settlement. Construction recommendations from above for subgrade proof rolling, subgrade improvements, and fill placement will reduce the amount of settlement. Due to the sandy nature of the soils, most of the anticipated or potential settlement within the embankments and under the embankments should occur during construction.

7.10 Permitting

If applicable, a permit application should be filed with the NMOCD in accordance with NMAC regulations prior to construction. Construction and installation in accordance with NMOCD regulations found in the NMAC and the design drawings and construction specifications is recommended. The NMOCD may require notification prior to construction and prior to operation of the pond.

8.0 CONCLUSIONS

The Tetra Tech investigation identified two potential issues that should be addressed prior to development of the proposed hydraulic fracturing ponds at the Hayhurst Section 2 site. The first is that water in the boreholes stabilized at depths of 26, 26, and 29 feet in borings 1, 4, and 5, respectively (when measured one to two days following the initial drilling). New Mexico Oil Conservation Division rules in the NMAC have specific siting requirements for "pits" (ponds), associated with oil and gas exploration and production, which are within specified proximities to groundwater. A hydrogeological study to meet the requirements of the NMAC should be performed to determine whether the water encountered is a perched layer or a continuous water bearing feature.

Another potential issue is based on review of mapped geology at the site which indicated a bedrock formation that is susceptible to formation of voids, especially in the presence of groundwater, where dissolution of the carbonate and evaporite minerals can occur. Voids can be exacerbated by loading or changes in hydrology that could occur as a result of the pond construction. Collapse of soils overlying such voids could damage the ponds or liner system and result in release of stored fluids to the environment.

Geophysical methods can be an effective means to identify potential voids that may exist at depth but are not readily identifiable by exploratory drilling. If geophysical methods suggest that voids may exist, additional exploratory drilling might be needed to confirm the presence of voids.

Tetra Tech can assist Chevron with further analyses of the Hayhurst Section 2 site should it be of interest. We can prepare a scope of work and cost estimate for Chevron review prior to authorization of these tasks.

Following further understanding of the groundwater and presence of subsurface voids, the proposed hydraulic fracturing ponds can be constructed in accordance with MCBU General Standards and NMOCD regulations, as described herein. Construction should be conducted in accordance with MCBU General Standards, NMOCD regulations, the engineering drawings and specifications prepared by Tetra Tech, and this report.

9.0 REFERENCES

Chevron Mid-Continent Business Unit MCBU General Standards for Brackish and Produced Water Containment Structures, DRAFT version (MCBU General Standards)

U.S. Department of Agriculture, Natural Resources Conservation Service (NRCS, 2017). Web Soil Survey. http://websoilsurvey.nrcs.usda.gov/app/WebSoilSurvey.aspx. Accessed July 10, 2017.

United States Geological Survey (USGS, 2005). Preliminary Integrated Geologic Map for the United States Central States. Open-File Report 2005-1351

United States Geological Survey (USGS, 2014). Karst in the United States: A Digital Map Compilation and Database. Open-File Report 2014-1156. Weary, D.J., and Doctor, D.H.

10.0 LIMITATIONS

This report was prepared from data developed during our field exploration, laboratory testing, and engineering judgment. Our design recommendations were based on subsurface data and our experience with similar projects and subsurface conditions. Our borings were located to obtain a reasonable interpretation of subsurface conditions. It should be noted that the borings were widely spaced and variation in the subsoils between borings is likely.

A qualified, experienced geotechnical engineer or their designated representative should observe the construction to look for evidence that would indicate differences in subsurface conditions from those described in this report. If any information becomes available that would alter our assumptions, conclusions or recommendations, the opinions presented in this report should be considered invalid until we have been contacted to review our recommendations based on the new information. The geotechnical engineer should review plans and specifications during the design. Placement and compaction of engineered fill, backfill, subgrade and other fills should be observed and tested by a representative of a Construction Materials Testing (CMT) firm during construction, and Tetra Tech should be retained to review these data.

We believe this study was conducted in a manner consistent with that level of skill and care ordinarily used by members of the profession currently practicing under similar conditions in the locality of this project. No warranty, express or implied, is made. If we can be of further service in discussing the contents of this report or in the analysis of the planned project from the geotechnical point of view, please contact us.

APPENDIX A EXPLORATORY BORING LOGS

TETRA TECH

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-1

PAGE 1 OF 2

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/16/2017

GROUND ELEVATION: NA

METHOD: HSA

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.067930 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.167640 W

DRILLED BY: Juan Uribe

Notes: Not Recorded

O DEPTH	SAMPLE TYPE	N Value	TESTS	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION
5	ss	62				Loose to Medium Dense, Brown, Sub Angular Medium Grained <u>SAND</u> 3.5 Very Dense, Pink, Fine Grained <u>SAND</u>
10	ss	50/5"	MC = 19.8% Fines = 36.1%			8.5 Very Dense, Pink, Weakly Cemented Fine Grained <u>SAND</u> , with < 20% Fine Gravel, Calcareous, Moist
15	ss	50/4"				
20	X ss	50/1"	MC = 13.2%	SM		23.5 Very Dense to Medium Dense, Dark Provin Medicable Occurs 15: 61:
30	ss	13	DD = 106.1 pcf LL = 37 Fines = 49.5%			Very Dense to Medium Dense, Dark Brown, Moderately Cemented Fine Silty and Clayey <u>SAND</u> , Increasing Plasticity with Depth, Moist to Wet Water depth 48 hours after drilling Water depth at the end of drilling
35	ss	15	MC = 18.8% DD = 102.3 pcf LL = 33 Fines = 47.4%	SC		☑ Water depth during drilling
40	ss	13				



BOREHOLE ID: B-1

PAGE 2 OF 2

CLIENT Chevron PROJECT NAME Hayhurst NM, Sec. 2 Frac Pond PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico SAMPLE TYPE GRAPHIC LOG DEPTH (ft) N Value U.S.C.S. **TESTS** MATERIAL DESCRIPTION Stiff to Very Stiff, Dark Brown, Low Plasticity CLAY with Sand, Moist MC = 17.7% DD = 122.6 pcf LL = 29 Fines = 57.7% 46 SS CL 45 Borehole terminated at 45.0 BOREHOLE/TP/WELL - VECTOR HAYHURST.GPJ LAB SUMMARY.GDT 7/13/17



BOREHOLE ID: B-2

PAGE 1 OF 1

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/18/2017

GROUND ELEVATION: NA

METHOD: HSA

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.069966 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.167700 W

DRILLED BY: Juan Uribe

Notes: Not Recorded

O DEPTH	SAMPLE TYPE	N Value	TESTS	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION
 	× ss	50/5"	MC = 14.1%			Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND 3.5 Very Dense, Pink, Strongly Cemented Medium Grained SAND, with <50%
5	× ss	50/2"	Fines = 41.9%			Quartz Fragments, Moist Hard, Red, SILT TO CLAY Fines and Plasticity Increasing with Depth, with Sand, with <50% Quartz Fragments, Calcareous, Moist
15	ss	50/3"	MC = 15.6% DD = 96.0 pcf LL = 44 Fines = 50.3%	ML		
20	ss	50/4"				
<u>25</u>	X ss	50/3"				
30	X ss	50/4"	MC = 20.4% DD = 93.1 pcf LL = 53 Fines = 59.2%	СН		Very Dense, Pink, Strongly Cemented Medium Grained <u>SILTY SAND</u> , with >50% Quartz Fragments, Calcareous, Moist
35	× ss	50/2"				
-	X ss	50/4"	MC = 19.5% LL = 42 Fines = 38.8%	SM		



BOREHOLE ID: B-3

PAGE 1 OF 1

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec. 2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/18/2017

CONSULTANT: Tetra Tech, Inc.

DRILLING CONTRACTOR: Enviro Drill

Notes: Not Recorded

GROUND ELEVATION: NA METHOD: HSA

LATITUDE: 32.070140 N

LONGITUDE: 104.165980 W

LOGGED BY: Clint Merritt and Raj Meruva

DRILLED BY: Juan Uribe

O DEPTH	SAMPLE TYPE	N Value	TESTS	GRAPHIC LOG	MATERIAL DESCRIPTION
 	-				Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND
5 -	ss	50/5"	MC = 13.8% Fines = 52.9%		Very Dense, Pale Red, Weakly Cemented Medium Grained Sandy Silty <u>CLAY</u> with <10% Small Angular Limestone Fragments, Moist
10 - -	ss	50/5"		1	3.0
15	× ss	50/3"			Hard, Yellowish Brown, Strongly Cemented SILTY CLAY, with < 20% Small Angular Limestone Fragments, Slight odor, Calcareous, Slightly Moist
20	× ss	50/4"	MC = 9.8% Fines = 85.6%		
25					
30		į			
35					
40				40	

TETRA TECH

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-4

PAGE 1 OF 2

CLIENT Chevron

Notes: Not Recorded

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/17/2017

GROUND ELEVATION: NA

METHOD: HSA

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.068070 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.165660 W

DRILLED BY: Juan Uribe

1.000	es: Not Rec	oraca			٠	
о ОЕРТН (ft)	SAMPLE TYPE	N Value	TESTS	U.S.C.S.	GRAPHIC	
	-					Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND
5	X ss	25	MC = 23.5% Fines = 54.8%			Medium Dense, Pink, Weakly Cemented Medium Grained SILT, Calcareous, Moist
10	× ss	50/2"				8.5 Hard, Red, Strongly Cemented Low Plasticity <u>CLAY</u> , with Sand, Calcareous, Moist
15	ss	50/2"	MC = 16.5% DD = 96.1 pcf LL = 37 Fines = 61.9%	CL		
20	× ss	50/2"				20.0 Very Dense, Red, Moderately Cemented Medium Grained Silty Clayey <u>SAND</u> , with < 20% Gypsum Fragments, Moist to Wet
25	× ss	50/4"	MC = 10.0% Fines = 43.2%			▼ Water depth 48 hours after drilling
30	ss	20				28.0 ∑ Water depth during drilling Very Stiff to Hard, Red, Low Plasticity <u>CLAY</u> , with Sand, Moist
30	X ss	26	MC = 15.5% DD = 113.9 pcf LL = 29 Fines = 92.1%	CL		
40	ss	35				Freestanding water



BOREHOLE/TP/WELL - VECTOR HAYHURST.GPJ LAB SUMMARY.GDT 7/13/17

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-4

PAGE 2 OF 2

CLIENT Chevron PROJECT NAME Hayhurst NM, Sec.2 Frac Pond PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico SAMPLE TYPE GRAPHIC LOG DEPTH (ft) N Value U.S.C.S. **TESTS** MATERIAL DESCRIPTION Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist (continued) 50/1" MC = 15.1% LL = 30 Fines = 88.6% SS CL 45 45.0 Borehole terminated at 45.0

TETRA TECH

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-5

PAGE 1 OF 2

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/17/2017

GROUND ELEVATION: NA

METHOD: HSA

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.069030 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.166890 W

DRILLED BY: Juan Uribe

Notes: Not Recorded

O DEPTH	SAMPLE TYPE	N Value	TESTS	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION
5	× ss	50/3"	MC = 17.0% Fines = 19.3%			Loose to Medium Dense, Brown, Sub Angular Medium Grained <u>SAND</u> 3.5 Very Dense, Pink, Strongly Cemented Medium Grained <u>SAND</u> , Calcareous, Moist
10	× ss	50/4"	MC = 15.8% DD = 99 8 pcf LL = 42 Fines = 44.4%	SM		Very Dense, Pale Red, Strongly Cemented Medium Grained, Silty to Clayey SAND with > 40% Gypsum/Quartz Fragments, Calcareous, Moist
15	× ss	50/4"	MC = 15.9%	- 00		
20	× ss	50/4"	DD = 114.2 pcf LL = 46 Fines = 49.7% MC = 16.5% Fines = 25.9%	SC	2	Hard Pink High Photisity CLAV 11. 0
30	SS	50/3"	MC = 20.3% DD = 96.6 pcf LL = 62 Fines = 51.5%	СН		Hard, Pink, High Plasticity CLAY with Sand, Calcareous, Wet Water depth 22.5 hours after drilling Water depth during drilling
35	ss	49			3	Very Dense to Medium Dense, Reddish Brown, Moderately Cemented Medium Grained <u>CLAYEY SAND</u> with > 30% Quartz Fragments, with Lenses of Clay, High Plasticity, Slightly Wet
40	ss	49				



BOREHOLE ID: B-5


PAGE 2 OF 2

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec. 2 Frac Pond

PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico

DEPTH (ft)	SAMPLE TYPE	N Value	TESTS	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION
45						Very Dense to Medium Dense, Reddish Brown, Moderately Cemented Medium Grained <u>CLAYEY SAND</u> with > 30% Quartz Fragments, with Lenses of Clay, High Plasticity, Slightly Wet (continued)
50	ss	25	MC = 33.1% DD = 82.3 pcf LL = 83 Fines = 39.2%	sc		
55						
60	⊠ ss	50/3"	MC = 28.8% LL = 45 Fines = 56.3%	CL	60.0	Very Dense, Reddish brown, Clayey, Strongly Cemented Medium Grained SAND , with > 40% Quartz, Wet and Muddy
65	× ss	50/1"			73.0	
					(3) (3.0	Borehole terminated at 73.0



DISCLAIMER: At this time, C. H. Fenstermaker & Associates, L.L.C. has not performed nor was asked to perform any type of engineering, hydrological modeling, flood plain, or "No Rise" certification analyses, including but not limited to determining whether the project will impact flood hazards in connection with federal/FEMA, state, and/or local laws, ordinances and regulations. Accordingly, Fenstermaker makes no warranty or representation of any kind as to the foregoing issues, and persons or entities using this information shall do so at their own risk.

Į,

Please be advised, that while reasonable efforts are made to locate and verify pipelines and anomalies using our standard pipeline locating equipment, it is impossible to be 100 % effective. As such, we advise using caution when performing work as there is a possibility that pipelines and other hazards, such as fiber optic cables, PVC pipelines, etc. may exist undetected on site.

NOTE

Many states maintain information centers that establish links between those who dig (excavators) and those who own and operate underground facilities (operators). It is advisable and in most states, law, for the contractor to contact the center for assistance in locating and marking underground utilities. For guidance: New Mexico One Call System - www.nmonecall.org.

FOR THE EXCLUSIVE USE OF CHEVRON U.S.A. INC.

I, Robert L. Lastrapes, Professional Surveyor, do hereby state this plat is true and correct to the best of my knowledge.

Not to be used for construction, bidding recordation, conveyance, sales, or as the basis for the issuance of a permit.



Robert L. Lastrapes Registration No. 23006 SURFACE USE PLAT

PAGE 2 OF 2

CHEVRON U.S.A. INC.

PROPOSED PADS GRAVITAS 2 STATE SWD NO. 2 WELL SECTION 2, T26S-R27E


Ш	λ G G	EDDY COUNTY, NEW MEXICO	EXICO
DRAWN BY: TBD		REVI	REVISIONS
PROJ. MGR.: GDG	No. 1	No. 1 DATE: 1/28/2016	REVISED BY: GDG
DATE: 12/17/2015	No. 2	No.2 DATE: 06/03/2016	REVISED BY: BOR


C. H. Fenstermaker & Associates, L.L.C 135 Regency Sq. Lafayette, LA 70508 Ph. 337-237-2200 Fax. 337-232-3299 www.fenstermaker.com


FRMAKER

FENST

FILENAME: T.\2015\2153364\DWG\GRAVITAS 2 STATE SWD 2 and FACILITY SUP.dwg







Chevron

Hayhurst New Mexico T26S R27E Section 2 U.S.A. Inc. | Recycling Containment and Facility

Appendix 3 – Recycling Containment Groundwater Boring Log



September 7, 2017

Mr. Ruben Kopara Chevron North America Exploration and Production Company 6301 Deauville Blvd, Midland, Texas 79706

Subject:

Addendum to Geotechnical Investigation Report

Hayhurst Section 2 Hydraulic

Fracturing Ponds

Eddy County, New Mexico

Dear Mr. Kopara:

On August 2, 2017, Tetra Tech published a report of our geotechnical study for the referenced site where Chevron intends to construct two earthen impoundments with capacities of approximately 350,000 bbl each to service well drilling operations. Subsequent to that investigation and report, Chevron moved the location of the proposed pits to an adjacent area immediately north of the previous site. On August 17 and 18, 2017, Tetra Tech returned to the site and drilled three additional borings in the new area to investigate subsurface conditions. The locations of the borings are shown on the attached Figure 1. Previous borings are labeled B-1 through B-5; the more recent borings are labeled B-6 through B-8.

Borings B-6 through B-8 encountered 21 to 30 feet of medium dense to dense sand over hard clay with cemented lenses. Standard Penetration Tests (SPT) in the sand had values or blow counts (N) ranging from 23 blows per foot to 50 blows for 2 inches; blow counts in the clay ranged from 9 blows per foot (in B-8 at the contact with the overlying sand) to 50 blows for 2 inches. In general, the density of the soils increases with depth based on the SPT values. Free water was not encountered in the borings.

The additional borings indicate that the subsurface conditions on the northern part of the site are consistent with those encountered to the south. The soils to the south have a higher silt and clay content, but blow counts are similar. The borings to the north have a lesser degree of cementation at shallow depth, which may simplify earthwork. No voids or carbonate rocks or deposits were encountered.

Recommendations made in our geotechnical report for the original site remain valid for the revised pit location. Our report: *Hayhurst, Section 2 Hydraulic Fracturing Ponds, Eddy County New Mexico*, dated August 2, 2017, should be carefully reviewed in its entirety during design and construction of the pits at the proposed revised location. In particular, we reiterate that although evidence of voids or karst terrain were not encountered, the site is located in a karst-prone geologic area and voids that were not observed in our widely spaced borings could exist under portions of the site. We recommend Chevron consider geophysical investigation to more conclusively determine if voids could exist below portions of the site.

Please contact the undersigned with any questions or comments you may have regarding this addendum letter or our recommendations for these sites.

Sincerely,


TETRA TECH, INC.

Thomas A. Chapel, CPG PE 97117
Principal Geotechnical Engineer
ONAL ENGIN

18861

Reviewed by

Don Grahlherr, PE Vice President



ATTACHMENT A

BORING LOGS



Fax: 432-682-3946

BOREHOLE ID: B-1

PAGE 1 OF 2

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec. 2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/16/2017

GROUND ELEVATION: NA

METHOD:

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.067930 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.167640 W

DRILLED BY: Juan Uribe

Notes: Not Recorded

BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17

Note	s: Not Re	corded				
O DEPTH	SAMPLE TYPE	BLOW COUNTS	TESTS	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION
						Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND
5	ss	62				3.5 Very Dense, Pink, Fine Grained <u>SAND</u>
 10	ss	50/5"	MC = 19.8% Fines = 36.1%			8.5 Very Dense, Pink, Weakly Cemented Fine Grained <u>SAND</u> , with < 20% Fine Gravel, Calcareous, Moist
	V	50/4"				
15 	X ss					
20	ss	50/1"				
	X ss	50/3"	MC = 13.2%	SM		23.5 Very Dense to Medium Dense, Dark Brown, Moderatoly Competed Fine City.
25	/\		DD = 106.1 pcf LL = 37 Fines = 49.5%			Very Dense to Medium Dense, Dark Brown, Moderately Cemented Fine Silty and Clayey <u>SAND</u> , Increasing Plasticity with Depth, Moist to Wet Water depth 48 hours after drilling Water depth at the end of drilling
30	ss	13				
35	ss	15	MC = 18.8% DD = 102.3 pcf LL = 33	sc		- water depth during drining
	1		LL = 33 Fines = 47.4%			
40	ss	13				



BOREHOLE/TPAMELL - TT HAYHURST GPJ LAB SUMMARY GDT 8/24/17

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-1

PAGE 2 OF 2

CLIENT Chevron PROJECT NAME Hayhurst NM, Sec. 2 Frac Pond PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico **BLOW COUNTS** SAMPLE TYPE GRAPHIC LOG DEPTH (ft) U.S.C.S. **TESTS** MATERIAL DESCRIPTION

Very Dense to Medium Dense, Dark Brown, Moderately Cemented Fine Silty and Clayey <u>SAND</u>, Increasing Plasticity with Depth, Moist to Wet (continued) Stiff to Very Stiff, Dark Brown, Low Plasticity <u>CLAY</u> with Sand, Moist Stiff to Very Stiff, Dark Brown, Low Plasticity <u>CLAY</u> with Sand, Moist (continued) MC = 17.7% DD = 122.6 pcf LL = 29 Fines = 57.7% 46 SS CL Borehole terminated at 45.0



BOREHOLE ID: B-2

PAGE 1 OF 1

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/18/2017

GROUND ELEVATION: NA

METHOD:

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.069966 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.167700 W

DRILLED BY: Juan Uribe

Notes: Not Recorded

O DEPTH	SAMPLE TYPE	BLOW COUNTS	TESTS	U.S.C.S.	GRAPHIC	MATERIAL DESCRIPTION
-						Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND
5	X ss	50/5"	MC = 14.1% Fines = 41.9%		1	Very Dense, Pink, Strongly Cemented Medium Grained <u>SAND</u> , with <50% Quartz Fragments, Moist
10	ss	50/2"				Hard, Red, SILT TO CLAY Fines and Plasticity Increasing with Depth, with Sand, with <50% Quartz Fragments, Calcareous, Moist
15	ss	50/3"	MC = 15,6% DD = 96,0 pcf LL = 44 Fines = 50,3%	ML		
20	ss	50/4"				
25	X ss	50/3"				
30	ss	50/4"	MC = 20.4% DD = 93.1 pcf LL = 53	СН		30.0
35	× ss	50/2"	Fines = 59.2%			Very Dense, Pink, Strongly Cemented Medium Grained SILTY SAND, with >50% Quartz Fragments, Calcareous, Moist
40	SS	50/4"	MC = 19.5% LL = 42 Fines = 38.8%	SM		0.0
	İ	_	Fines = 38.8%		Y:X 4	Borehole terminated at 40.0



BOREHOLE ID: B-3

PAGE 1 OF 1

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION _Eddy County, New Mexico

DATE(S) OF DRILLING: 05/18/2017

GROUND ELEVATION: NA

METHOD:

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.070140 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.165980 W

DRILLED BY: Juan Uribe

Notes: Not Recorded

BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17

		Г -			
o DEPTH (ft)	SAMPLE TYPE	BLOW COUNTS	TESTS	GRAPHIC LOG	MATERIAL DESCRIPTION
		50/5"	MC = 13.8%	3.5	Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND
5	ss ss	50/5"	MC = 13.8% Fines = 52.9%		Very Dense, Pale Red, Weakly Cemented Medium Grained Sandy Silty <u>CLAY</u> with <10% Small Angular Limestone Fragments, Moist
15	× ss	50/3"		13.0	Hard, Yellowish Brown, Strongly Cemented <u>SILTY CLAY</u> , with < 20% Small Angular Limestone Fragments, Slight odor, Calcareous, Slightly Moist
20	× ss	50/4"	MC = 9.8% Fines = 85.6%		
25					
30					
35					·
40				40.0	Borehole terminated at 40.0
					Doleriole terrifficated at 40.0



BOREHOLE ID: B-4

PAGE 1 OF 2

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/17/2017

CONSULTANT: Tetra Tech, Inc.

DRILLING CONTRACTOR: Enviro Drill

Notes: Not Recorded

GROUND ELEVATION: NA

LATITUDE: 32.068070 N

LONGITUDE: 104.165660 W

METHOD:

LOGGED BY: Clint Merritt and Raj Meruva

DRILLED BY: Juan Uribe

TESTS TE							
SS 50/2" MC=18.5% DD=18.1 pc Fines = 61.9% MC=10.0% Fines = 43.2% Weter depth 48 hours after drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist Water depth 48 hours after drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist		SAMPLE TYPE	BLOW COUNTS	TESTS	U.S.C.S.	GRAPHIC LOG	
Medium Dense, Pink, Weakly Cemented Medium Grained SILT, Calcareous, Moist Medium Dense, Pink, Weakly Cemented Medium Grained SILT, Calcareous, Moist Hard, Red, Strongly Cemented Low Plasticity CLAY, with Sand, Calcareous, Moist Very Dense, Red, Moderately Cemented Medium Grained Silty Clayey SAND. Very Dense, Red, Moderately Cemented Medium Grained Silty Clayey SAND. With < 20% Gypsum Fragments, Moist to Wet Water depth 48 hours after drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist		-					Loose to Medium Dense, Brown, Sub Angular Medium Grained <u>SAND</u>
Hard, Red, Strongly Cemented Low Plasticity CLAY, with Sand, Calcareous, Moist SS 50/2" MC = 16.5% DD = 96.1 pd	- -	X ss	25	MC = 23.5% Fines = 54.8%			Medium Dense, Pink, Weakly Cemented Medium Grained SILT, Calcareous
Hard, Red, Strongly Cemented Low Plasticity CLAY, with Sand, Calcareous, Moist 15				1 11103 - 0-7,070	-		Moist South Charles Street, Calcareous,
Hard, Red, Strongly Cemented Low Plasticity CLAY, with Sand, Calcareous, Moist 15							8.5
SS 50/2" 20.0 Very Dense, Red, Moderately Cemented Medium Grained Silty Clayey SAND. with < 20% Gypsum Fragments, Moist to Wet Water depth 48 hours after drilling 28.0 ▼ Water depth during drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist	10	× ss	50/2"				Hard, Red, Strongly Cemented Low Plasticity CLAY with Sand, Calcareous
SS 50/2" 20.0 Very Dense, Red, Moderately Cemented Medium Grained Silty Clayey SAND. with < 20% Gypsum Fragments, Moist to Wet Water depth 48 hours after drilling 28.0 ▼ Water depth during drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist	-						
SS 50/2" 20.0 Very Dense, Red, Moderately Cemented Medium Grained Silty Clayey SAND. with < 20% Gypsum Fragments, Moist to Wet SS 50/4" MC = 10.0% Fines = 43.2% Water depth 48 hours after drilling 28.0 Water depth during drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist	15	ss	50/2"	MC = 16.5% DD = 96.1 pcf	CL		
20.0 Very Dense, Red, Moderately Cemented Medium Grained Silty Clayey SAND. with < 20% Gypsum Fragments, Moist to Wet SS 50/4" MC = 10.0% Fines = 43.2% Water depth 48 hours after drilling 28.0 Water depth during drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist				LL = 37 Fines = 61.9%			
20.0 Very Dense, Red, Moderately Cemented Medium Grained Silty Clayey SAND. with < 20% Gypsum Fragments, Moist to Wet SS 50/4" MC = 10.0% Fines = 43.2% Water depth 48 hours after drilling 28.0 Water depth during drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist			500"				
SS 50/4" MC = 10.0% Fines = 43.2% Water depth 48 hours after drilling 28.0 \(\superscript{\substraction}\) Water depth during drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist	20	35	30/2		_		
Water depth 48 hours after drilling 28.0 Water depth during drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist							with < 20% Gypsum Fragments, Moist to Wet
Water depth 48 hours after drilling 28.0 Water depth during drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist SS 26 MC=15.5% DD=113.9 pcf LL=29 Fines=92.1%	 _ 25	× ss	50/4"	MC = 10.0% Fines = 43.2%			
SS 20 Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist SS 26 MC = 15.5% DD = 113.9 pcf LL = 29 Fines = 92.1%							▼ Water depth 48 hours after drilling
SS 26 MC = 15.5% DD = 113.9 pcf LL = 29 Fines = 92.1%			20				28.0 Very Stiff to Hard, Red, Low Plasticity CLAY with Sord, Meiet
SS 26 MC = 15.5% DD = 113.9 pcf LL = 29 Fines = 92.1%	30	X ss					Service state, 1866, 2007 todatoly <u>SEA1</u> , With Sand, Worst
SS 26 MC = 15.5% DD = 113.9 pcf LL = 29 Fines = 92.1%							
LL = 29 Fines = 92.1%	35	X ss	26	MC = 15.5% DD = 113.9 pcf	CL		
				Fines = 92.1%			
			25				
SS 35 Freestanding water	40	X ss	35				



BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-4

PAGE 2 OF 2

CLIENT Chevron PROJECT NAME Hayhurst NM, Sec 2 Frac Pond PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico SAMPLE TYPE **BLOW COUNTS** GRAPHIC LOG DEPTH (ft) U.S.C.S. **TESTS** MATERIAL DESCRIPTION Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist (continued) MC = 15.1% LL = 30 Fines = 88.6% 50/1" SS CL 45 45.0 Borehole terminated at 45.0



Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-5

PAGE 1 OF 2

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/17/2017

GROUND ELEVATION: NA

METHOD:

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.069030 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.166890 W

DRILLED BY: Juan Uribe

Notes: Not Recorded

BOREHOLE/TPAMELL - TT HAYHURST.GPJ LAB SUMMARY GDT 8/24/17

O DEPTH (ft) SAMPLE TYPE	STOWN COUNTY TESTS	U.S.C.S. GRAPHIC	MATERIAL DESCRIPTION
			Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND 3.5
5	MC = 17.0% Fines = 19.3%		Very Dense, Pink, Strongly Cemented Medium Grained <u>SAND</u> , Calcareous, Moist
SS 50	MC = 15.8% DD = 99.8 pcf LL = 42 Fines = 44.4%	SM	Very Dense, Pale Red, Strongly Cemented Medium Grained, Silty to Clayey SAND with > 40% Gypsum/Quartz Fragments, Calcareous, Moist
- X SS 500	/4"		
- SS 500	/5" MC = 15.9% DD = 114.2 pcf LL = 46 Fines = 49.7%	SC	
SS 50/	MC = 16.5% Fines = 25.9%		25.0
			Hard, Pink, High Plasticity <u>CLAY</u> with Sand, Calcareous, Wet
- SS 50/	3" MC = 20.3% DD = 96.6 pcf LL = 62 Fines = 51.5%	ih /	▼ Water depth 22.5 hours after drilling ▼ Water depth during drilling
35 SS 45			Very Dense to Medium Dense, Reddish Brown, Moderately Cemented Medium Grained <u>CLAYEY SAND</u> with > 30% Quartz Fragments, with Lenses of Clay, High Plasticity, Slightly Wet
ss ⁴⁹			



BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-5

PAGE 2 OF 2

CLIENT Chevron PROJECT NAME Hayhurst NM, Sec. 2 Frac Pond PROJECT NUMBER _212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico **BLOW COUNTS** SAMPLE TYPE GRAPHIC LOG DEPTH (ft) U.S.C.S. **TESTS** MATERIAL DESCRIPTION Very Dense to Medium Dense, Reddish Brown, Moderately Cemented Medium Grained <u>CLAYEY SAND</u> with > 30% Quartz Fragments, with Lenses of Clay, High Plasticity, Slightly Wet *(continued)* 45 25 SC SS DD = 82.3 pcf LL = 83 50 Fines = 39.2% 55 MC = 28.8% 50/3' SS CL LL = 45 Fines = 56.3% 60 Very Dense, Reddish brown, Clayey, Strongly Cemented Medium Grained SAND, with > 40% Quartz, Wet and Muddy 65 50/1 SS 70 Borehole terminated at 73.0

TETRA TECH

CLIENT Chevron

30REHOLE/TPAWELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-6

PROJECT NAME _Hayhurst NM, Sec.2 Frac Pond

PAGE 1 OF 2

PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico **DATE(S) OF DRILLING: 08/17/2017** GROUND ELEVATION: NA METHOD: CONSULTANT: Tetra Tech, Inc. LATITUDE: 32.071130 N LOGGED BY: Not Recorded DRILLING CONTRACTOR: Not Recorded LONGITUDE: 104.166990 W **DRILLED BY: Not Recorded** Notes: No groundwater encountered. N values have been corrected for sampler diameter. **BLOW COUNTS** SAMPLE TYPE GRAPHIC LOG DEPTH (ft) MATERIAL DESCRIPTION 0 Medium Dense, Brown, SAND, some Organics, No Odor, Dry 29 CA Very Dense, Reddish Yellow, SAND with about 40% Small, Fine, Moderately Cemented Gravel Sandstone 49 Fragments, No Organics, No Odor, Dry CA 50/5 CA Very Dense, Yellowish Brown, Fine SAND, with about 50%, Coarse Strongly Cemented Sandstone, Gravel, with Fine Moderately Cemented Quartz Gravel, No Odor, No Organics, Dry ST 10 15 50/1 CA 20 50/3 CA 25 72 ~ 10% Coarse Strongly Cemented Chert Gravel CA 30 19 Hard, Pale Red, CLAY, with about 20% Quartz, No Organics, No Odor, Dry CA 35 ST 50/1 CA



BOREHOLE/TPAWELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fay: 432-682-3046

BOREHOLE ID: B-6

PAGE 2 OF 2

Fax: 432-682-3946 CLIENT Chevron PROJECT NAME Hayhurst NM, Sec.2 Frac Pond PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico **BLOW COUNTS** SAMPLE TYPE GRAPHIC LOG DEPTH (ft) MATERIAL DESCRIPTION Hard, Pale Red, CLAY, with about 20% Quartz, No Organics, No Odor, Dry (continued) 45 50 50.0 ST 55 60 50/2" CA 65 70 50/3" CA 75 Borehole terminated at 76.5



Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-7

PAGE 1 OF 2

CLIENT Chevron

BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 08/18/2017

GROUND ELEVATION: NA

METHOD:

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.071740 N

LOGGED BY: Not Recorded

DRILLING CONTRACTOR: Not Recorded

LONGITUDE: 104.167650 W

DRILLED BY: Not Recorded

Notes: No groundwater encountered. N values have been corrected for sampler diameter.

O DEPTH	SAMPLE TYPE	BLOW COUNTS	GRAPHIC LOG	
				Dense to Very Dense, Reddish Brown SAND, No Organics, No Odor, Dry
-	CA	27		
[-]	CA	50/5"		
5	0,1		11/	
-	CA	50/3"	13/4	7.0
-	CA	50/2"		Very Dense, Pink, <u>SAND</u> , with about 20% Weakly Cemented Quartz, No Odor, No Organics, Calcareous, Dry
10		50/4"	11	
-	CA	30/4	19	
15			1/1	
	CA	50/3"		
-				
			16.3	
20	CA	50/4"		21.0
F				Hard, CLAY, with about 60% Moderately Cemented Quartz, No Odor, No Organics, Dry
25	ST			
30				
	CA	63		
-				
		}		
35	CA	43		
40	ST			
			/	



BOREHOLE/TP/WELL - TT HAYHURST GPJ LAB SUMMARY GDT 8/24/17

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559

BOREHOLE ID: B-7 PAGE 2 OF 2

1					Fax: 432-682-3946	
		NT C				PROJECT NAME Hayhurst NM, Sec.2 Frac Pond
	PROJ	JECT N	UMBER	212C-N	1D-00848	PROJECT LOCATION Eddy County, New Mexico
ľ			\ \ \ \ \ \ \ \	T		Eddy County, New Mexico
	DEPTH (ft)	SAMPLE TYPE	BLOW COUNTS	GRAPHIC		MATERIAL DESCRIPTION
l				7	41.5	
ı						Borehole terminated at 41.5
l						
l			-			
l						
	- 1		-			
l						
l	1			1		
l	- 1					
			-			
	1			1 1		
				1 1		
	- 1					
				1 1		
				1 1		
				1		
				1 1		
				1 1		
				1 1		
				1 1		
						*
	:51					
						4
						F)
						İ
			ĺ	- 1		



Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-8

PAGE 1 OF 2

CLIENT Chevron
PROJECT NUMBER 212C-MD-00848

BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 08/18/2017

GROUND ELEVATION: NA

METHOD:

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.071940 N

LOGGED BY: Not Recorded

DRILLING CONTRACTOR: Not Recorded

LONGITUDE: 104.166430 W

DRILLED BY: Not Recorded

Notes: No groundwater encountered. N values have been corrected for sampler diameter.

O DEPTH (ft)	SAMPLE TYPE	BLOW COUNTS	GRAPHIC LOG	MATERIAL DESCRIPTION
			13	Medium Dense to Very Dense, Reddish Brown, SAND, some Organics, No Odor, Dry
-	CA	23		
	CA	50/5"	1/2	
_ 5				
F -	CA	50/4"	1/3	7.0
	CA	50/5"		Very Dense, Red, <u>SAND</u> , some Organics, No Odor, Dry
10	CA	50/5"		
	CA		16	
15				
	CA	50/5"		
			1/1	
20			164	
	CA	50/6"		
┟╶┤			1	
25	T CA	9		Stiff, Red, <u>CLAY</u> , with 30% Quartz, No Odor, No Organics, Dry
	CA			ount, red, <u>serr</u> , with 50 % Quartz, No Odor, No Organics, Dry
- +	ST			
30	31	- 10	3	30.0
<u> </u>	CA	16		Very Stiff to Hard, Red, CLAY, with 30% Quartz, No Odor, No Organics, Moist
35				
	ST			
		ŀ		
		ľ		
40	CA	50/4"		
				(Continued Next Page)



BOREHOLE/TP/WELL - TT HAYHURST GPJ LAB SUMMARY GDT 8/24/17

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559


BOREHOLE ID: B-8 PAGE 2 OF 2


				Fax: 432-682-3946				
	CLIENT Chevron				PROJECT NAME Hayhurst NM, Sec. 2 Frac Pond			
PRO	DJECT NI	MBER _	212C-N	1D-00848	PROJECT LOCATION Eddy County, New Mexico	_		
					Eudy County, New Mexico	=		
DEPTH (#)	SAMPLE TYPE	BLOW COUNTS	GRAPHIC	41,5	MATERIAL DESCRIPTION			
				11.5	Borehole terminated at 41.5	_		


Chevron U.S.A. Inc.


Hayhurst New Mexico T26S R27E Section 2 Recycling Containment and Facility


Appendix 4 – Recycling Containment Engineering Drawings











Chevron U.S.A. Inc. Hayhurst New Mexico T26S R27E Section 2 Recycling Containment and Facility

Appendix 5 – Recycling Containment Construction Specifications

CONSTRUCTION PROJECT CHEVRON N.A. E&P, MCBU HAYHURST SECTION 2 HYDRAULIC FRACTURING POND 1 AND POND 2



NDEX OF DRAWINGS

EDDY COUNTY, NEW MEXICO

- SHEET C-1 COVER SHEET

 SHEET C-2 EMBTINGS SITE CONDITIONS

 SHEET C-3 POWNT AND POWD 2 EXCLANATION PLAN

 SHEET C-4 POWNT AND POWD 2 EMCLAN GRADE STAKING PLAN

 SHEET C-4 POWNT AND POWN 2 COMPLETION PLAN

 SHEET C-5 POWNT AND POWN 2 CAPONE GRADE STAKING PLAN

 SHEET C-6 POWNT AND POWN 2 CAPONE GRADE STAKING PLAN

 SHEET C-6 SUMP CROSS-SECTION AND DETAILS

 SHEET C-6 SUMP CROSS-SECTION AND DETAILS

 SHEET C-6 SUMP CROSS-SECTION AND DETAILS

 SHEET C-6 STRISE AND COLLECTION TRENGH DETAILS

 SHEET C-6 STRISE PAN CROSS-SECTION SHEET C-6 STRISE SHEET C-6 STRISE SHEET C-6 SHEET C-6 STRISE SHEET C-6 SHEET C-6 SHEET C-6 SHEET C-6 SHEET C-6 SHEET C-7 SHEET

CONFIDENTIAL NOTICE

뒤

Tetra Tech Inc.
Town Payment Departing for Fusion
4000 N. Bird SPRING, Sullin 401
MEDILAND, TEXAS 17705
(432) 682-4559


CHEVRON N.A. E&P, MCBU EDDY COUNTY, NEW MEXICO GPS (WGS84) 32.068884"N, -104.168851"W


GENERAL NOTES

- ALT TOPOGRAPHIC, UTILITY AND CONTRICE, FRONT LOCATION RECORDATION IS BASED OF SERVICE RECORDATION PARKINGS BY THE OWNERS, THE CONTRACTION WAS THE BOLE RESPONSED ITY FOR FELD VICENTICATION.
- COORDINATE INFORMATION IS BLAIED ON AND ANE BAIED ON STATE PLANES COORDINATE WEW MEDICO EAST 20ME (4738) NADIOL THE CONTRACTOR SHALL IDENTRY ANY DISCREPANCES PRICES TO PROCESSING WITH CONSTRUCTION.
- DEFFECT, PERF "CPTBAC" LOCATION IS AT DETAINED SECTION IS AT LOCATION IS AT LOCAT
- THE CONTRACTOR SHALL REFER TO THE HAYMURST SECTION 2 HYDRAULUC FRACTURIAN POND 1 AND POND 2 TECHNICAL BRECHROATIONS IN ADDITION TO THE DRAWNINGS FOR THE CONSTRUCTION.





COVER SHEET
HAYHURST SECTION 2
EDDY COUNTY, NEW MEXICO








PED/20/048 DESCRIPTION DESCRIP	1000 1107 1100	
CONFIDENTIAL NOTICE This bitter are usually are to be party of the control of th	1135	
Tetra Tech Inc. 10078 See SPRING, Auto-407 10074-1007-1007 10074-1007 10074-1008 10074-1008	1207 123 1237 1231 1233 1234 1	
CHEVRON N.A. E&P, MCBU EDDY COUNTY, NEW MEXICO GPS (WGS84) 32.088864"N, -104.168851"W	1200 1200 1200 1200 1200 1200 1200 1200	
VERRIPY SCALE AM 8 DOE (1) HOOD OF THE STATE OF THE SCALE SCALES: POST AGAIN THE STATE OF THE SCALE SCALES SCALES: POST AGAIN THE STATE OF THE SCALE SCALES SCAL		
POND 1 AND POND 2 BELOW GRADE STAKING PLAN HAYHURST SECTION 2 EDDY COUNTY, NEW MEXICO	POND 1 EXCAVATION CALCULATION TOTAL AREA = 4.02 AGRES EXCAVATION VOLUME = 30,427 CLYPS POND 2 EXCAVATION CALCULATION TOTAL AREA = 4.11 AGRES EXCAVATION VOLUME = 29,375 CLYPS EXCAVATION VOLUME = 29,375 CLYPS **POND 1 BELOW GALE STANDAR POWER ARE PREAM 1000 THRU 1100 TOTAL AREA PLA FORD SELVING GALE STANDARD TO TOTAL AREA PLA FORD SELVING GALE STANDARD TO TOTAL AREA PLA FORD SELVING GALE STANDARD TO TOTAL STANDARD TO TOTA	






































Chevron

Hayhurst New Mexico T26S R27E Section 2 U.S.A. Inc. | Recycling Containment and Facility

Appendix 6 – Recycling Containment Geotechnical Engineering Report



Hayhurst Section 2 Hydraulic Fracturing Ponds

Eddy County, New Mexico

August 2017

complex world

CLEAR SOLUTIONS™

Report of Geotechnical Study Hayhurst Section 2 Hydraulic Fracturing Ponds

Eddy County, New Mexico

Prepared for:

Mr. Ruben Kopara Chevron North America Exploration and Production Company

6301 Deauville Blvd, Midland, Texas 79706 Phone: (432) 687-7215

Prepared by:

Tetra Tech

4000 North Big Spring Street, Suite 401 Midland, Texas 79705 Phone (432) 682-4559; Fax (432) 682-3946 **Texas Registered Engineering Firm 3924**

Tetra Tech Project N 1000 A 100 848

Thomas A. Change Principal Engineer O. SOONAL ENGIN

Reviewed by: Don Grahlherr, P.E.

Vice President

August 2, 2017

TABLE OF CONTENTS

EXEC	UTIVE	SUMMARYi
1.0		POSE AND SCOPE OF STUDY
2.0		CONDITIONS
3.0	PRO	POSED DEVELOPMENT4
4.0	GEO	LOGIC CONDITIONS5
5.0		ORATORY SOIL BORINGS6
6.0		SURFACE CONDITIONS7
7.0		NEERING ANALYSES AND RECOMMENDATIONS 8
	7.1	Primary Geotechnical Considerations 8
	7.2	Site Preparation 8
	7.3	Excavation and Embankment Slopes 8
	7.4	Fill Placement and Compaction9
	7.5	Proof Rolling
	7.6	Geomembrane Liner Protection
	7.8	Freeboard11
	7.9	Settlement of Subgrade and Embankment Materials11
	7.10	Permitting 11
8.0	CONC	CLUSIONS
9.0		RENCES
10.0		ATIONS 14

EXECUTIVE SUMMARY

Chevron North America Exploration and Production Company (Chevron) plans to construct hydraulic fracturing ponds at the Hayhurst, New Mexico, Section 2 property located in Eddy County, New Mexico. Chevron will construct two separate ponds, with a capacity of approximately 350,000 barrels (bbl) each to service well drilling operations. The ponds will be designed with a double liner and a leak detection system. The floor of each pond will be sloped to a sump where fluids can be collected, sampled, and pumped if needed.

The purposes of this study were to obtain information on subsurface conditions, and to provide geotechnical design criteria for the construction of the proposed ponds. The general site location is shown on the Site Location Map, Figure 1 and Topographic Map (Figure 2).

Between May 16th and 19th, 2017, Tetra Tech and a subcontractor mobilized to the site with a truck-mounted drilling rig to drill five (5) exploratory soil borings to identify subsurface conditions and collect samples. Borings B-1 and B-4 were drilled to a depth of approximately 45 feet below the existing ground surface (bgs). Borings B-2 and B-3 were drilled to a depth of approximately 40 feet bgs. Boring B-5 was drilled to a depth of approximately 73 feet. Water was encountered at approximate depths of 31, 28, and 31 feet (bgs) in B-1, B-4, and B-5 respectively, and rose to depths of 26, 26, and 29 feet when checked prior to backfilling the boreholes one to two days following the initial drilling. New Mexico Oil Conservation Division Rules published in the New Mexico Administrative Code (NMAC) have specific siting requirements for "pits" (ponds), associated with oil and gas exploration and production, which are within specified proximities to groundwater. A hydrogeological study to meet the requirements of the NMAC should be performed to determine whether the groundwater encountered is a perched layer or a continuous water bearing feature. Approximate locations of the borings are shown on Figure 4.

The borings encountered 3½ to 8½ feet of loose to very dense sand and silt over naturally cemented soil. The cemented soil extended to the maximum depth drilled of 40 feet in boreholes B-2 and B-3.Relatively less cemented soil was encountered starting at depths of 23.5, 28, and 33 feet, and continued to depths of 38.5, 40, and 60 feet respectively in B-1, B-4, and B-5 (located in the southern and central portions of the site). The poorly cemented layer continued to the maximum depth drilled of 45 feet in B-1. Strongly cemented soil was encountered in B-4 and B-5 to the maximum depths drilled of 45 and 73 feet respectively.

Review of mapping by the U.S. Geological Survey (Figure 3) indicates that the Rustler Formation, which is a carbonate based sedimentary rock with evaporates present, underlies the site, and can be prone to karst formation and dissolution leaving voids. No voids were encountered during our investigation, however this does not ensure that voids do not exist beneath the proposed site. Tetra Tech recommends that Chevron consider additional investigation to determine more conclusively if voids exist beneath the site.

Additional investigation and construction recommendations for development of the site are provided in the body of this report.

We have prepared this executive summary solely to provide a general overview, and it should not be used for any purpose except that for which it was intended. We recommend detailed review of the entire report for information about our findings, recommendations and other concerns related to geotechnical conditions for the site.


1.0 PURPOSE AND SCOPE OF STUDY


Chevron plans to construct hydraulic fracturing ponds at the Hayhurst New Mexico, Section 2 property located in Eddy County, New Mexico. Chevron will construct two ponds at the site. Each pond will have an approximate operational capacity of 350,000 barrels (bbls) and will service well drilling operations. We understand the hydraulic fracturing ponds will be designed with a double liner and a leak detection system. The bottom of the pond will be sloped and equipped with a sump and access port/riser at the low point of the floor of the pond.


The scope of the study for this project included the following.


- 1) New Mexico 811 Utility locate request;
- Mobilize a CME 75 drilling rig to drill four (4) borings to a depth of 40 or 45 feet and one
 boring to a depth of 73 feet to look for evidence of groundwater;
- Perform Standard Penetration Tests (SPT) at every 5 or 10-foot interval to evaluate soil consistency and collect soil samples for evaluation;
- 4) Backfill borings with soil cuttings after completion of drilling and 24-hour measurements, as required; and
- 5) Provide geotechnical engineering design criteria and recommendations and prepare a geotechnical report.

The general location of the site is shown on the Site Location Map, Figure 1 and Topographic Map, Figure 2.









2.0 SITE CONDITIONS

The site for the proposed hydraulic fracturing pond is identified as the Hayhurst Section 2 site. It is located adjacent to unpaved roads, 12½ miles southwest of Malaga, New Mexico in Eddy County at the intersection of County Road 775 and Whites City Road. GPS coordinates recorded at the site are 32.067930N and 104.167640W.

The site was wooded with mesquite trees and wild shrubs; clearing with a bulldozer was necessary to access the boring locations at the central and north ends of the site. The site appeared to be relatively flat. Surface utilities, fences, and access roads (on the site) were not observed to be present at the time of drilling, however two underground pipeline right-of-ways were observed at the west and south ends of the site adjacent to the south and west lease roads. In addition, an abandoned underground pipeline running from the southwest to northeast direction was noted. Care was taken to ensure the borings were not located near these underground lines. Drainage streams, swales, playa, or other potential issues were not observed. The existing ground surface appeared to be loose but it adequately supported the drilling rig during drilling. The immediate surrounding property was undeveloped.

3.0 PROPOSED DEVELOPMENT

Based on the information provided by Chevron via electronic mail, the proposed development will consist of two hydraulic fracturing ponds, constructed adjacent to each other, in accordance with the standards outlined in the Chevron Mid-Continent Business Unit General Standards for Brackish and Produced Water Containment Structures (MCBU General Standards) and New Mexico Oil Conservation Division (NMOCD), to service well drilling operations. Each pond will have an operational storage capacity of approximately 350,000 bbl and will be partially below ground. We understand Chevron prefers to balance cut and fill volumes using onsite soil for fill to construct the earthen berms. The ponds will be double lined and equipped with a leak detection system. The bottom of the ponds will be sloped to drain to an installed liquid leak detection sump.

4.0 GEOLOGIC CONDITIONS

Geologic mapping by the U.S. Geological Survey (USGS, 2005 and 2014) indicates the Rustler Formation is the foundation bedrock at the site (Figure 3). This sedimentary rock is primarily composed of carbonate from the Permian Period with evaporites also present. The contact with sediments of the underlying Permian Salado Formation is mapped about one mile west of the subject site.

Mapping by the Natural Resources Conservation Service (NRCS, 2017) identifies the site soils as the Reeves-Gypsum and Reeves-Reagan mapping units (Figure 4). These soils are both described as loam or clay loam derived as residuum weathered from gypsum.

The bedrock and soils described above can often be prone to karst formation and dissolution leaving voids, especially in the presence of groundwater. The size, orientation, extent and such voids is difficult to predict using conventional exploratory geotechnical drilling. Geophysical methods often provide a more effective means to identify potential karst features which can then be verified or ruled out using exploratory drilling.

Our findings of the geotechnical study are consistent with this characterization within the depths explored. No voids in the subsurface were encountered in our borings.

5.0 EXPLORATORY SOIL BORINGS

Tetra Tech drilled five (5) exploratory soil borings (B-1 through B-5) to identify subsurface conditions at the site between May 16 and 18, 2017. The boring locations were selected by a representative from Tetra Tech using a satellite image provided by Chevron. The proposed pond footprint was overlaid on the satellite image and GPS coordinates were obtained for each boring location. The boring locations were marked in the field by Tetra Tech using these GPS coordinates and a commercially available hand held GPS unit. The boring locations were cleared for drilling by comparing the proposed locations to buried utility locations marked by New Mexico 811 utility locating services. In addition, Chevron subcontractors cleared the boring locations using handheld pipeline locating instruments.

The borings were drilled by Enviro-Drill Company from Albuquerque, New Mexico using a truck mounted CME 75 drilling rig. After the necessary vegetation clearing, the ground surface was stable for the drilling rig to access the boring locations and no access issues were noted. Tetra Tech's representative was on site to observe site conditions and the drilling.

Hollow stem auger (HSA) drilling equipment was used to complete the borings. Borings B-1 and B-4 were drilled to a depth of approximately 40 feet below the existing ground surface (bgs) and borings B-2 and B-3 were drilled to a depth of approximately 45 feet bgs. Boring B-5 was drilled to an approximate depth of 73 feet bgs to investigate the presence or absence of groundwater. All borings were left open for a period of approximately 24 to 48 hours to let groundwater levels stabilize. Final water level measurements were taken in each boring after 24 or 48 hours (as applicable) and groundwater was sampled in B-5 and delivered to a commercial laboratory for purposes of analyzing for TPH, Chlorides and RCRA metals, as requested by Chevron.

Soil samples were collected using a split-spoon sampler in borings B-1 through B-4 at 5-foot intervals. In boring B-5 samples were collected at 5-foot intervals to a depth of 30 feet bgs, then the spacing interval was increased to 10-feet. Standard Penetration Tests (SPT) were performed during sampling in accordance with ASTM D 1586 where a 140-pound automatic hammer is repeatedly dropped from a height of 30 inches. The number of blows for each 6-inch increment was recorded on the logs to categorize the consistency of the soil. After drilling and sampling activities were complete the borings were backfilled with soil cuttings. The soil boring logs are presented in Appendix A, and approximate locations of the borings are shown on Figure 4.

6.0 SUBSURFACE CONDITIONS

The information from the borings indicate the subsurface conditions were relatively consistent within the area where the borings were drilled. Beneath minimal vegetation and topsoil, all five (5) borings encountered 3½ to 8½ feet of unconsolidated soil over naturally cemented soil. The cemented soil extended to the maximum depth drilled of 40 feet in boreholes B-2 and B-3 (located on the north side of the proposed site). Relatively less cemented soil was encountered starting at depths of 23.5, 28, and 33 feet, and continued to depths of 38.5, 40, and 60 feet in B-1, B-4, and B-5 (located in the southern and central portions of the site) respectively. The poorly cemented layer continued to the maximum depth drilled of 45 feet in B-1. Strongly cemented soil was encountered in B-4 and B-5 to the maximum depths drilled of 45 and 73 feet respectively. Free water appears to coincide with the relatively less cemented layers in B-1, B-4, and B-5 as described below.

A moisture content of 23.5% was measured on a sample recovered from B-4 at 3.5 feet that had a fines content (percent silt and clay sized particles) of 54.8% by mass. Standard Penetration Test (SPT) N-values in this stratum ranged from 25 bpf in B-4 at 3.5 feet to 62 blows per foot (bpf) in B-1 at 3.5 feet and 50 blows for 3 inches in B-5 at 3.5 feet. Cemented layers had in-situ moisture contents at ranged from 9.8 to 20.4% for 19 samples tested at depths of up to 45 feet. Deeper samples from B-5 at 48.5 and 58.5 feet had moisture contents of 33.1 and 28.8% respectively. Insitu dry densities ranged from 82.3 to 122.6 pounds per cubic foot (pcf). Eleven of the 22 cemented soils samples had a fines content less than 50% and were therefore classified as sand soils in accordance the Unified Soil Classification System (USCS). No consistent layering was observed among the cemented soils in relation to the fines content. Atterberg limits testing of the cemented soils indicated a liquid limit ranging from 33 to 83 and plasticity index ranging from 6 to 61. The sample from B-5 at 48.5 feet was anomalous with a much higher liquid limit of 83 and plasticity index of 61 than the rest of the cemented soils where the liquid limit ranged from 33 to 42 and the plasticity index ranged from 6 to 15. Based on these index properties three of the samples were classified as silty sand (SM) and three were classified as clayey sand (SC). The fines content of the cemented soils with 50% or more fines ranged from 50 to 92%. Atterberg limits testing of these samples indicated a liquid limit ranging from 29 to 62 and plasticity index ranging from 12 to 37. Five of the fine grained cemented soil samples were classified as low plasticity clay (CL) and two were classified as high plasticity clay (CH). N-values within this stratum ranged from 13 bpf to greater than 100 bpf with the lower N-values corresponding to clayey samples or zones where free water was prevalent.

Free water was encountered in three of the five borings at the time of drilling. Water was not encountered in borings B-2 and B-3 (both located on the northern side of the site). Depths to water at the time of drilling were 31, 28 and 31 feet in borings B-1, B-4, and B-5, respectively. Water levels rose to depths of 26, 26, and 29 feet when checked prior to backfilling the boreholes one to two days following the initial drilling. Our observations are only indicative of conditions at the time and boring locations indicated. Water levels can vary due to many factors, including seasonal changes, site topography, surface runoff, post development conditions, the layering and permeability of subsurface strata, water levels in waterways, utilities, and other factors that may not have been evident at the time this study. Long-term observations would be necessary to more accurately evaluate the groundwater behavior and fluctuations.

7.0 ENGINEERING ANALYSES AND RECOMMENDATIONS

7.1 Primary Geotechnical Considerations

The two primary concerns that could impact the proposed development are the presence of strongly cemented soil within the proposed depths of excavation and the possibility of voids due to karst/evaporite subsurface conditions.

Excavation of strongly cemented soil will be difficult for construction due to the high energy required to excavate and eventually pulverize the cemented soil into fragments small enough to use as fill as described below.

While no voids due to karst/evaporite soil and bedrock were encountered during our borehole exploration, they could exist beneath the construction site and could become evident as a result of additional loading or changes to groundwater conditions as a result of construction or through natural progression. Settlement of pond floors or sidewalls due to undetected voids could cause distress or failure of liner systems and discharge of the pond contents to the subgrade. We recommend a geophysical exploration program be considered to search for voids that may not have been identified by the exploratory drilling. Such a program was beyond the scope of the current investigation; however should Chevron decide to undertake a geophysical investigation, Tetra Tech is available to assist.

7.2 Site Preparation

To prepare the site for pond construction, an area larger than the proposed footprint by at least 10 feet in plan dimension on all sides should be stripped of vegetation, roots, organic material, existing construction materials, debris, and other unsuitable materials. A typical stripping depth is approximately 6 inches; however, the actual depth will vary and should be based on field conditions and observations. After stripping, we anticipate a moderately stable surface for support of construction equipment. Unsuitable areas (such as those with loose, wet, soft, yielding, and/or pumping subgrade) should be corrected before construction proceeds.

Obstructions that could hinder preparation of the site should also be removed, with special attention given to unknown or un-documented below ground appurtenances and any existing above and below ground flow lines. Care should be taken not to damage any existing buried utilities located within the footprint of the proposed construction. Any resulting utility trenches/excavations due to replacement or relocation of utilities should be backfilled as discussed in the Fill Placement and Compaction section of this report.

7.3 Excavation and Embankment Slopes

Based on the subsurface data, sandy soil is present to depths of 3½ to 8½ feet below the existing grade and then cemented soils were encountered. Conventional construction equipment can be used to excavate the soil, however excavation into the cemented soils will be more difficult and additional effort to excavate may be necessary. Heavy duty rock ripping equipment like a ripper mounted on a Caterpillar D8 bulldozer or equivalent may be necessary.

The earthwork contractor should review the subsurface conditions and appropriately select excavation equipment and initial slope of the excavation to minimize potential sloughing and to remain in compliance with OSHA Regulations 1926.651 and 1926.652 on excavation safety. Wetting of the exposed excavation sides to a moisture content near or slightly above optimum may be necessary to stabilize and maintain the slopes during construction.

During construction the excavation slopes should be inspected and kept under observation for safety purposes. Excavation slopes specified by OSHA are dependent on types of soil and groundwater conditions encountered. Based on our investigation the on-site soil is classified as Type C and the cemented soil can be considered to be Type B according to OSHA 1926, Subpart P, Appendix A. The contractor's "competent person" should identify the soils encountered in the excavation and refer to OSHA 1926.651 and 1926.652 to verify the conditions and classifications from our investigation and determine appropriate slopes. If deemed unstable, the excavation sides should be flattened or benched to remain in compliance. Stockpiles of soils and equipment should not be placed within a horizontal distance equal to one-half the excavation depth, from the edge of excavation. Excavations deeper than 20 feet should be designed by a Professional Engineer as recommended by OSHA.

Embankment slopes must be constructed slopes flat enough to prevent slope failures. For soil and embankment fill design parameters, an angle of internal friction of 30 degrees with no cohesion is recommended in lieu of design parameters based on shear strength testing. A compacted/improved subgrade soil unit weight of 120 pcf is appropriate. The pond will be lined and we have assumed the liner system will function to prevent development of a phreatic surface within the embankment. We understand that side slopes will be designed at 3 horizontal to 1 vertical (3H:1V), which is consistent with the New Mexico Administrate Code (NMAC) requirements for design of "pits" (or ponds) associated with oil and gas exploration and production operations and not considered temporary, which states that the maximum allowed pond embankment slope is 3H:1V for exterior slopes and 2H:1V for interior slopes. Although steeper slopes may be shown to be stable and acceptable per regulations, we recommend 3H.1V based on consideration of potential constructability issues, liner stability, seepage, and slope stability. We understand the MCBU General Standards have similar slope requirements. If Chevron would like to consider construction of slopes steeper than the 3H:1V recommended above Tetra Tech is available to conduct slope stability analysis to evaluate the feasibility of steeper slopes and liner system performance on those slopes. This analysis would be supported by slope stability modeling and hand calculations to present to the NMOCD in a variance request.

7.4 Fill Placement and Compaction

On-site soils free of rocks greater than 1-inch in diameter, organics, and debris are suitable for use as structural fill or backfill. The cemented soils will likely require additional processing beyond ripping to achieve a soil consistency and meet the maximum particle size dimension in the construction specifications. Fill and backfill should not be placed on organics or other deleterious materials such as soil or rock with soluble components such as gypsum. If additional fill is needed for construction of the embankment, imported fill should be a well-graded clayey sand (SC) or low plasticity clay (CL), or imported soils with engineering properties that are similar to on-site soils (depending on the intended use of the fill). For structural support, a uniform, granular material having 100% passing the 1-inch sieve, 30% to 70% passing the No. 4 sieve, and 3% to 15% passing the number 200 sieve is recommended. Prior to importation, samples of soils being considered as fill should be examined and evaluated by a geotechnical engineer for engineering properties to determine suitability of the material for its intended use.

The bases of fills in soil should be scarified at least 8 inches deep, moisture-conditioned or dried to within 2% of optimum moisture content, processed to a uniform condition, and then compacted to at least 95 percent of maximum dry density determined by standard Proctor (ASTM D698). For on-site and imported fill and backfill, moisture should be adjusted to within minus 1 to 3 percent above optimum moisture content as determined by standard Proctor and the soils thoroughly mixed prior to placement and compaction to provide uniform water content throughout the fill. Fill and backfill should be placed in uniform lifts of 8 inches or less in loose thickness and compacted to at least 95% of standard Proctor maximum dry density (ASTM D 698). Fill should be compacted using heavy vibratory equipment. In areas with limited space for heavy equipment, appropriate compaction equipment, such as a jumping jack or other hand tools should be used. Where smaller compacting equipment or hand tools are used, the fill lifts should be 6 inches or less in loose thickness. The contractor should select the equipment type based upon the fill soil conditions.

Placement and compaction of fill should be observed and tested by a qualified geotechnical engineer or their qualified representative during construction. Each vertical foot of compacted fill placed should be tested for compaction comparison to standard Proctor results. A minimum of one moisture/density verification test should be performed for every 5,000-square-feet of compacted area, or for every 150-lineal feet of utility trench backfill. For smaller areas, a minimum of three (3) verification tests should be conducted for every lift. Subsequent lifts should not be placed until the exposed lift has been tested to confirm compliance with the specified moisture and density. Lifts failing to meet the moisture and density requirements should be reworked to meet the required specifications prior to subsequent lifts being placed. Density and moisture verification testing is recommended to provide an indication that adequate earthwork is being performed. However, the quality of the fill and compaction is the sole responsibility of the contractor. Satisfactory verification testing is not a guarantee of the quality of the contractor's earthwork operations.

The specified moisture content must be maintained until compaction of the overlying lift, or until the cushioning sand layer or geotextile fabric and geomembrane liner are installed. Failure to maintain the specified moisture content could result in excessive soil movement resulting in embankment failure. The contractor must provide some means of controlling the moisture content (such as water hoses, water trucks, etc.). Maintaining subgrade moisture is always critical, but will require the most effort during warm, windy and/or sunny conditions.

7.5 Proof Rolling

Proof rolling of the subgrade prior to fill placement and liner installation should be used to detect areas of soft and/or pumping soil. Proof rolling should be conducted using a heavy, rubber-tired vehicle weighing at least 25 tons, with the tires inflated to the manufacturer's specified operating pressure. The entire area should be proof rolled, with each succeeding pass offset by not greater than one tire width. The geotechnical engineer or an experienced soils technician should be present during proof rolling activities to assist with the identification of unsuitable soil. Unsuitable soil should be undercut and reworked, or otherwise improved in a manner that is suitable to the design and approved by the geotechnical engineer.

7.6 Geomembrane Liner Protection

Where the exposed surface is rough, rock protrusions and sharp edges can potentially damage the geomembrane liner. Additionally an irregular foundation with voids can create localized stress points on the geomembrane liner. The subsurface conditions at this site indicate sandy soils to a depth of 3½ to 8½ feet deep which should suffice for geomembrane liner foundation, however, the pond bottom will likely be in the underlying cemented soil with rock-like protrusions and surface irregularities. If the protrusions are greater than ½-inch or if voids greater than 2 inches deep will exist below the liner, a cushion, such as a fine grained sand layer, approximately 6 inches thick or a properly designed cushion geotextile should be used to reduce the risk of damage to the liner. Liner requirements must meet those presented in the New Mexico Administrative Code (NMAC).

7.8 Freeboard

An important aspect of embankment stability and performance is maintaining the appropriate freeboard (the vertical distance from the water surface to the crest of the embankment). If the freeboard is insufficient, the embankment could overtop, leading to excessive erosion and possible failure. The NMAC requirements for operation of "pits" (or ponds) associated with oil and gas exploration and production and MCBU General Standards require a minimum freeboard of three feet which must be maintained at all times.

7.9 Settlement of Subgrade and Embankment Materials

Settlement of embankment material is another important aspect of embankment stability and total fluid storage potential over time. It is anticipated that the embankments will be constructed of fill consisting of on-site material or imported fill. The on-site sandy soils have a relatively low potential for post-construction settlement. Construction recommendations from above for subgrade proof rolling, subgrade improvements, and fill placement will reduce the amount of settlement. Due to the sandy nature of the soils, most of the anticipated or potential settlement within the embankments and under the embankments should occur during construction.

7.10 Permitting

If applicable, a permit application should be filed with the NMOCD in accordance with NMAC regulations prior to construction. Construction and installation in accordance with NMOCD regulations found in the NMAC and the design drawings and construction specifications is recommended. The NMOCD may require notification prior to construction and prior to operation of the pond.

8.0 CONCLUSIONS

The Tetra Tech investigation identified two potential issues that should be addressed prior to development of the proposed hydraulic fracturing ponds at the Hayhurst Section 2 site. The first is that water in the boreholes stabilized at depths of 26, 26, and 29 feet in borings 1, 4, and 5, respectively (when measured one to two days following the initial drilling). New Mexico Oil Conservation Division rules in the NMAC have specific siting requirements for "pits" (ponds), associated with oil and gas exploration and production, which are within specified proximities to groundwater. A hydrogeological study to meet the requirements of the NMAC should be performed to determine whether the water encountered is a perched layer or a continuous water bearing feature.

Another potential issue is based on review of mapped geology at the site which indicated a bedrock formation that is susceptible to formation of voids, especially in the presence of groundwater, where dissolution of the carbonate and evaporite minerals can occur. Voids can be exacerbated by loading or changes in hydrology that could occur as a result of the pond construction. Collapse of soils overlying such voids could damage the ponds or liner system and result in release of stored fluids to the environment.

Geophysical methods can be an effective means to identify potential voids that may exist at depth but are not readily identifiable by exploratory drilling. If geophysical methods suggest that voids may exist, additional exploratory drilling might be needed to confirm the presence of voids.

Tetra Tech can assist Chevron with further analyses of the Hayhurst Section 2 site should it be of interest. We can prepare a scope of work and cost estimate for Chevron review prior to authorization of these tasks.

Following further understanding of the groundwater and presence of subsurface voids, the proposed hydraulic fracturing ponds can be constructed in accordance with MCBU General Standards and NMOCD regulations, as described herein. Construction should be conducted in accordance with MCBU General Standards, NMOCD regulations, the engineering drawings and specifications prepared by Tetra Tech, and this report.

9.0 REFERENCES

Chevron Mid-Continent Business Unit MCBU General Standards for Brackish and Produced Water Containment Structures, DRAFT version (MCBU General Standards)

U.S. Department of Agriculture, Natural Resources Conservation Service (NRCS, 2017). Web Soil Survey. http://websoilsurvey.nrcs.usda.gov/app/WebSoilSurvey.aspx. Accessed July 10, 2017.

United States Geological Survey (USGS, 2005). Preliminary Integrated Geologic Map for the United States Central States. Open-File Report 2005-1351

United States Geological Survey (USGS, 2014). Karst in the United States: A Digital Map Compilation and Database. Open-File Report 2014-1156. Weary, D.J., and Doctor, D.H.

10.0 LIMITATIONS

This report was prepared from data developed during our field exploration, laboratory testing, and engineering judgment. Our design recommendations were based on subsurface data and our experience with similar projects and subsurface conditions. Our borings were located to obtain a reasonable interpretation of subsurface conditions. It should be noted that the borings were widely spaced and variation in the subsoils between borings is likely.

A qualified, experienced geotechnical engineer or their designated representative should observe the construction to look for evidence that would indicate differences in subsurface conditions from those described in this report. If any information becomes available that would alter our assumptions, conclusions or recommendations, the opinions presented in this report should be considered invalid until we have been contacted to review our recommendations based on the new information. The geotechnical engineer should review plans and specifications during the design. Placement and compaction of engineered fill, backfill, subgrade and other fills should be observed and tested by a representative of a Construction Materials Testing (CMT) firm during construction, and Tetra Tech should be retained to review these data.

We believe this study was conducted in a manner consistent with that level of skill and care ordinarily used by members of the profession currently practicing under similar conditions in the locality of this project. No warranty, express or implied, is made. If we can be of further service in discussing the contents of this report or in the analysis of the planned project from the geotechnical point of view, please contact us.

APPENDIX A EXPLORATORY BORING LOGS



BOREHOLE ID: B-1

PAGE 1 OF 2

CLIENT Chevron

PROJECT NUMBER 212C-MD-00848

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/16/2017

CONSULTANT: Tetra Tech, Inc.

DRILLING CONTRACTOR: Enviro Drill

Notes: Not Recorded

BOREHOLE/TPAWELL - VECTOR HAYHURST.GPJ LAB SUMMARY.GDT 7/13/17

GROUND ELEVATION: NA

LATITUDE: 32.067930 N

LONGITUDE: 104.167640 W

METHOD: HSA

LOGGED BY: Clint Merritt and Raj Meruva

DRILLED BY: Juan Uribe

о ОЕРТН	SAMPLE TYPE	N Value	TESTS	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION
	X ss	62				Loose to Medium Dense, Brown, Sub Angular Medium Grained <u>SAND</u> 3.5 Very Dense, Pink, Fine Grained <u>SAND</u>
5 	<u> </u>					8.5
10	SS	50/5"	MC = 19.8% Fines = 36.1%			Very Dense, Pink, Weakly Cemented Fine Grained <u>SAND</u> , with < 20% Fine Gravel, Calcareous, Moist
15	ss	50/4"				
20	ss	50/1"				
	1	50/3"	MC = 13.2%	014		23.5
25 /	X ss	\	MC = 13.2% DD = 106.1 pcf LL = 37 Fines = 49.5%	SM		Very Dense to Medium Dense, Dark Brown, Moderately Cemented Fine Silty and Clayey SAND, Increasing Plasticity with Depth, Moist to Wet Water depth 48 hours after drilling Water depth at the end of drilling
30	ss	13				☑ Water depth during drilling
35	ss	15	MC = 18.8% DD = 102.3 pcf LL = 33 Fines = 47.4%	sc		
40	ss	13				



BOREHOLE ID: B-1 PAGE 2 OF 2

PROJECT NAME Hawhard NM, Sec 2 Frate Pond PROJECT NUMBER 212C-MD-00848 TESTS SS 46 CONTROL 123 FM PROJECT LOCATION Fidth County, New Mexico MATERIAL DESCRIPTION Stiff to Very Stiff, Dark Brown, Low Plasticity CLAY with Sand, Molet 150 Material Description Stiff to Very Stiff, Dark Brown, Low Plasticity CLAY with Sand, Molet 150 Material Description Stiff to Very Stiff, Dark Brown, Low Plasticity CLAY with Sand, Molet 150 Material Description Borehole terminated at 45.0		432-682-3946	
PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico HEAD STATESTS SO ST		PROJECT N	AME _Hayhurst NM, Sec.2 Frac Pond
Stiff to Very Stiff, Dark Brown, Low Plasticity CLAY with Sand, Moist CL 45 SS 46 MC = 17.7% DD = 122.6 per Fines 2 57.7% CL Borehole terminated at 45.0	CT NUMBER 212C-I		
SS 46 MC = 17.7% DD = 122.6 pcf LL = 29 Fines = 57.7%	SAMPLE TYPE N Value		
Borehole terminated at 45.0	SS 46	CL CL	rk Brown, Low Plasticity CLAY with Sand, Moist
			Borehole terminated at 45.0



BOREHOLE ID: B-2

PAGE 1 OF 1

CLIENT Chevron

Notes: Not Recorded

PROJECT NAME Hayhurst NM, Sec. 2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/18/2017

GROUND ELEVATION: NA

METHOD: HSA

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.069966 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.167700 W

DRILLED BY: Juan Uribe

DEPTH (ft)	SAMPLE TYPE	N Value	TESTS	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION
0					13	Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND
	× ss	50/5"	MC = 14.1% Fines = 41.9%			3.5 Very Dense, Pink, Strongly Cemented Medium Grained SAND, with <50%
5						Depth, with Sand, with <50% Quartz Fragments, Moist Hard, Red, SILT TO CLAY Fines and Plasticity Increasing with Depth, with Sand, with <50% Quartz Fragments, Calcareous, Moist
	X ss	50/2"				
10	/ 00					
-	X ss	50/3"	MC = 15.6%	ML		
15	\ 33		MC = 15.6% DD = 96.0 pcf Lt = 44 Fines = 50.3%	-		
-	X ss	50/4"				
20 /	\ 33					
	X ss	50/3"				
25 /						
	ss	50/4"	MC = 20.4%	СН		
30 /	V 22		MC = 20.4% DD = 93.1 pcf LL = 53 Fines = 59.2%	-		Very Dense, Pink, Strongly Cemented Medium Grained SILTY SAND, with >50% Quartz Fragments, Calcareous, Moist
	ss	50/2"				
35	33	- 27 64				
+	ss	50/4"	MC = 19.5% LL = 42 Fines = 38.8%		1	
		:11//4	NIC = 18.3%	SM	V V	



BOREHOLE ID: B-3

PAGE 1 OF 1

CLIENT Chevron

PROJECT NAME _Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/18/2017

GROUND ELEVATION: NA

METHOD: HSA

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.070140 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.165980 W

DRILLED BY: Juan Uribe

Notes: Not Recorded

BOREHOLE/TP/WELL - VECTOR HAYHURST.GPJ LAB SUMMARY.GDT 7/13/17

	3. Ivol Icc	oraca			
O DEPTH	SAMPLE TYPE	N Value	TESTS	GRAPHIC	MATERIAL DESCRIPTION
		F0/5/1	NO - 42 0V		Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND 3.5
5	Ss	50/5"	MC = 13.8% Fines = 52.9%		Very Dense, Pale Red, Weakly Cemented Medium Grained Sandy Silty <u>CLAY</u> with <10% Small Angular Limestone Fragments, Moist
10	ss	50/5"			
15	× ss	50/3"			Hard, Yellowish Brown, Strongly Cemented SILTY CLAY, with < 20% Small Angular Limestone Fragments, Slight odor, Calcareous, Slightly Moist
20	× ss	50/4"	MC = 9.8% Fines = 85.6%	-	
 25					
30					
35					
40					40.0 Borehole terminated at 40.0

TETRA TECH

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-4

PAGE 1 OF 2

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/17/2017

GROUND ELEVATION: NA

METHOD: HSA

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.068070 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.165660 W

DRILLED BY: Juan Uribe

Notes: Not 1		TOK. ENVIO DIM			DRILLED BY: Juan Uribe
O DEPTH (ft) SAMPLE TYPE	N Value	TESTS	U.S.C.S.	GRAPHIC	MATERIAL DESCRIPTION
					Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND
5 S	25	MC = 23.5% Fines = 54.8%			3.5 Medium Dense, Pink, Weakly Cemented Medium Grained <u>SILT</u> , Calcareous, Moist
- S:	50/2"				B.5 Hard, Red, Strongly Cemented Low Plasticity <u>CLAY</u> , with Sand, Calcareous, Moist
15 SS	50/2"	MC = 16.5% DD = 96.1 pcf LL = 37 Fines = 61.9%	CL		
	5 50/2"				20.0 Very Dense, Red, Moderately Cemented Medium Grained Silty Clayey <u>SAND</u> , with < 20% Gypsum Fragments, Moist to Wet
SS	50/4"	MC = 10.0% Fines = 43.2%			with < 20% Gypsum Fragments, Moist to Wet
30 SS	20				Water depth 46 hours after drilling Water depth during drilling Very Stiff to Hard, Red, Low Plasticity <u>CLAY</u> , with Sand, Moist
35 SS	26	MC = 15.5% DD = 113.9 pcf LL = 29 Fines = 92.1%	CL		
40 ss	35				Freestanding water



BOREHOLE ID: B-4
PAGE 2 OF 2

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJ	ECT NU	MBER 2	12C-MD-00848			PROJECT LOCATION Eddy County, New Mexico
DEPTH (ft)	SAMPLE TYPE	N Value	TESTS	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION
45	× ss	50/1"	MC = 15.1% LL = 30 Fines = 88.6%	CL		Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist (continued) 45.0
			1 1100 - 00.070			Borehole terminated at 45.0
		=				

TETRATECH

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559

Fax: 432-682-3946

BOREHOLE ID: B-5

PAGE 1 OF 2

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec. 2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/17/2017

CONSULTANT: Tetra Tech, Inc.

DRILLING CONTRACTOR: Enviro Drill

Notes: Not Recorded

GROUND ELEVATION: NA

LATITUDE: 32.069030 N

LONGITUDE: 104.166890 W

METHOD: HSA

LOGGED BY: Clint Merritt and Raj Meruva

DRILLED BY: Juan Uribe

O DEPTH	SAMPLE TYPE	N Value	TESTS	U.S.C.S.	GRAPHIC	MATERIAL DESCRIPTION
5	× ss	50/3"	MC = 17.0% Fines = 19.3%			Loose to Medium Dense, Brown, Sub Angular Medium Grained <u>SAND</u> 3.5 Very Dense, Pink, Strongly Cemented Medium Grained <u>SAND</u> , Calcareous,
	× ss	50/4"	MC = 15.8% DD = 99.8 pcf	SM		Moist 8.5 Very Dense, Pale Red, Strongly Cemented Medium Grained, Silty to Clayey SAND with > 40% Gypsum/Quartz Fragments, Calcareous, Moist
 - 15	× ss	50/4"	LL = 42 Fines = 44.4%	<i>J</i>		SANU with > 40% Gypsum/Quartz Fragments, Calcareous, Moist
20	× ss	50/5"	MC = 15.9% DD = 114.2 pcf LL = 46 Fines = 49.7%	sc		
25	× ss	50/4"	MC = 16.5% Fines = 25.9%			25.0 Hard, Pink, High Plasticity <u>CLAY</u> with Sand, Calcareous, Wet
	× ss	50/3"	MC = 20.3% DD = 96.6 pcf LL = 62 Fines = 51.5%	СН		
35	X ss	49				Very Dense to Medium Dense, Reddish Brown, Moderately Cemented Medium Grained <u>CLAYEY SAND</u> with > 30% Quartz Fragments, with Lenses of Clay, High Plasticity, Slightly Wet
40	ss	49				



BOREHOLE ID: B-5

PAGE 2 OF 2

CLIENT Chevron

BOREHOLE/TP/WELL - VECTOR HAYHURST.GPJ LAB SUMMARY.GDT 7/13/17

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico

PRU	JECT NUI	MBER 2	12C-MD-00848			PROJECT LOCATION Eddy County, New Mexico
DEPTH (ft)	SAMPLE TYPE	N Value	TESTS	U.S.C.S.	GRAPHIC LOG	
45						Very Dense to Medium Dense, Reddish Brown, Moderately Cemented Medium Grained <u>CLAYEY SAND</u> with > 30% Quartz Fragments, with Lenses of Clay, High Plasticity, Slightly Wet (continued)
50	× ss	25	MC = 33.1% DD = 82.3 pcf LL = 83 Fines = 39.2%	sc		
55						
60	× ss	50/3"	MC = 28.8% LL = 45 Fines = 56.3%	CL		Very Dense, Reddish brown, Clayey, Strongly Cemented Medium Grained SAND, with > 40% Quartz, Wet and Muddy
65	× ss	50/1"		12 12 12 12 12 12 12 12 12 12 12 12 12 1		
				27.77		73.0 Borehole terminated at 73.0
				RE		



September 7, 2017

Mr. Ruben Kopara Chevron North America Exploration and Production Company 6301 Deauville Blvd, Midland, Texas 79706

Subject:

Addendum to Geotechnical Investigation Report

Hayhurst Section 2 Hydraulic

Fracturing Ponds

Eddy County, New Mexico

Dear Mr. Kopara:

On August 2, 2017, Tetra Tech published a report of our geotechnical study for the referenced site where Chevron intends to construct two earthen impoundments with capacities of approximately 350,000 bbl each to service well drilling operations. Subsequent to that investigation and report, Chevron moved the location of the proposed pits to an adjacent area immediately north of the previous site. On August 17 and 18, 2017, Tetra Tech returned to the site and drilled three additional borings in the new area to investigate subsurface conditions. The locations of the borings are shown on the attached Figure 1. Previous borings are labeled B-1 through B-5; the more recent borings are labeled B-6 through B-8.

Borings B-6 through B-8 encountered 21 to 30 feet of medium dense to dense sand over hard clay with cemented lenses. Standard Penetration Tests (SPT) in the sand had values or blow counts (N) ranging from 23 blows per foot to 50 blows for 2 inches; blow counts in the clay ranged from 9 blows per foot (in B-8 at the contact with the overlying sand) to 50 blows for 2 inches. In general, the density of the soils increases with depth based on the SPT values. Free water was not encountered in the borings.

The additional borings indicate that the subsurface conditions on the northern part of the site are consistent with those encountered to the south. The soils to the south have a higher silt and clay content, but blow counts are similar. The borings to the north have a lesser degree of cementation at shallow depth, which may simplify earthwork. No voids or carbonate rocks or deposits were encountered.

Recommendations made in our geotechnical report for the original site remain valid for the revised pit location. Our report: *Hayhurst, Section 2 Hydraulic Fracturing Ponds, Eddy County New Mexico*, dated August 2, 2017, should be carefully reviewed in its entirety during design and construction of the pits at the proposed revised location. In particular, we reiterate that although evidence of voids or karst terrain were not encountered, the site is located in a karst-prone geologic area and voids that were not observed in our widely spaced borings could exist under portions of the site. We recommend Chevron consider geophysical investigation to more conclusively determine if voids could exist below portions of the site.

Please contact the undersigned with any questions or comments you may have regarding this addendum letter or our recommendations for these sites.

Sincerely,


TETRA TECH, INC.

Thomas A. Chapel, CPG PE 97117
Principal Geotechnical Engineer
ONAL ENG

18861

Reviewed by

Don Grahlherr, PE Vice President



ATTACHMENT A BORING LOGS



BOREHOLE ID: B-1

PAGE 1 OF 2

Fax: 432-682-3946 CLIENT Chevron PROJECT NAME Hayhurst NM, Sec.2 Frac Pond PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico **DATE(S) OF DRILLING: 05/16/2017 GROUND ELEVATION: NA METHOD:** CONSULTANT: Tetra Tech, Inc. LATITUDE: 32.067930 N LOGGED BY: Clint Merritt and Raj Meruva DRILLING CONTRACTOR: Enviro Drill LONGITUDE: 104.167640 W **DRILLED BY: Juan Uribe** Notes: Not Recorded SAMPLE TYPE **BLOW COUNTS** GRAPHIC LOG DEPTH (ft) U.S.C.S. **TESTS** MATERIAL DESCRIPTION 0

Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND 62 Very Dense, Pink, Fine Grained SAND SS 5 50/5 MC = 19.8% Very Dense, Pink, Weakly Cemented Fine Grained SAND, with < 20% Fine SS Fines = 36.1% 10 Gravel, Calcareous, Moist 50/4' SS 15 50/1' SS 20 MC = 13.2% 50/3' SM SS 25

Very Dense to Medium Dense, Dark Brown, Moderately Cemented Fine Silty and Clayey <u>SAND</u>, Increasing Plasticity with Depth, Moist to Wet DD = 106.1 pcf LL = 37 BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17 Fines = 49.5% ▼ Water depth 48 hours after drilling Water depth at the end of drilling 13 SS 30 MC = 18.8% DD = 102.3 pcf LL = 33 Fines = 47.4% 15 SC SS 35 13 SS



BOREHOLE ID: B-1 PAGE 2 OF 2

		Fax:	432-0	682 - 39	46
	CNT Chevron				PROJECT NAME Hayhurst NM, Sec.2 Frac Pond
PROJ	JECT NUMBER _2	12C-MD-00848			PROJECT LOCATION Eddy County, New Mexico
DEPTH (ft)	SAMPLE TYPE BLOW COUNTS	TESTS	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION
45	SS 46	MC = 17.7% DD = 122.6 pcf LL = 29 Fines = 57.7%	CL		Very Dense to Medium Dense, Dark Brown, Moderately Cemented Fine Silty and Clayey SAND, Increasing Plasticity with Depth, Moist to Wet (continued) Stiff to Very Stiff, Dark Brown, Low Plasticity CLAY with Sand, Moist Stiff to Very Stiff, Dark Brown, Low Plasticity CLAY with Sand, Moist (continued Borehole terminated at 45.0
					Describe telliminated at 49.0



BOREHOLE ID: B-2

PAGE 1 OF 1

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/18/2017

GROUND ELEVATION: NA

METHOD:

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.069966 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.167700 W

DRILLED BY: Juan Uribe

Notes: Not Recorded

BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY GDT 8/24/17

TESTS TE							
SS 50/5" SS 50/6" MC = 14, Try Press = 41, 9% SS 50/6" MC = 18, Try Press = 41, 9% SS 50/6" MC = 18, Try Press = 41, 9% ML Hard, Ref. SILT TO CLAY Fines and Plasticity Increasing with Depth, with Sand, with <50% Quartz Fragments, Calcareous, Moist ML Finise = 59, 3% MS 50/4" MC = 20, 4% Finise = 59, 3% ML SS 50/4" MC = 20, 4% Finise = 59, 3% CH 30.0 Very Dense, Pink, Strongly Cemented Medium Grained SAND with <50% Quartz Fragments, Calcareous, Moist CH 30.0 Very Dense, Pink, Strongly Cemented Medium Grained SILTY SAND, with <50% Quartz Fragments, Calcareous, Moist		SAMPLE TYPE	BLOW COUNTS	TESTS	U.S.C.S.	GRAPHIC	MATERIAL DESCRIPTION
SS 50/5" MC = 11 % Pres = 41 % Pres = 41 % Very Dense, Prink, Strongly Cemented Medium Grained SAND, with <50% Quartz Fragments, Moist Hard, Red, SiLT TO CLAY Fines and Plasticity Increasing with Depth, with Sand, with <50% Quartz Fragments, Calcareous, Moist ML 10	 						
Hard, Red, SILT TO CLAY Fines and Plasticity Increasing with Depth, with Sand, with <50% Quartz Fragments, Calcareous, Moist ML SS 50/3" MC = 15.8% DD = 96.9 pcf LL = 44 Fines = 50.3% ML SS 50/4" MC = 20.4% DD = 93.1 pcf LL = 35 DD = 93.1 pcf LL = 35 Pres = 59.2% Very Dense, Pink, Strongly Cemented Medium Grained SILTY SAND, with >50% Quartz Fragments, Calcareous, Moist	- 5	X ss	50/5"	MC = 14.1% Fines = 41.9%		1/1	Very Dense, Pink, Strongly Cemented Medium Grained SAND, with CEOP
15	10	X ss	50/2"				Hard, Red, <u>SILT TO CLAY</u> Fines and Plasticity Increasing with Depth, with Sand, with <50% Quartz Fragments, Calcareous, Moist
SS 50/4" SS 50/4" SS 50/4" MC = 20.4% DD = 93 1 std. Fines = 59.2% Very Dense, Pink, Strongly Cemented Medium Grained SILTY SAND, with >50% Quartz Fragments, Calcareous, Moist	15	ss	50/3"	DD = 96.0 pcf	ML		
30 D= 93.1 pcf LL = 53 Fines = 59.2% Very Dense, Pink, Strongly Cemented Medium Grained SILTY SAND, with >50% Quartz Fragments, Calcareous, Moist							
>50% Quartz Fragments, Calcareous, Moist	30	X ss	50/4"	DD = 93.1 pcf LL = 53	СН		
SS 50/4" MC = 19.5% LL = 42 Fines = 38.8%	35	× ss	50/2"	, n tou - U.J. <u>2</u> 79			very Dense, Pink, Strongly Cemented Medium Grained SILTY SAND, with >50% Quartz Fragments, Calcareous, Moist
Borehole terminated at 40.0	40	ss	50/4"	MC = 19.5% LL = 42 Fines = 38.8%	SM		40.0



BOREHOLE ID: B-3

PAGE 1 OF 1

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/18/2017

GROUND ELEVATION: NA

METHOD:

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.070140 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.165980 W

DRILLED BY: Juan Uribe

Notes: Not Recorded

BOREHOLE/TP/WELL - TT HAYHURST GPJ LAB SUMMARY GDT 8/24/17

O DEPTH	SAMPLE TYPE	BLOW COUNTS	TESTS	GRAPHIC LOG	MATERIAL DESCRIPTION
		50/5"	MC = 13.8%		Loose to Medium Dense, Brown, Sub Angular Medium Grained <u>SAND</u> 3.5
5	X ss		MC = 13.5% Fines = 52.9%		Very Dense, Pale Red, Weakly Cemented Medium Grained Sandy Silty <u>CLAY</u> with <10% Small Angular Limestone Fragments, Moist
10	X ss	50/5"		HEER	Hard Vellowish Brown, Strongly Comented SILTY CLAY with a COV Co. II A.
15	× ss	50/3"	10.000		Hard, Yellowish Brown, Strongly Cemented <u>SILTY CLAY</u> , with < 20% Small Angular Limestone Fragments, Slight odor, Calcareous, Slightly Moist
20	× ss	50/4"	MC = 9.8% Fines = 85.6%		
25					
30					
35					10
40				4	0.0
					Borehole terminated at 40.0

TETRA TECH

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-4

PAGE 1 OF 2

CLIENT Chevron PROJECT NAME Hayhurst NM, Sec.2 Frac Pond PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico DATE(S) OF DRILLING: 05/17/2017 GROUND ELEVATION: NA METHOD: CONSULTANT: Tetra Tech, Inc. LATITUDE: 32.068070 N LOGGED BY: Clint Merritt and Raj Meruva DRILLING CONTRACTOR: Enviro Drill LONGITUDE: 104.165660 W **DRILLED BY: Juan Uribe** Notes: Not Recorded SAMPLE TYPE **BLOW COUNTS** GRAPHIC LOG DEPTH (ft) U.S.C.S. **TESTS** MATERIAL DESCRIPTION 0 Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND 25 MC = 23.5% Medium Dense, Pink, Weakly Cemented Medium Grained SILT, Calcareous, SS Fines = 54.8% 5 SS 50/2" Hard, Red, Strongly Cemented Low Plasticity CLAY, with Sand, Calcareous, 10 50/2' CL SS DD = 96.1 pcf LL = 37 Fines = 61.9% 15 50/2 SS 20 20.0 Very Dense, Red, Moderately Cemented Medium Grained Silty Clayey SAND, with < 20% Gypsum Fragments, Moist to Wet 50/4" MC = 10.0% SS BOREHOLE/TPAMELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17 25 Fines = 43.2% Water depth 48 hours after drilling 28.0 V Water depth during drilling Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist 20 SS MC = 15.5% DD = 113.9 pcf LL = 29 Fines = 92.1% 26 CL SS 35 35 SS Freestanding water



BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946 BOREHOLE ID: B-4
PAGE 2 OF 2

CLIENT Chevron PROJECT NAME Hayhurst NM, Sec.2 Frac Pond PROJECT NUMBER _212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico **BLOW COUNTS** SAMPLE TYPE GRAPHIC LOG U.S.C.S. **TESTS** MATERIAL DESCRIPTION Very Stiff to Hard, Red, Low Plasticity CLAY, with Sand, Moist (continued) 50/1" MC = 15.1% LL = 30 Fines = 88.6% SS CL 45 45.0 Borehole terminated at 45.0



BOREHOLE ID: B-5

PAGE 1 OF 2

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec. 2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 05/17/2017

GROUND ELEVATION: NA

METHOD:

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.069030 N

LOGGED BY: Clint Merritt and Raj Meruva

DRILLING CONTRACTOR: Enviro Drill

LONGITUDE: 104.166890 W

DRILLED BY: Juan Uribe

Notes: Not Recorded

o DEPTH (ft)	SAMPLE TYPE	BLOW COUNTS	TESTS	U.S.C.S.	GRAPHIC	MATERIAL DESCRIPTION
	X ss	50/3"	MC = 17.0%			Loose to Medium Dense, Brown, Sub Angular Medium Grained SAND 3.5
5 -			Fines = 19.3%			Very Dense, Pink, Strongly Cemented Medium Grained <u>SAND</u> , Calcareous, Moist
10	× ss	50/4"	MC = 15.8% DD = 99.8 pcf LL = 42 Fines = 44.4%	SM		Very Dense, Pale Red, Strongly Cemented Medium Grained, Silty to Clayey SAND with > 40% Gypsum/Quartz Fragments, Calcareous, Moist
15 -	× ss	50/4"				
20	× ss	50/5"	MC = 15.9% DD = 114.2 pcf LL = 46 Fines = 49.7%	sc		
25	× ss	50/4"	MC = 16,5% Fines = 25.9%			25.0 Hard, Pink, High Plasticity <u>CLAY</u> with Sand, Calcareous, Wet
30	× ss	50/3"	MC = 20.3% DD = 96 6 pcf LL = 62 Fines = 51.5%	CH		▼ Water depth 22.5 hours after drilling ▼ Water depth during drilling
35	X ss	49			3	Very Dense to Medium Dense, Reddish Brown, Moderately Cemented Medium Grained <u>CLAYEY SAND</u> with > 30% Quartz Fragments, with Lenses of Clay, High Plasticity, Slightly Wet
40	X ss	49				



BOREHOLE ID: B-5

PAGE 2 OF 2

CLIENT Chevron PROJECT NAME Hayhurst NM, Sec.2 Frac Pond PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico **BLOW COUNTS** SAMPLE TYPE GRAPHIC LOG U.S.C.S. DEPTH (ft) **TESTS** MATERIAL DESCRIPTION Very Dense to Medium Dense, Reddish Brown, Moderately Cemented Medium Grained <u>CLAYEY SAND</u> with > 30% Quartz Fragments, with Lenses of Clay, High Plasticity, Slightly Wet (continued) 45 MC = 33.1% DD = 82.3 pcf LL = 83 Fines = 39.2% 25 SC SS 50 55 MC = 28.8% LL = 45 Fines = 56.3% 50/3 SS CL 60 Very Dense, Reddish brown, Clayey, Strongly Cemented Medium Grained SAND, with > 40% Quartz, Wet and Muddy 65 50/1" SS 70 BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17 Borehole terminated at 73.0



BOREHOLE ID: B-6

PAGE 1 OF 2

CLIENT Chevron

BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY,GDT 8/24/17

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 08/17/2017

GROUND ELEVATION: NA

METHOD:

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.071130 N

LOGGED BY: Not Recorded

DRILLING CONTRACTOR: Not Recorded

LONGITUDE: 104.166990 W

DRILLED BY: Not Recorded

Notes: No groundwater encountered. N values have been corrected for sampler diameter.

ļ				
O DEPTH	SAMPLE TYPE	BLOW COUNTS	GRAPHIC LOG	MATERIAL DESCRIPTION
				Medium Dense, Brown, <u>SAND</u> , some Organics, No Odor, Dry
	CA	29		3.0
5	CA	49		Very Dense, Reddish Yellow, <u>SAND</u> with about 40% Small, Fine, Moderately Cemented Gravel Sandstone Fragments, No Organics, No Odor, Dry
+ +		50/5"	1	7.0
	CA	50/5"		Very Dense, Yellowish Brown, Fine <u>SAND</u> , with about 50%, Coarse Strongly Cemented Sandstone, Gravel, with Fine Moderately Cemented Quartz Gravel, No Odor, No Organics, Dry
10	ST		1	orange addite Graver, No Organics, Dry
-				
15	CA	50/1"	1/	
	LCA		1/4	
_ 20	CA	50/3"		
			1/1	
25	CA	72		~ 10% Coarse Strongly Cemented Chert Gravel
-	1 5.		113	
30	CA	19	3	10.0 Hard, Pale Red, <u>CLAY,</u> with about 20% Quartz, No Organics, No Odor, Dry
<u> </u>				
35				
	ST	}		
40		ľ		
	CA	50/1"		(Continued Next Dece)



BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephota. 432-682-4559

BOREHOLE ID: B-6

PAGE 2 OF 2

Fax: 432-682-3946 CLIENT Chevron PROJECT NAME Hayhurst NM, Sec.2 Frac Pond PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico **BLOW COUNTS** SAMPLE TYPE GRAPHIC LOG DEPTH (ft) MATERIAL DESCRIPTION Hard, Pale Red, CLAY, with about 20% Quartz, No Organics, No Odor, Dry (continued) 45 50 50.0 ST 55 60 50/2" CA 65 70 50/3" CA Borehole terminated at 76.5



CLIENT Chevron

Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone: 432-682-4559 Fax: 432-682-3946

BOREHOLE ID: B-7

PROJECT NAME _Hayhurst NM, Sec.2 Frac Pond

PAGE 1 OF 2

PROJECT NUMBER _212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico DATE(S) OF DRILLING: 08/18/2017 **GROUND ELEVATION: NA METHOD:** CONSULTANT: Tetra Tech, Inc. LATITUDE: 32.071740 N LOGGED BY: Not Recorded DRILLING CONTRACTOR: Not Recorded LONGITUDE: 104.167650 W **DRILLED BY: Not Recorded** Notes: No groundwater encountered. N values have been corrected for sampler diameter. **BLOW COUNTS** SAMPLE TYPE GRAPHIC LOG DEPTH (ft) MATERIAL DESCRIPTION 0 Dense to Very Dense, Reddish Brown SAND, No Organics, No Odor, Dry 27 CA 50/5' CA 5 50/3' CA Very Dense, Pink, SAND, with about 20% Weakly Cemented Quartz, No Odor, No Organics, Calcareous, CA 50/2" 10 50/4" CA 15 50/3 CA 20 50/4" CA Hard, CLAY, with about 60% Moderately Cemented Quartz, No Odor, No Organics, Dry BOREHOLE/TPAWELL - TT HAYHURST.GPJ LAB SUMMARY.GDT 8/24/17 25 ST 30 63 CA 35 43 CA ST



BOREHOLE ID: B-7

PAGE 2 OF 2

CLIENT Chevron

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond PROJECT NUMBER 212C-MD-00848 PROJECT LOCATION Eddy County, New Mexico **BLOW COUNTS** SAMPLE TYPE GRAPHIC LOG DEPTH (ft) MATERIAL DESCRIPTION 41.5 Borehole terminated at 41.5

BOREHOLE/TPAWELL - TT HAYHURST.GPJ LAB SUMMARY GDT 8/24/17



BOREHOLE ID: B-8

PAGE 1 OF 2

CLIENT Chevron

BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY GDT 8/24/17

PROJECT NAME Hayhurst NM, Sec.2 Frac Pond

PROJECT NUMBER 212C-MD-00848 PROJECT L

PROJECT LOCATION Eddy County, New Mexico

DATE(S) OF DRILLING: 08/18/2017

GROUND ELEVATION: NA

METHOD:

CONSULTANT: Tetra Tech, Inc.

LATITUDE: 32.071940 N

LOGGED BY: Not Recorded

DRILLING CONTRACTOR: Not Recorded

LONGITUDE: 104.166430 W

DRILLED BY: Not Recorded

Notes: No groundwater encountered. N values have been corrected for sampler diameter.

O DEPTH	SAMPLE TYPE	BLOW COUNTS	GRAPHIC LOG	MATERIAL DESCRIPTION
			11	Medium Dense to Very Dense, Reddish Brown, SAND, some Organics, No Odor, Dry
+ +	CA	23		
	CA	50/5"		
5	CA		1	
	CA	50/4"	1	7.0
+ +	CA	50/5"		Very Dense, Red, <u>SAND</u> , some Organics, No Odor, Dry
10			1	
+	CA	50/5"		
- 15			1/3	
	CA	50/5"		
<u> </u>			1	
			15%	
20	CA	50/6"		
-	JOA		1/1	
25		9	7)	25.0
├	CA			Stiff, Red, <u>CLAY</u> , with 30% Quartz, No Odor, No Organics, Dry
30	ST		3	30.0
	CA	16		Very Stiff to Hard, Red, <u>CLAY</u> , with 30% Quartz, No Odor, No Organics, Moist
				į
[]				
35	ST			
40		50/4"		
	CA	30/4		(Continued Next Page)



Tetra Tech Inc. 4000 N. Big Spring, Suite 401 Midland, TX, 79705 Telephone 432-682-4559

BOREHOLE ID: B-8 PAGE 2 OF 2

					Fax: 432-682-3946							
	CLIE	NT Che	vron			PROJECT NAME Hayh	urst NM, Sec.2 Frac Pond					
	PRO.	JECT NU	MBER _2	212C-N	1D-00848	PROJECT LOCATION Eddy County, New Mexico						
				Ī								
	DEPTH (ft)	SAMPLE TYPE	BLOW COUNTS	GRAPHIC LOG		MATERIAL DESCR	RIPTION					
		SAMP	BLOW	GR								
			-		41.5	Borehole terminate						
						Dorenole terrimate	:u at 41.5					
117												
BOREHOLE/TP/WELL - TT HAYHURST.GPJ LAB SUMMARY GDT 8/24/17												
GPJ LAB SUM												
TT HAYHURST		-										
LE/TP/WELL			ű									
BOREHO								:				

Appendix 7 – HDPE Liner Specifications



19103 Gundle Road Houston, TX 77073 800 435 2008 • 281 443 8564 281 230 8650 Fax www.gseworld.com

October 27, 2016

Tony Banuelos EC Applications-Texas 12002 E Highway 158 Gardendale, TX 79758

RE: GSE Geomembrane - Permeability for EDS-040NE and EDS-060NE

Certification of Compliance

The undersigned, being qualified and authorized to do so, hereby certifies that GSE 40 mil and 60 EDS Geomembrane will meet a permeability of $\leq 1 \times 10^{-12}$ cm/s when tested per ASTM E96.

Sincerely,

Miguel Garcia

GSE Technical Support



GSE HD Smooth Geomembrane

GSE HD is a smooth high density polyethylene (HDPE) geomembrane manufactured with the highest quality resin specifically formulated for flexible geomembranes. This $product is \textit{used in applications that require excellent chemical resistance} \ and \textit{endurance}$

ATTHE CORE:

An HDPE geomembrane used in applications that require excellent chemical resistance and endurance properties

Product Specifications

Tested Property	Te-t Malhad	Frequency			These proc	duct specification	ons meet GRI (
		v.r.dræurA		Average Value			
Thickness, mil	ASTM D 5199		30 mil	40 mil	60 mil	80 mll	100 mil
Lowest individual reading		everyroll	30 27	40 36	60	80	100
Density, g/cm ³	ASTM D 1505	200,000 lb	0.940		54	72	90
Tensile Properties (each direction) Strength at Break, Ib/in-width Strength at Yiold, Ib/in-width	ASTM D 6693, Type IV Dumbbell, 2 ipm		114 63 700	0.940 152 84 700	0.940	0.940	094
Elongation at Break, % Elongation at Yield, %	G.L. 2.0 in G.L. 1.3 in				228 126 700	304 168 700	380 210 700
Tear Resistance, lb	ASTM D 1004	45,000 lb	21	12	12	12	12
Puncture Resistance, Ib	ASTM D 4833	45,000 lb		28	42	56	70
Carbon Black Content, % (Range)	ASTM D 1603*/4218		54 2.0 - 3.0 Note	72 2 0 - 3 0 Note	108	144	180
Carbon Black Dispersion	ASTM D 5596				2.0 3.0	2.0 - 3.0	2.0 - 3.0
Notched Constant Tensile Load, hr	ASIM D 5397 Appendix				Note	Note ¹	Note
					500	500	500
Oxidative Induction Time mins	ASIM D 3895, 200°C; O 1 atm	200,000 lb	>100	>100	>100	>100	
						100	>100
Poll Length , ft		TYPICAL ROLL D	IMENSIONS	M. S. Carlot		NAME OF THE PERSON OF THE PERS	109110
Poll Width 1, ft			1.120	870	560	430	340
oll Area, ft		22.5	22.5	22.5	22.5	22.5	
DTES:			25,200	19,575	12,600	9,675	7.650

- (*) Dispersion only applies to mear spherical agglomerates 9 of 10 views shall be Category 1 or 2. No more than 1 view from Category 3
- GSE HD is available in rolls weighing approximately 3,900 lb.
- All GSE geomembranes have dimensional stability of ±2% when tested according to ASTM D 1204 and LTB of <-77°C when tested according to ASTM D 746

GSE is a leading manufacturer and marketer of geosynthetic lining products and services. We've built a reputation of reliability through our dedication to providing consistency of product, price and protection to our global customers.

Our commitment to innovation, our focus on quality and our industry expertise allow us the flexibility to collaborate with our clients to develop a custom, purpose-fit solution.

[DURABILITY RUNS DEEP]

For more information on this product and others, please visit us at GSEworld com, call 800 435.2008 or contact your local sales ofice

