

Inspector :	Paul Frier
Date & Time:	6/7/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<div><div>NOTE: If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</div></div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
<div>Bird deterrent TKT DS20102949/Materials on order</div>			

Inspector :	Steve Poe
Date & Time:	6/14/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading		
<div style="border: 1px solid black; padding: 10px; text-align: center;"> <p><b>NOTE:</b></p> <p><b>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</b></p> </div>		
Oil absorbent boom or other device is in good repair and available on site	<input type="checkbox"/>	<input type="checkbox"/>
<b>Comments</b>		

Bird deterrent TKT DS20102949

Inspector :	Paul Frier
Date & Time:	6/21/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.	<input checked="checked" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading		
<div style="border: 1px solid black; padding: 10px; text-align: center;"> <p><b>NOTE:</b></p> <p><b>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</b></p> </div>		
Oil absorbent boom or other device is in good repair and available on site	<input type="checkbox"/>	<input type="checkbox"/>
<b>Comments</b>		
Bird deterrent TKT DS20102949/Materials on order		

Inspector :	Steve Poe
Date & Time:	6/28/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<div><p><b>NOTE:</b></p><p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p></div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
Bird deterrent TKT DS20102949			



Inspector :	Paul Frier
Date & Time:	7/5/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
	<div>NOTE: If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</div>		
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments			
<div>Bird deterrent TKT DS20102949/Materials on order</div>			

Inspector :	Steve Poe
Date & Time:	7/12/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<div><p><b>NOTE:</b></p><p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p></div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
Bird deterrent TKT DS20102949			

Inspector :	Paul Frier
Date & Time:	7/19/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Leak detection reading		
<div style="border: 1px solid black; padding: 10px; text-align: center;"> <p><b>NOTE:</b></p> <p><b>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</b></p> </div>		
Oil absorbent boom or other device is in good repair and available on site	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Comments</b>		
Bird deterrent TKT DS20102949/Materials on order/TKT DS20396841 is for leak and level detection		

Inspector :	Dave Nunley
Date & Time:	7/26/20
RWCS Name:	SD 23 North

NMOCD Registration number:
1RF-11
Allowable Leakage Rate: 5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading		
<div style="border: 1px solid black; padding: 10px; text-align: center;"> <p><b>NOTE:</b></p> <p><b>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</b></p> </div>		
Oil absorbent boom or other device is in good repair and available on site	<input type="checkbox"/>	<input type="checkbox"/>
<b>Comments</b>		

Bird Deterrent TKT DS20102949



Inspector :	Paul Frier
Date & Time:	8/2/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Leak detection reading		
<div style="border: 1px solid black; padding: 10px; text-align: center;"> <p><b>NOTE:</b></p> <p><b>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</b></p> </div>		
Oil absorbent boom or other device is in good repair and available on site	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Comments</b>		
Bird deterrent TKT DS20102949/Materials on order/TKT DS20396841 is for leak and level detection		

Inspector :	Steve Poe
Date & Time:	8/9/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<p><b>NOTE:</b></p> <p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
<p>Bird deterrent TKT DS20102949, Brackish water 7-25-20</p>			

Inspector :	Paul Frier
Date & Time:	8/16/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Leak detection reading		
<div style="border: 1px solid black; padding: 10px; text-align: center;"> <p><b>NOTE:</b></p> <p><b>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</b></p> </div>		
Oil absorbent boom or other device is in good repair and available on site	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Comments</b>		
Bird deterrent TKT DS20102949/Materials on order/TKT DS20396841 is for leak and level detection		

Inspector :	Steve Poe
Date & Time:	8/22/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<p><b>NOTE:</b></p> <p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
<p>Bird deterrent TKT DS20102949, Brackish water 7-25-20</p>			



Inspector :	Paul Frier
Date & Time:	8/30/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Leak detection reading		
<div style="border: 1px solid black; padding: 10px; text-align: center;"> <p><b>NOTE:</b></p> <p><b>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</b></p> </div>		
Oil absorbent boom or other device is in good repair and available on site	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Comments</b>		
Bird deterrent TKT DS20102949/Materials on order/TKT DS20396841 is for leak and level detection		

Inspector :	Steve Poe
Date & Time:	9/6/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<div>NOTE: If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
<div>TKT DS20102949, Brackish water 7-25-20, Fence cut on south side west of W. gate tied up with rope for temp. r</div>			

Inspector :	Paul Frier
Date & Time:	9/13/20
RWCS Name:	SD 23 North

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Reported to Water Management Team</b>			
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Leak detection reading		
<div style="border: 1px solid black; padding: 10px; text-align: center;"> <p><b>NOTE:</b></p> <p><b>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</b></p> </div>		
Oil absorbent boom or other device is in good repair and available on site	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Comments</b>		
Bird deterrent TKT DS20102949/Materials on order/TKT DS20396841 is for leak and level detection		

Inspector :	Paul Frier
Date & Time:	6/7/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<div><p><b>NOTE:</b></p><p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p></div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
<div>Bird Deterrent TKT DS20102949/Materials on order</div>			



Inspector :	Steve Poe
Date & Time:	6/14/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.	<input checked="checked" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading		
<div style="border: 1px solid black; padding: 10px; text-align: center;"> <p><b>NOTE:</b></p> <p><b>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</b></p> </div>		
Oil absorbent boom or other device is in good repair and available on site	<input type="checkbox"/>	<input type="checkbox"/>
<b>Comments</b>		

Bird Deterrent TKT DS20102949

Inspector :	Paul Frier
Date & Time:	6/21/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
	<div>NOTE: If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</div>		
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
<div>Bird Deterrent TKT DS20102949/Materials on order</div>			

Inspector :	Steve Poe
Date & Time:	6/28/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<div><p><b>NOTE:</b></p><p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p></div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
Bird Deterrent TKT DS20102949			

Inspector :	Paul Frier
Date & Time:	7/5/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<div><div>NOTE: If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</div></div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments			
<div>Bird Deterrent TKT DS20102949/Materials on order</div>			



Inspector :	Steve Poe
Date & Time:	7/12/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<div><p><b>NOTE:</b></p><p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p></div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
Bird Deterrent TKT DS20102949			

Inspector :	Paul Frier
Date & Time:	7/19/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Leak detection reading		
<div style="border: 1px solid black; padding: 10px; text-align: center;"> <p><b>NOTE:</b></p> <p><b>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</b></p> </div>		
Oil absorbent boom or other device is in good repair and available on site	<input type="checkbox"/>	<input checked="" type="checkbox"/>
<b>Comments</b>		
Bird Deterrent TKT DS20102949/Materials on order/TKT DS20396841 is for leak and level detection		

Inspector :	Dave Nunley
Date & Time:	7/26/20
RWCS Name:	SD 23 South

NMOCD Registration number:
1RF-11
Allowable Leakage Rate: 5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading		0	
<div>NOTE: If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</div>			
Oil absorbent boom or other device is in good repair and available on site		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Comments			
<p>e was knocked off cement block causing it to mess up the fence will get repaired ASAP.Bird Deterrent TKT DS20</p>			

Inspector :	Paul Frier
Date & Time:	8/2/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Leak detection reading			
<p><b>NOTE:</b></p> <p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments			
<p>Bird Deterrent TKT DS20102949/Materials on order/TKT DS20396841 is for leak and level detection</p>			



Inspector :	Steve Poe
Date & Time:	8/9/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<p align="center"><b>NOTE:</b></p> <p align="center">If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
<p align="center">Bird Deterrent TKT DS20102949, Brackish water 7/25/20</p>			

Inspector :	Paul Frier
Date & Time:	8/16/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Leak detection reading			
<div><p><b>NOTE:</b></p><p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p></div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments			
<div>Bird Deterrent TKT DS20102949/Materials on order/TKT DS20396841 is for leak and level detection</div>			

Inspector :	Steve Poe
Date & Time:	8/23/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<p><b>NOTE:</b></p> <p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
<p>Bird Deterrent TKT DS20102949, Brackish water 7/25/20</p>			

Inspector :	Paul Frier
Date & Time:	8/30/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Leak detection reading			
<div><p><b>NOTE:</b></p><p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p></div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments			
<div>Bird Deterrent TKT DS20102949/Materials on order/TKT DS20396841 is for leak and level detection</div>			



Inspector :	Steve Poe
Date & Time:	9/6/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leak detection reading			
<div><p><b>NOTE:</b></p><p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p></div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input type="checkbox"/>
Comments			
<div></div> <div>49, Brackish water 7/25/20 Fence need repairs on N side where traatment line comes through fence and head</div>			

Inspector :	Paul Frier
Date & Time:	9/13/20
RWCS Name:	SD 23 South

NMOCD Registration number:	1RF-11
Allowable Leakage Rate:	5.19 gpm

Inspection Checklist		YES	NO
Fencing is in good repair		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Access gates are locked (when access is not required)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms and elevation are in good repair to prevent surface run-on		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Audible bird deterrent system is functioning properly		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Absence of any dead birds or other wildlife		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> The NMOCD and New Mexico Department of Game and Fish must be notified within 30 days if a dead bird or other wildlife is discovered.		
Absence of any visible oil layer on surface		<input checked="" type="checkbox"/>	<input type="checkbox"/>
	<b>NOTE:</b> Immediate action must be taken if visible oil is detected		
Freeboard - minimum of 3 feet present?		<input checked="" type="checkbox"/>	<input type="checkbox"/>
Any visible damage to primary liner above fluid level to include those areas where pipes, hoses, supports, etc. may be in contact with liner		<input type="checkbox"/>	<input checked="" type="checkbox"/>
	<b>NOTE:</b> If damaged, repair / replacement must commence within 48 hours of discovery or the NMOCD District Office must be contacted to seek an extension		

Observed leakage rate less than established acceptable rate.		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Leak detection reading			
<div><p><b>NOTE:</b></p><p>If leak detection monitoring indicates that the primary liner has been compromised below the fluid surface, immediately notify the NMOCD District Office and initiate efforts to repair/replace</p></div>			
Oil absorbent boom or other device is in good repair and available on site		<input type="checkbox"/>	<input checked="" type="checkbox"/>
Comments			
<div>Bird Deterrent TKT DS20102949/Materials on order/TKT DS20396841 is for leak and level detection</div>			