District I - (505) 393-6161
P.O. Box 1980
Hobbs, NM 88241-1980
District II - (505) 748-1283
1301 W. Grand Ave.
Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Road
Aztec, NM 87410

District IV - (505) 827-7131

## **State of New Mexico**

Energy Mineral and Natural Resources Department
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505
(505) 476-3440

Form C-141 Originated 2/13/97

Submit 2 copies to Appropriate District Office in accordance with Rule 116 on back side of form

30-015-	30112			Release Notification and Corrective Action					Г	٦	:-10		
OPERATOR											ial Report	Final Report	
Name Co Marathon Oil Company Dw							-	odbock	•				
							Wight Brodbeck Telephone No.						
Audicoo							05-457-2621						
							cility Type						
On location with Rocky Hills #1 Stri							ripper Water Storage						
Surface Owner Mineral Owner								Lease No.					
BLM BLM													
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the	North/Sc	outh Line	ne F	eet from the	East/West Line	e Cou	inty		
L	19	21S	24E	0		)		0	0		Edd	ly	
NATURE OF RELEASE													
Type of Release							Volume of Release 10.4 Bbls				Volume Recovered		
Treated produced water from the sour water stripper.  Source of Release							Date of Occurrence Hour of Occurrence		nence	10 Bbls  Date of Discovery Hour of Discovery			
Tank								4/07/04	10:30 AM		04/07/04	10:30 AM	
Was Immediate Notice Given?								To Whom?	1 10.007	<del></del>	0 1/0//01	70.00740	
Yes No Not Required													
By Whom?							Date of Notification				Hour of Notification		
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
Yes No									-				
If a watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)											EIVED		
•								APR 1 4 2004					
N/A													
N/A  Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets if Necessary)													
( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )													
Tank level transmitter failed on blow fuse allowing tank to over-fill. The fuse was replaced and the control scheme is being													
reviewed to examine the possiblility of improving its reliability (fail-safe).													
Describe Area	Affected and	Cleanup Action	Taken. (Att	ach Additional She	ets if Necess	sary)							
The water was captured inside the tanks lined secondary containment and removed by vacuum truck. Some of the fluid was													
accumulated rain water.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulation all operators are required to report and/or file certain release politications and perform corrective actions for releases which may endeager public beautiful to the contract of a C 144 country to the country to the country to the contract of a C 144 country to the contract of													
to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a													
thread to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance													
with any other fe	ederar, state,	or local laws al	ng/or regular	ions.			<del></del>						
Signature: MA all solled							OIL CONSERVATION DIVISION						
Signature: JW AIRALEN —								Approved by TIM W. GUN					
Printed Name: Dight A BROOBECK								District Supervisor: DISTRICT TRUDERVISOR - n.S.					
Title: Endustron Super								Approval Date: Expiration Date:					
								rs of Approval:	Eand .	-	Attached	<del></del>	
4/	12/04	٠.		05) 457-2621				P					