

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised September 20, 2004

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-32837

Release Notification and Corrective Action *Eagle 35 F Fed. #12*

nMLB0426150656

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Devon Energy Production Co. LP	Contact: Jennifer Van Curen
Address: PO Box 250; Artesia, NM 88211	Telephone No.: 505-748-0160
Facility Name: Eagle 35 Battery	Facility Type: Battery

Surface Owner <i>BLM</i>	Mineral Owner	Lease No.
--------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter <i>F</i>	Section 35	Township 17S	Range 27E	Feet from the 2310	North/South Line North	Feet from the 1750	East/West Line West	County Eddy
-------------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release: Water	Volume of Release: 380	Volume Recovered: 35
Source of Release: Corroded plug	Date and Hour of Occurrence 9-16-04; 10:00 am	Date and Hour of Discovery 9-16-04; 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? <i>Jerry Chaney</i>	Date and Hour: 9-16-04; 11:05	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

SEP 24 2004

COO-ARTESIA

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A 1/4" plug corroded and came out of the transfer pump and dumped 380 bbls of produced water inside dike that was overcome and broke. The water traveled approx. 300' and was about 5' wide in a pasture. Stopped leak by putting a plug in the transfer pump. Called vacuum truck to pick up water.

Describe Area Affected and Cleanup Action Taken.\*

Area affected was a 300' X 5' strip in pasture. Will take soil samples within affected area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Van Curen</i>	OIL CONSERVATION DIVISION		
Printed Name: Jennifer Van Curen	Approved by District Supervisor:		
Title: Production Field Tech	Approval Date:	Expiration Date:	
E-mail Address: Jennifer.vancuren@dvnm.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 9/22/2004	Phone: 748-0160		

\* Attach Additional Sheets If Necessary