

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCD Rec'd:08/10/18

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Lime Rock Resources II-A, L.P. 277558	Contact	Mike Barrett
Address	1111 Bagby St. Ste 4600, Houston, TX 77002	Telephone No.	575-365-9724
Facility Name	Hawk 9 F Federal #7	Facility Type	

Surface Owner	Private	Mineral Owner	State	API No.	30-015-29026
---------------	---------	---------------	-------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	09	18S	27E	1500	N	1650	W	Eddy

Latitude 32.7653732 Longitude -104.2865372 NAD83

NATURE OF RELEASE


Type of Release	Produced Water	Volume of Release	35 BBLS PW	Volume Recovered	0
Source of Release	Poly Transfer Line	Date and Hour of Occurrence	7-22-18 14:30	Date and Hour of Discovery	7-23-18 14:30
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD via verbal notice		
By Whom?	David Adkins	Date and Hour	7-23-18 15:40		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
The poly transfer line from the Hawk 9 Battery split resulting in a release of 35 barrels of produced water down the road and on the side of the Hawk 9 #7 location. The line was isolated and repairs were made to the poly line. No fluids were recovered. Talon mobilized personnel to the location for initial site assessment.

Describe Area Affected and Cleanup Action Taken.*
The spill travelled down the road app 150'. It then went off the road and travelled app another 300' on the north and east sides of the location. The flow path is app 5-15' wide.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Mike Barrett	Approved by Environmental Specialist: Maria Pruett		
Title: Production Superintendent	Approval Date: 08/10/18	Expiration Date: N/A	
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 8-7-18 Phone: 575-365-9724			2RP-4909

* Attach Additional Sheets If Necessary

#:pMAP1822255873
#:nMAP1822256231