	State of New M	Г	DECID, 0/44/2020	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Nat	ural Resources 1		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-015-46449	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	NOIVISION	5. Indicate Type of Leas	10
District III - (505) 334-6178	1220 South St. Fra	ıncis Dr.	STATE X	FEE
1000 Rio Brazos Rd., Aztec, NM 8741 District IV – (505) 476-3460	Santa Fe, NM 8	37505	6. State Oil & Gas Lease	
1220 S. St. Francis Dr., Santa Fe, NM				
87505	OTICES AND DEPORTS ON WELL	0	7. Lease Name or Unit	A graement Nome
	OTICES AND REPORTS ON WELL OPOSALS TO DRILL OR TO DEEPEN OR PI		7. Lease Name of Omit A	Agreement Ivame
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		RAY STATE COM	1	
PROPOSALS.)	Gas Well X Other		8. Well Number	204H
Type of Well: Oil Well Name of Operator	J Gas Well 📐 Other		9. OGRID Number	
MATADOR PRODUCTION COMPANY			228	3937
3. Address of Operator			10. Pool name or Wildcat	
5400 LBJ FREEWAY, STE 1500, DALLAS, TX 75240			PURPLE SAGE;WOLFCAMP(GAS)	
4. Well Location				
Unit Letter 1	: 953 feet from the N	line and	298 feet from the	line
Section 1	Township 24S	Range 28E	NMPM Cour	nty EDDY
	11. Elevation (Show whether D	R, RKB, RT, GR, etc	:.)	
	2962' GR			
12. Ched	ck Appropriate Box to Indicate	Nature of Notice,	, Report or Other Data	
NOTICE OF	INTENTION TO:	I SUE	BSEQUENT REPOR	T OF
PERFORM REMEDIAL WORK		REMEDIAL WOR		RING CASING
TEMPORARILY ABANDON	☐ CHANGE PLANS ☐		RILLING OPNS. P AN	_
PULL OR ALTER CASING	☐ MULTIPLE COMPL ☐	CASING/CEMEN	_	
DOWNHOLE COMMINGLE			_	
CLOSED-LOOP SYSTEM				
OTHER:		OTHER: Dorfo	rate fractions tract proc	IVI
OTHER: OTHER: Perforate, fracture treat, produce IX 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
13. Describe proposed or co	ompleted operations. (Clearly state al	l pertinent details, ar	nd give pertinent dates, incl	uding estimated date
13. Describe proposed or co	d work). SEE RULE 19.15.7.14 NMA	l pertinent details, an AC. For Multiple Co	nd give pertinent dates, incl ompletions: Attach wellbor	uding estimated date re diagram of
13. Describe proposed or co	d work). SEE RULE 19.15.7.14 NMA	l pertinent details, an AC. For Multiple Co	nd give pertinent dates, incl ompletions: Attach wellbor	uding estimated date re diagram of
13. Describe proposed or confidence of starting any proposed proposed completion of	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20	l pertinent details, an AC. For Multiple Co 198' reached 01	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r	uding estimated date re diagram of reached 01/27/20
13. Describe proposed or configuration of starting any proposed proposed completion of 03/28/20 WOC 141	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 I7 hrs. Perform production casing	l pertinent details, an AC. For Multiple Co 198' reached 01	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r	uding estimated date re diagram of reached 01/27/20
13. Describe proposed or configuration of starting any proposed proposed completion of 03/28/20 WOC 141 Good test	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 I7 hrs. Perform production casing t.	I pertinent details, and AC. For Multiple Constitution 198' reached 01 integrity test to 5	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of 03/28/20 WOC 141 Good test 04/01/20 Perforate	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe	I pertinent details, and AC. For Multiple Constitution 198' reached 01 integrity test to 5	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of 03/28/20 WOC 141 Good test 04/01/20 Perforate 48 stages	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe	I pertinent details, and AC. For Multiple Constitution 198' reached 01 integrity test to 5	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of 03/28/20 WOC 141 Good test 04/01/20 Perforate 48 stages	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 I7 hrs. Perform production casing t. , fracture treat and produce Wolfe s. ac spread. WSI w/o drillout.	I pertinent details, and AC. For Multiple Constitution 198' reached 01 integrity test to 5	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of the confidence of starting any proposed completion of the confidence of	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe s. ac spread. WSI w/o drillout. drillout.	I pertinent details, and AC. For Multiple Constitution 198' reached 01 integrity test to 5	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of the confidence of starting any proposed completion of the confidence of	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe ac spread. WSI w/o drillout. drillout. flowback	I pertinent details, and AC. For Multiple Constitution 198' reached 01 integrity test to 5	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of the confidence of starting any proposed proposed completion of the confidence of the confi	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe ac spread. WSI w/o drillout. drillout. flowback owback.	I pertinent details, and AC. For Multiple Constitution 198' reached 01 integrity test to 5	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of the confidence of starting any proposed proposed completion of the confidence of the confi	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe ac spread. WSI w/o drillout. drillout. flowback owback. luces.	I pertinent details, and C. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dros' - 20043' w/26,650,478	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of the confidence of starting any proposed proposed completion of the confidence of the confi	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe ac spread. WSI w/o drillout. drillout. flowback owback.	I pertinent details, and C. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dros' - 20043' w/26,650,478	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of the confidence of starting any proposed proposed completion of the confidence of the confi	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 I7 hrs. Perform production casing t. , fracture treat and produce Wolfe s. ac spread. WSI w/o drillout. flowback owback owback. luces. y tubing installation in order for w	I pertinent details, and C. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118	nd give pertinent dates, inclumpletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Drost - 20043' w/26,650,478 d pressure to decline.	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of the confidence of starting any proposed proposed completion of the confidence of the confi	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe ac spread. WSI w/o drillout. drillout. flowback owback. luces.	I pertinent details, and C. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118	nd give pertinent dates, inclompletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dros' - 20043' w/26,650,478	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of the confidence of starting any proposed proposed completion of the confidence of the confi	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 I7 hrs. Perform production casing t. , fracture treat and produce Wolfe s. ac spread. WSI w/o drillout. flowback owback owback. luces. y tubing installation in order for w	I pertinent details, and C. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118	nd give pertinent dates, inclumpletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Drost - 20043' w/26,650,478 d pressure to decline.	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidential any proposed proposed completion of 03/28/20 WOC 141 Good test 04/01/20 Perforate 48 stages 04/21/20 RDMO from 04/28/20 Mill plugs 04/30/20 Finished 05/01/20 WSI w/o 06/01/20 Well on flogology 04/30/20 Well proposed Requesting to delay Spud Date: 11/25/19	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 I7 hrs. Perform production casing t. , fracture treat and produce Wolfe s. ac spread. WSI w/o drillout. drillout. flowback owback luces. y tubing installation in order for w Rig Release I	Pertinent details, and C. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118 ell to clean up and Date:	nd give pertinent dates, inclumpletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro '- 20043' w/26,650,478 d pressure to decline .	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidential any proposed proposed completion of 03/28/20 WOC 141 Good test 04/01/20 Perforate 48 stages 04/21/20 RDMO from 04/28/20 Mill plugs 04/30/20 Finished 05/01/20 WSI w/o 06/01/20 Well on flogology 04/30/20 Well proposed Requesting to delay Spud Date: 11/25/19	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 I7 hrs. Perform production casing t. , fracture treat and produce Wolfe s. ac spread. WSI w/o drillout. flowback owback owback. luces. y tubing installation in order for w	Pertinent details, and C. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118 ell to clean up and Date:	nd give pertinent dates, inclumpletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro '- 20043' w/26,650,478 d pressure to decline .	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidential any proposed proposed completion of 03/28/20 WOC 141 Good test 04/01/20 Perforate 48 stages 04/21/20 RDMO from 04/28/20 Mill plugs 04/30/20 Finished 05/01/20 WSI w/o 06/01/20 Well on flogology 04/30/20 Well proposed Requesting to delay Spud Date: 11/25/19	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 I7 hrs. Perform production casing t. , fracture treat and produce Wolfe ac spread. WSI w/o drillout. drillout. flowback owback. luces. y tubing installation in order for w Rig Release I	Pertinent details, and C. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118 ell to clean up and Date: Date: 0 best of my knowled	nd give pertinent dates, inclumpletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro '- 20043' w/26,650,478 d pressure to decline .	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidential any proposed proposed completion of 03/28/20 WOC 141 Good test 04/01/20 Perforate 48 stages 04/21/20 RDMO from 04/28/20 Mill plugs 04/30/20 Finished 05/01/20 WSI w/o 06/01/20 Well on flogology 04/30/20 Well proposed Requesting to delay Spud Date: 11/25/19	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 I7 hrs. Perform production casing t. , fracture treat and produce Wolfe ac spread. WSI w/o drillout. drillout. flowback owback. luces. y tubing installation in order for w Rig Release I	Pertinent details, and C. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118 ell to clean up and Date:	nd give pertinent dates, inclumpletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro '- 20043' w/26,650,478 d pressure to decline .	uding estimated date re diagram of reached 01/27/20 opped 59 psi
13. Describe proposed or confidence of starting any proposed proposed completion of the starting any proposed proposed completion of the starting any proposed completion of the starting any proposed completion of the starting and starting any proposed completion of the starting and starting any proposed completion of the starting and starting any proposed completion of the starting and st	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe s. ac spread. WSI w/o drillout. drillout. flowback owback. luces. y tubing installation in order for w Rig Release I	Pertinent details, and AC. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118 ell to clean up and Date: Date: Date: 0 Dest of my knowled	nd give pertinent dates, inclumpletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro r - 20043' w/26,650,478 d pressure to decline .	uding estimated date re diagram of reached 01/27/20 opped 59 psi Ibs sand.
13. Describe proposed or confidence of starting any proposed proposed completion of the starting any proposed proposed completion of the starting any proposed completion of the starting any proposed completion of the starting and starting any proposed completion of the starting and starting	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe s. ac spread. WSI w/o drillout. drillout. flowback owback. luces. y tubing installation in order for w Rig Release I	Pertinent details, and AC. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118 ell to clean up and Date: Date: Date: 0 Dest of my knowled	nd give pertinent dates, inclumpletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro '- 20043' w/26,650,478 d pressure to decline .	uding estimated date re diagram of reached 01/27/20 opped 59 psi Ibs sand.
13. Describe proposed or confidence of starting any proposed proposed completion of the starting any proposed proposed completion of the starting any proposed completion of the starting any proposed completion of the starting and starting any proposed completion of the starting and starting any proposed completion of the starting and starting any proposed completion of the starting and st	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe s. ac spread. WSI w/o drillout. drillout. flowback owback. luces. y tubing installation in order for w Rig Release I	Pertinent details, and AC. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118 ell to clean up and Date: Date: Date: 0 Dest of my knowled	nd give pertinent dates, inclumpletions: Attach wellbor /27/20; PTBD 20090' r 5949 psi for 30 min. Dro r - 20043' w/26,650,478 d pressure to decline .	uding estimated date re diagram of reached 01/27/20 opped 59 psi Ibs sand.
13. Describe proposed or confidence of starting any proposed proposed completion of the starting any proposed proposed completion of the starting any proposed completion of the starting any proposed completion of the starting and starting any proposed completion of the starting and starting	d work). SEE RULE 19.15.7.14 NMA r recompletion. TVD/MD 9740'/20 17 hrs. Perform production casing t. , fracture treat and produce Wolfe s. ac spread. WSI w/o drillout. drillout. flowback owback. luces. y tubing installation in order for w Rig Release I	Pertinent details, and AC. For Multiple Co. 198' reached 01 integrity test to 5 camp from 10118 ell to clean up and Date: Date: Date: 0 Dest of my knowled	nd give pertinent dates, including pertinent dat	uding estimated date re diagram of reached 01/27/20 opped 59 psi Ibs sand.

8/12/2020 ab