

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION

RECEIVED BY

JUN 10 1985

O. C. D.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
30-005-60434

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TXO Production Corp. ✓	8. Farm or Lease Name O'Brien #1 C
3. Address of Operator 900 Wilco Bldg. Midland Tx 79701	9. Well No. 1
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 9S RANGE 29E NMPM.	10. Field and Pool, or Wildcat Uncl. Strawn
15. Elevation (Show whether DF, RT, GR, etc.) 3980.8 GR	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TIH w/GR & junk basket to 8500'
Set 4 1/2" CIBP @ 8500. Dump 35' cmt
TIH & set 25 sx cmt @ 7375' (in 4 1/2)
Cut & pull 4 1/2" @ 6725'
TIH & set 25 sx cmt @ 6865 (on 4 1/2 stub)
Tag TOC
Set 35 sx cmt @ 6130 (in OH)
Set 35 sx cmt @ 5650 (in OH)
Set 25 sx cmt @ 3800 (in OH)
Set 35 sx cmt @ 2675 (at 8 5/8" shoe)
Tag TOC (must be 50' into 8 5/8" shoe)
Set 25 sx @ 350'
Set 10 sx @ surface

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale D. Lovely TITLE Production Engineer DATE June 7, 1985

APPROVED M. J. Williams TITLE OIL AND GAS INSPECTOR DATE JUN 12 1985

CONDITIONS OF APPROVAL, IF ANY:

Notify U.S.G.C. in sufficient time to witness