

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 09 2013

NMOCD ARTESIA

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

nJMW 1301749383

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	6137	Contact Merle Lewis, Production Foreman
Address P. O. Box 250 Artesia, NM 88211		Telephone No. 575-748-630
Facility Name Roche Federal #1		Facility Type Oil Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

API 30-015-25972

Unit Letter O	Section 7	Township 18S	Range 31E	Feet from the 330	North/South Line South	Feet from the 1980	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	-------------

NATURE OF RELEASE

Type of Release Oil	Volume of Release 10 bbls	Volume Recovered 4bbls
Source of Release Corrosion Spill	Date and Hour of Occurrence 01/05/13, 3:27 PM	Date and Hour of Discovery 01/05/13, 3:27 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Left Message at BLM & OCD	
By Whom?	Date and Hour 01/05/13 BLM 4:45PM OCD 5:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N/A
--

Describe Cause of Problem and Remedial Action Taken.* At the Roche Battery, an oil dump line developed a hole caused by corrosion which lead to a 9 barrel spill of oil.
---

Describe Area Affected and Cleanup Action Taken.* At the Roche Battery, an oil dump line developed a hole caused by corrosion which lead to a 9 barrel spill of oil. Lease operator immediately contacted a vacuum truck and was able to recover 4 barrels of oil. Talon LPE will conduct cleanup plan and remediate the contaminated soil.
--

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Graciela C. Bustamante		OIL CONSERVATION DIVISION	
Printed Name: Graciela C. Bustamante		Approved by District Supervisor: Signed By <i>Mike Deacon</i>	
Title: Field Adm. Support		JAN 17 2013 Approval Date:	Expiration Date:
Date: 01/08/13 Phone: (575) 746-5561		Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule &  
Guidelines. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

February 17, 2013

2RP-1503